


Inspection for every environment

Training Course



Important Notice

Welcome to Autodesk.

This document is supplied as part of an Autodesk Training Course. It is not intended to be distance-learning material: rather as an aid for Tutors when presenting material to course delegates and as a subsequent aid memoir to those delegates.

Autodesk does not accept responsibility for any personal belongings / valuables whilst on the premises. Delegates are advised to keep their belongings with them at all times.

Autodesk has no control over the use of the software described in this document and cannot accept any responsibility for any loss or damage caused as a result of using the software. Users are advised that all results from the software are checked by a competent person in accordance with good quality control procedures.

The software described in this document is furnished under a license agreement and may be used only in accordance with the terms of this license.

Copyright 2016 – Autodesk.

All rights reserved.

PowerInspect CNC 2017

Contents

| Chapters | Page Number |
|---------------------------|-------------|
| 1 Introduction | 1.1 - 1.18 |
| 2 Machine Tab | 2.1 - 2.10 |
| 3 CAD Management | 3.1 - 3.10 |
| 4 Calibration | 4.1 - 4.4 |
| 5 Alignments | 5.1 - 5.12 |
| 6 Controlling The Machine | 6.1 - 6.8 |
| 7 Geometric Inspection | 7.1 - 7.16 |
| 8 Surface Inspection | 8.1 - 8.18 |
| 9 Modifying Elements | 9.1 - 9.4 |
| 10 Multiple Alignments | 10.1 - 10.6 |

1. Introduction

PowerInspect CNC enables you to perform rapid inspections of parts and tools by comparing manufactured items with their CAD models. It includes a full geometric package, which can be used to inspect parts with or without a CAD model.

You can also create inspection sequences offline and simulate them within PowerInspect CNC before running them on the measuring device.

Choosing what to inspect

PowerInspect CNC's Sequence Tree specifies the features to be inspected and the order of inspection. You can add features to the inspection sequence by picking them from a CAD model, or by selecting them from the Item toolbar.

What can you measure?

You can measure the following types of feature in CNC mode:

- Surfaces
- Edges
- Sections
- Geometry, including 2D features, such as circles, and 3D features, such as cones

In addition, you can measure Point clouds in manual mode.

Aligning the part

PowerInspect CNC provides the following methods of aligning the part to the CAD model:

- Free Form alignment — Aligns the part to the CAD using measured dynamic points. This enables you to measure parts that have no clearly definable features.
- Geometric PLP alignment — Creates an alignment using geometric features that have known nominal coordinates.
- Three Spheres alignment — Creates a PLP alignment by probing tooling balls that have nominal coordinates.
- From File alignment — Loads a previously saved alignment from file. You can use this option when inspecting multiple examples of a part. When you use this alignment, each example must be identically positioned on the inspection table.
- Best Fit From Points — Aligns the part using three or more points that have known nominal coordinates.
- Reference Point System (RPS) alignment — Creates an alignment using the XYZ values of up to one hundred features.

- From Point Cloud alignment — Aligns the part using a point cloud. The point cloud must include data from more than one surface.
- Point Cloud Picked-Points alignment — Creates an alignment using selected points in a point cloud.
- PLP (Plane, Line, Point) alignment — Creates a geometric alignment using a datum created from a Plane, a Line and a Point item.
- User Defined alignment — Aligns the part by specifying the relationship between the reference systems of the Machine Datum and the PCS (CAD Datum).
- Offset alignment — Creates an alignment by measuring a specified position on the part.

When you have measured one or more inspection groups, you can use Best Fit items to optimize the alignment of the part with the CAD model. PowerInspect CNC compares the points of selected groups to the nominals and adjusts the alignment using one of five fitting methods.

Inspecting the part

You can perform inspections manually or by creating probe paths and running inspection sequences under computer control.

As you inspect the part, PowerInspect CNC displays inspection points and features in the CAD view. Customizable colour-coding enables you to quickly see which items are in tolerance, above tolerance, and below tolerance, and the Info tab provides full details of the currently selected item in the inspection sequence.

If you want to inspect several examples of the same part using the same inspection sequence, you can use Measures to save all the results in one document.

Creating reports

PowerInspect CNC automatically produces a customizable HTML report on the Report tab. You can choose which measurements to include, or you can show all measurements for all features in your inspection.


You can also generate printable reports using a PDF generator or Microsoft Excel.

Opening PowerInspect CNC

To open **PowerInspect CNC**, double-click the desktop icon.





The screen should look as follows:



The work environment remains empty until you start a new session. When a new session is started, further options become available in the **Menu** bar, and a graphics window, Sequence Tree and context-sensitive toolbar are generated.


Creating a new session


A new session can be started from the **File** menu or from the **Main** toolbar.

- **New Session**  creates a new inspection document without loading a CAD model.
- **New Session Wizard**  allows you to choose whether you want to open one or more CAD models. When you start a new session using the **New Session Wizard**, you are guided through the process step by step.
- If a PowerInspect CNC session (*.pwi) already exists, you can select **File > Open**.

Alternatively, click **Open**  on the **Main** toolbar.


New Session Wizard

- 1 Click the **New Session Wizard**  button to open the **New Inspection Session** dialog.



This dialog contains three options for creating an inspection session:

- **Measurement without CAD** creates an inspection session without opening a CAD model. This is the same as selecting **New Session** from the **Main** toolbar.
 - **Measurement with a single CAD Part** creates an inspection session using one CAD model.
 - **Measurement with multiple CAD Parts** creates an inspection session using multiple CAD models.
- 2 Select **Measurement with a single CAD part** and click **Next** to display the second page of the wizard.



Use this dialog to browse to the CAD file that you want to open. You can also specify the **Units** you want to work in, and specify offsets for surface and edge points.

- 3 Click **New** to browse to the CAD file for the part you want to inspect.
- 4 In the **Open** dialog, select **DemoBlock2008(CMM+Arm).dgk** and click **Open**.



*After a CAD file has been selected, it can be transformed. Click **Details** to display the **CAD Details** dialog and select **Transformation Matrix** (For further details, see Chapter 2).*

- 5 Click **Next** to display the next page of the wizard, **Variables**.

The **Variables** dialog allows you to choose the template in which you want to report your measurements. Click **Browse** to navigate to the template file you want to use.

| Name | Value |
|--------------------|---------------------------------|
| Customer | Your customer company name here |
| Customer contact | Your contact person |
| Customer fax No. | Your customer fax No. |
| Customer phone No. | Your customer phone No. |
| Datum | Your Datum |
| Description | Your part description here |
| Drawing number | Your drawing number |
| Inspector | Your inspector's name here |

☒ Save as default parameters

< Back Next > **Finish** Cancel Help

PowerInspect CNC has the ability to create reports in two formats:

- **HTML format** reports are created directly inside the PowerInspect *.pwi file, and are accessible through the **Report** tab below the Graphics window.
 - **Microsoft Excel** reports allow backwards compatibility for older versions.
- Entries can be edited by clicking on the required field and editing the contents.


- 6 Click **Finish** to complete the process and begin the session.

The Graphics Window

When a session is open, a number menus and toolbars are displayed, as shown below.



This screen layout is for CNC licence.




- ① Sequence Tree
- ② CAD/View toolbars
- ③ Graphics window
- ④ View tabs
- ⑤ Probe status bar


The Graphics window includes the following tabs:


- **CAD View** displays the CAD model and all inspected results.
- **Info** displays information about the selected item in the Sequence Trss.
- **Report** displays the report in HTML format.
- **Dynamic Points** lists the points used in an inspection.
- **Section** displays the section each time you create a Section group. This tab is only available when you create a Section group.

Menu bar

The **Menu** bar is located at the top of the main window.




Click a menu to open it. If a menu item is unavailable, it does not apply to the document. A small arrow  next to a menu item indicates that there are more options available. Move the cursor over the item to display these options.



Click outside a menu option to cancel a command and close the menu.


Main toolbar

The **Main** toolbar is displayed at the top of the graphics window under the **Menu** bar. The buttons allow easy access to the most frequently used **PowerInspect CNC** menu items.



Item toolbar

The **Item** toolbar is used for the creation of alignments, geometric groups, inspection groups, and datums.



The toolbar changes according to the function chosen.

Click on an icon with a small arrow next to it to open that item's submenu. For

example, clicking the **Miscellaneous**  button displays the following toolbar:



CAD View toolbar

The **CAD View** toolbar contains options to orientate and shade the CAD model.




View Options toolbar

The **View Options** toolbar enables you to display measurement data in the graphics window, and to control the information that is displayed.




Mouse Context toolbar

The **Mouse Context** toolbar enables you to choose the function of the cursor.



Toolbar visibility

Right-click in and empty area of the toolbar or menu bar to toggle the visibility of all toolbars.



Views and View Manipulation

After the new session has been created, you can view the CAD model in order to gain some visual information about the part. To do this, the various views and their manipulation need to be understood.

Before running through the views and view manipulation, the use of the mouse functions will be established.

Mouse buttons

Each of the three mouse buttons performs a different dynamic operation.

Left mouse button: Picking and selecting



This button is used for selecting items from the menus, options within dialogs, and items in the graphics area.

It is also responsible for view manipulation depending on the setting used in the



Set Mouse Button 1 View Mode button.

Middle mouse button: Dynamics



- Zooming in and out: Hold down the **Ctrl** key and the middle mouse button. Move the mouse up and down to zoom in and out. Alternatively, rotate the scroll wheel, if available.
- Pan around the model: Hold down the **Shift** key and the middle mouse button. Move the mouse in the required direction.
- Zoom box: Hold down the **Ctrl** and **Shift** keys, and drag a box around the area that you want to zoom into using the middle mouse button.
- Rotate mode: Hold down the middle mouse button and move the mouse to rotate the view.

Right mouse button: Dynamics, Special Menus and PowerInspect CNC Sequence Tree Options




- Zooming in and out: Hold down the **Ctrl** key and the right mouse button. Move the mouse up and down to zoom in and out.
- Pan around the model: Hold down the **Shift** key and the right mouse button. Move the mouse in the required direction.
- Zoom Box: Hold down the **Alt** key and the right mouse button. Drag a box around the area that you want to zoom into.
- Rotate mode: Hold down the **Ctrl** and **Shift** keys, and use the right mouse button to rotate the view.

When the right mouse button is pressed on its own, a popup menu is displayed based on the item that the mouse is over, such as the Sequence Tree, or the toolbar menus.

View menu

The **View** menu is accessed from the **Menu** bar and contains the **Resize to Fit** option, and a number of **View** submenus. Each of these submenus corresponds to a different group of views.



- **From** — These options allow you to alter the viewing angle of the part shown in the CAD view.
- **ISO** — These options allow you to alter the CAD view layout.
- **Custom View** — These options allow you to save the current CAD view for future use and to reload previously saved views.
- **Rotation Anchor** — These options allow you to specify how the model in the CAD view is rotated.
- **Machine** — These options allow you to toggle the Machine/Probe/Tool visibility within the graphics window. It also details the keyboard shortcuts.

- **Probe Paths** — These options are only applicable for the CNC version of the software. They allow you to control which probe paths can be seen in the CAD view.
- **Grid Mode** — These options allow you to specify the coordinate system in which the grid is displayed.
- **Level** — These options allow you to group surfaces into levels and to control which levels are displayed in the CAD view.
- **Toolbars** — Use these options to display or hide the toolbars and Status bar.


The **View** flyout shares these functions.

View flyout


Open the **View** flyout by clicking the arrow below the **Select View** button on the **CAD View** toolbar. This flyout contains a series of buttons that correspond to the same icons in the view menu.



The 1, 2, 3, and 4 buttons are used to select the **Custom Views**, which can be saved


using the corresponding **Save**  button. Rotations can also be triggered using the **Arrow** keys on the keyboard, by dynamically moving the cursor using the **Mouse**



Functions, or by using the **Rotations**  flyout. The rotation axis is selected from the flyout and the view then rotated incrementally by clicking on the button.

Window menu

If more than one session is open, you can view all sessions in a single screen, using the **Window** menu. The sessions can then be arranged according to your preference.



The CAD View

The CAD View is where all the inspection and geometric information is viewed. CAD models can be seen either with no shading, transparent shading, or solid shading, combined with or without wireframe.




Click the **Shading Mode For Model** button to open the **Shading Mode**




flyout and choose the shading you want to apply to the CAD model. Alternatively, use the shortcut keys to toggle the wireframe and shading.

- **w** — toggle wireframe on/off
- **s** — toggle shading on/off


Solid Shading



Transparent Shading




Wireframe Shading



Surface normal direction

PowerInspect CNC has a function which allows you to determine the surface normal direction.


Using the **Highlight back-facing surfaces**  button in combination with the shading, will show all reversed surfaces as bright red. This is useful for determining the direction needed for surface offsets.

To reverse a surface:


- 1 Click **Highlight back-facing surfaces** .

- 2 Click **Surface Selector** .


- 3 Click a surface to select it. The edges of the selected surface are highlighted yellow.



- 4 Right-click in the CAD View and select **Inverse Surface** from the menu.



The selected surface changes colour to red to demonstrate that it is reversed.



The Report Template

PowerInspect CNC enables you to select from a number of templates to control the form in which your measurement data is output. For HTML format, the report is integrated into the PowerInspect CNC work environment, and can be accessed at any time using the **Report** tab. Reports can be customised to suit your customers' needs.



Delcam
Advanced
Manufacturing
Solutions

PowerINSPECT

Delcam plc, AMS Division
Talbot Way, Small Heath Business Park
Birmingham B10 0HJ, UK

Tel: +44 (0)121 766 5544 | Fax: +44 (0)121 766 5511
email: marketing@delcam.com | www.powerinspect.com
www.delcam-ams.com | www.delcam.tv

| | | | |
|----------------|---------------------------------|--------------------|----------------------------|
| Customer | Company Logo | Inspector | Your inspector's name here |
| Description | Your customer company name here | Customer contact | Your contact person |
| Part No. | Your part description here | Customer phone No. | Your customer phone No. |
| Drawing number | Your drawing number | Customer fax No. | Your customer fax No. |
| Datum | Your datum | Report Type | Your type here |

Measure: Master part



CAD View Report 1

Alignment Features

| | | Hi-Tol | Lo-Tol | Nominal | Measured | Deviation | Error |
|--|---|--------|--------|---------|----------|-----------|-------|
| Circle 1 (Datum - Geometric PLP Alignment 1 (used in alignment definition)) | | | | | | | |
| Centre | X | 0.100 | -0.100 | 58.488 | 58.488 | 0.000 | |
| | Y | 0.100 | -0.100 | 52.439 | 52.439 | 0.000 | |
| | Z | 0.100 | -0.100 | 0.000 | 0.000 | 0.000 | |
| Diameter | | 0.100 | -0.100 | 13.001 | 13.001 | 0.000 | |
| Number of probed points: 4 | | | | | | | |

| | | | | | | | |
|--|--------|--------|---------|----------|-----------|-------|--|
| Circle 2 (Datum - Geometric PLP Alignment 1 (used in alignment definition)) | | | | | | | |
| | Hi-Tol | Lo-Tol | Nominal | Measured | Deviation | Error | |
| Centre X | 0.100 | -0.100 | 103.511 | 103.488 | -0.023 | | |
| Centre Y | 0.100 | -0.100 | 24.639 | 24.639 | 0.000 | | |
| Centre Z | 0.100 | -0.100 | -0.000 | -0.000 | 0.000 | | |
| Diameter | 0.100 | -0.100 | 13.001 | 13.001 | 0.000 | | |
| Number of probed points: 4 | | | | | | | |
| Line 1 (Datum - Geometric PLP Alignment 1 (used in alignment definition)) | | | | | | | |
| | Hi-Tol | Lo-Tol | Nominal | Measured | Deviation | Error | |
| Distance | | | | 46.267 | | | |
| Circles and Slot | | | | | | | |
| Circle 3 (Datum - Geometric PLP Alignment 1) | | | | | | | |
| | Hi-Tol | Lo-Tol | Nominal | Measured | Deviation | Error | |
| Centre X | 0.100 | -0.100 | 252.000 | 254.501 | 2.501 | | |
| Centre Y | 0.100 | -0.100 | 12.000 | 12.249 | 0.249 | | |
| Centre Z | 0.100 | -0.100 | -10.000 | -9.467 | 0.533 | | |
| Diameter | 0.100 | -0.100 | 10.000 | 10.001 | 0.001 | | |
| Number of probed points: 3 | | | | | | | |
| Circle 4 (Datum - Geometric PLP Alignment 1) | | | | | | | |
| | Hi-Tol | Lo-Tol | Nominal | Measured | Deviation | Error | |
| Centre X | 0.100 | -0.100 | 113.282 | 113.263 | -0.019 | | |
| Centre Y | 0.100 | -0.100 | 55.816 | 55.792 | -0.024 | | |
| Centre Z | 0.100 | -0.100 | 0.000 | 0.000 | 0.000 | | |
| Diameter | 0.100 | -0.100 | 13.001 | 13.000 | -0.001 | | |
| Number of probed points: 3 | | | | | | | |
| Circle 5 (Datum - Geometric PLP Alignment 1) | | | | | | | |
| | Hi-Tol | Lo-Tol | Nominal | Measured | Deviation | Error | |
| Centre X | 0.100 | -0.100 | 89.001 | 79.562 | -9.439 | | |
| Centre Y | 0.100 | -0.100 | 95.000 | 94.987 | -0.013 | | |
| Centre Z | 0.100 | -0.100 | 0.000 | 0.000 | 0.000 | | |
| Diameter | 0.100 | -0.100 | 13.001 | 13.001 | 0.000 | | |
| Number of probed points: 3 | | | | | | | |
| Circle 6 (Datum - Geometric PLP Alignment 1) | | | | | | | |
| | Hi-Tol | Lo-Tol | Nominal | Measured | Deviation | Error | |
| Centre X | 0.100 | -0.100 | 41.957 | 41.936 | -0.021 | | |
| Centre Y | 0.100 | -0.100 | 67.361 | 67.368 | 0.007 | | |
| Centre Z | 0.100 | -0.100 | 0.000 | 0.000 | 0.000 | | |
| Diameter | 0.100 | -0.100 | 13.001 | 13.000 | -0.001 | | |
| Number of probed points: 3 | | | | | | | |
| Circle 7 (Datum - Geometric PLP Alignment 1) | | | | | | | |
| | Hi-Tol | Lo-Tol | Nominal | Measured | Deviation | Error | |
| Centre X | | | | | | | |
| Centre Y | | | | 55.058 | | | |
| Centre Z | | | | 0.000 | | | |
| Diameter | | | | 79.961 | | | |
| Slot 1 (Datum - Geometric PLP Alignment 1) | | | | | | | |
| | Hi-Tol | Lo-Tol | Nominal | Measured | Deviation | Error | |
| Centre X | 0.100 | -0.100 | 0.000 | 0.149 | 0.149 | | |
| Centre Y | 0.100 | -0.100 | 37.500 | 37.589 | 0.089 | | |
| Centre Z | 0.100 | -0.100 | -29.000 | -29.451 | -0.451 | | |
| Overall length | 0.100 | -0.100 | 0.000 | 67.442 | 67.442 | | |
| Width | 0.100 | -0.100 | 12.000 | 12.130 | 0.130 | | |
| Number of probed points: 6 | | | | | | | |

The Information Tab

The **Info** tab allows you to view specific items for positional data, tolerances, deviations and errors. This can be displayed by selecting the item to be investigated from the Sequence Tree, and then selecting the **Info** tab. The following example shows the information for a Probed Circle:

Circle 1 (Probed Circle)

Information

| | |
|-------|--------------------|
| Datum | <Active Alignment> |
|-------|--------------------|

CNC Probe

| Entity | Instruction | Status | Probe | Sensor | Orientation | Source |
|----------|---|--------|-----------|------------|--|------------------------------|
| Circle 1 | Sensor definition Probe orientation change | OK | TP20x20x2 | M2_20x2_SS | Specified: A=0, B=0 Adjusted: A=0, B=0 I=0.00000, J=0.00000, K=1.00000 | Default Probe and Parameters |

Probe Path Faults

| | |
|---------------------|-----------------|
| Verification Status | No faults found |
|---------------------|-----------------|

Links

| Name | Link |
|-----------------|---------|
| Reference Plane | Plane 1 |

Parameters

| Name | Start Angle | End Angle |
|--------------------|--------------|-----------|
| Angle Quadrant | -269.996° | 90.004° |
| Name | Value | |
| Material Side | Hole (ID) | |
| Name | Used | Offset |
| Guided Measure | No | -1.000 |
| Name | Value | |
| Fitting Algorithm | Least Square | |
| Orientation | I | 1.00000 |
| | J | 0.00000 |
| | K | 0.00000 |
| Name | Used | Value |
| Auto accept points | No | 3 |

Properties

| | | Nominal | Lo-Tol | Hi-Tol | Actual | Deviation | Error |
|------------------|---|---------|--------|--------|------------|-----------|-------|
| Centre | X | 56.489 | -0.100 | 0.100 | 56.445 | -0.044 | - |
| | Y | 22.640 | -0.100 | 0.100 | 22.599 | -0.041 | - |
| | Z | 0.000 | -0.100 | 0.100 | 0.042 | 0.042 | - |
| Diameter | | 13.001 | -0.100 | 0.100 | 12.926 | -0.076 | - |
| | | Value | | | Calculated | | |
| Offset/Thickness | | 0.000 | | | No | | |
| | | Maximum | | Actual | | Error | |
| Circularity | | 0.100 | | 0.000 | | | |

Exported Items


| Name | Type | Description | Linked as |
|-----------------------|--------------------|-----------------------|-----------|
| Circle 1::Centre | pwi_feature_Point | Circle 1::Centre | |
| Circle 1 | pwi_feature_Circle | Circle 1 | |
| Circle 1::Normal Axis | pwi_feature_Line | Circle 1::Normal Axis | |

☐ List of probed points (probe centre)


PowerInspect CNC Help

PowerInspect CNC comes with an online help which can be accessed from the **Help** menu. When faced with a problem, it is best practice to make the **Help** menu your first port of call.

To access the online help, select **Contents** from the **Help** menu.




The most effective way to use the Reference Help is to use the **Search** tab to search for help topics, but you can also browse the **Contents** or **Index**.




To target your search more effectively, enclose the search terms within quotation marks. For example, to search for help on exporting point clouds, enter "Export point cloud" in the search box so that only topics containing this exact phrase are displayed.

Customising PowerInspect CNC

Select **Tools > Options** to display the **Options** dialog and specify settings and defaults for PowerInspect CNC.



Use the **Options** dialog to specify settings including, the colour of entities, the size of points, confetti or edge points and toggle displayed items such as the CAD Datum.




02. Machine Tab

The **Machine** tab enables you to configure the tools you will use for an inspection, to model the measuring device displayed in the CAD view, and to calibrate the probe head and probe assembly prior to an inspection. It contains a Probe view that displays the status of your probes and probe assemblies, and nine areas that cover the different aspects of machine management.

To view and configure the measuring device for an inspection:


- 1 Select **File > New Session**.
- 2 At the top of the Sequence Tree, select the **Machine** tab.



- 3 To display the details of an area, click its title. To close an area, click the title again.

Setting the calibration details

The **Calibration** area of the **Machine** tab displays the diameter and name of the sphere used to calculate the position of the probe and the effective diameter of the stylus.



Use the area to customize the calibration process, and to view and manage calibrations. Click:

- **Change** to move the calibration sphere. The **Calibration Sphere Repositioning Wizard** is displayed.
- **Calibration settings** to change the number of calibration points, the safe distances settings, traceability, or manual calibration. The **Calibration Settings** dialog is displayed.




*The **Calibration Settings** button is not available when **Simple calibration mode** is selected in the **Calibration** page of the **Options** dialog.*

- **Calibration Details** to view and export the details of calibrations for traceability purposes.

Specifying the machine

The **Machine** area enables you to select the measuring device displayed in the CAD view so that on-screen simulations are shown realistically.



To specify the machine model:

- 1 Click **Change Model**.



*Alternatively, you can select the **Tools > Simulator > Change Machine Model** menu option.*

- 2 In the **Open** dialog, navigate to the \CMM folder of your PowerInspect CNC installation, and select the model you want to display. For this example, select **No_model_head-head.mtd**.




If your machine is not listed, contact your reseller to request the model you need.

- 3 Click **Open** to display the model in the **CAD View** tab.

Selecting the probe head

The **Probe head** area enables you to select and calibrate the head to be used for the inspection. By default, PowerInspect CNC includes the complete range of Renishaw CNC probe heads; contact your reseller to add heads from other manufacturers.




To select the probe head for the inspection:

- 1 In the drop-down list, select **Renishaw PH10T**. The head is displayed in the **CAD View** tab.
- 2 If the head in the CAD view is not aligned with the head of the measuring device, use the **RX**, **RY**, and **RZ** boxes to rotate the on-screen head to the same orientation as the device head. Click **Apply** to save your changes.

Creating the probe tool

The **Probe Tool** area enables you to specify and select probe assemblies for the inspection. The probe assembly is built from the Renishaw catalogue; the available options are determined by the selection you make in the **Probe Head** area.



To create a probe tool assembly:

- 1 Click **New** in the **Probe tool** area. The **Probe Tool Assembly** dialog is displayed.

Probe tool assembly

Default

.....Probe tool assembly (to m8)

Remove Part

Available probe tool parts

Probe bodies

| Name | Length | Diameter | To | From |
|------------------|----------|----------|--------------|------|
| MDM_Probe | 10.00 mm | | m3 | m8 |
| TP2 | 38.00 mm | | m2 | m8 |
| TP20 | 17.50 mm | | AutoMagnetic | m8 |
| TP200 | 30.00 mm | | AutoMagnetic | m8 |
| TP6 | 41.00 mm | | m3 | m8 |
| Eagle_p_touch_SF | 26.30 mm | | m2 | m8 |
| Eagle_p_touch_EF | 26.30 mm | | m2 | m8 |
| Eagle_p_touch_MF | 26.30 mm | | m2 | m8 |
| Eagle_p_touch_LF | 26.30 mm | | m2 | m8 |
| Eagle_p_touch_r | 41.00 mm | | m3 | m8 |
| Eagle_mp_body | 20.35 mm | | AutoMagnetic | m8 |

Insert Part Create custom part

- 2 In the **Probe tool assembly** box, enter **TP20_MED_20x2** as the name of the assembly.
- 3 In the **Available probe tool parts** drop-down list, select **Probe bodies**.
- 4 In the list of bodies, select **TP20** and click **Insert Part**.



*If the body you want to use is not listed, click **Create Custom Part** to specify the details of the body.*


The part is added to the **Probe tool assembly** list, and the list's insertion line moves to show where the next part will be inserted. In addition, the **Available probe tool parts** lists the modules available for the body you selected.

- 5 In the list of modules, select **TP20_MED**, and click **Insert Part**.

The part is added to the **Probe tool assembly** list, the list's insertion line moves is updated and the **Available probe tool parts** lists the available styli.

- 6 In the list of styli, select **M2_20x2_SS** and click **Insert Part**.
- 7 Click **Save** to save the changes and close the dialog.

The assembly is displayed in the **Probe tool** area. It is also selected as the current probe tool in the Probe view at the top of the **Machine** tab, and displayed in the CAD view.



If you need to update the tool, click **Edit**.




To copy a probe assembly, click **Clone**.


Calibrating the probe

Before you can inspect a part, you must calibrate the probe head and the assemblies you want to use. This enables PowerInspect CNC to calculate the effective stylus diameter and to apply compensation to measurements.

To calibrate the probe:



- 1 In the **Machine** toolbar, click  to connect the document to the measuring device.
- 2 In the **Calibration** area, click **Calibration Settings**. The **Calibration Settings** dialog is displayed.
- 3 To automate the calibration process, deselect the **Perform manual calibration** check box, and click **OK** to close the dialog.
- 4 In the **Probe head** area, click **Calibrate**. The **Probe Head Calibration Wizard** is displayed.
- 5 Read the information in the first dialog, and click **Next**. The Limits dialog is displayed.
- 6 Leave the limit values unchanged, and click **Next**. The **Calibration Sphere** dialog is displayed.
- 7 Enter the calibration sphere parameters:
 - a In the **Enter the diameter of the calibration sphere** box, type **20**.
 - b In the **Enter the name of the calibration sphere** box, type **Sphere20**.
 - c Leave the direction settings unchanged, and click **Next**. The Probe Selection dialog is displayed.
- 8 Select the probe tool you created earlier, and click **Next**. The Probe Head Main Orientation dialog is displayed.
- 9 Leave the orientation unchanged, and click **Next**. The Probe Head Angles dialog is displayed.
- 10 Select the **(A0 : B0) (A90 : B0) (A90 : B90)** option to specify the probe head angles you want to calibrate, and click **Next**. The first Calibration dialog is displayed.
- 11 In the dialog:
 - a Manually probe the point on the calibration sphere normal to the probe assembly.
 - b Position the probe so it can rotate without touching the sphere, and click **Set A=90, B=0**. The probe rotates to the new orientation.
 - c Probe the sphere at the same position you used in step a.
 - d Click **Next**. The **Assisted Calibration** dialog is displayed.
- 12 Position the probe so it can rotate without touching the sphere, and click **Next**.
- 13 In the warning message, click **Yes**. PowerInspect probes the sphere to complete the calibration. When it has finished, the results are displayed in the dialog.
- 14 Click **Finish** to close the wizard. The last calibration date; the effective or nominal diameter of the stylus and its sphericity are displayed below the Probe view, for example:



In addition, icons indicate whether the probe and probe position are calibrated ✓, calibrated but outside form tolerance ⚠, or uncalibrated !.



The ⚠ icon is only displayed when you specify a form tolerance for the calibration in the **Calibration Settings** dialog.


You can now probe the part or create more head positions.



To check the results of all the calibrations you have made for the document, open the **Calibration** area, and click **Calibration Details**.

Adding probe positions

When you have selected an indexable head, such as a PH10, you can specify multiple probe positions so that the probe is at the optimum orientation for measuring the different features on the part. The **Probe head angles** area enables you to specify any probe orientations not included in the original calibration.




To specify a position for the inspection:


- 1 In the **A** box, enter an angle of **45** degrees.
- 2 In the **B** box, enter an angle of **0** degrees.

- 3 Click **Create** to add the position to the Probe view list, or click **Create & Apply** to add the position and select it.




You can also create new positions by selecting **ToolCollection** in the Probe view, and then clicking .

To calibrate the new position:

- 1 Select the position  in the Probe view.
- 2 Click the **Calibrate Selected Item** button. The Probe Calibration Wizard is displayed.
- 3 Position the probe so it can rotate without touching the sphere, and click **Next**. PowerInspect probes the sphere and reports the results.
- 4 Click **Finish**. The results of the calibration are displayed in the Probe view.

Setting target points

The **Target Point** area enables you to find the current position of the probe, or to move the probe to a specified position.





If the document is not connected to the measuring device, only the probe in the CAD view is moved.




To set a target point:

- 1 Choose an entry in the list to specify the coordinate system you want to use. Select:
 - **CMM Probe Tip Coordinates** to specify the target coordinates relative to the position of the probe tip.
 - **CAD Coordinates** to specify the target coordinates relative to the PCS (CAD Datum).




The list is not displayed when **<no measure>** is selected in the Active Measure list.

- 2 To display the current position of the probe, click . The position is displayed in the X, Y, and Z boxes.
- 3 Choose the method with which you want to specify the position of the target point:
 - Select the mode  button to specify the position relative to the origin of the coordinate system.

- Deselect the mode  button to specify the position relative to the probe's current position.
- 4 Enter the point's coordinates in the **X**, **Y**, and **Z** boxes.
- 5 Click  to move the probe to the target point; click  to halt the probe movement.

Controlling the simulation speed

When you simulate an inspection in the **Run** tab, PowerInspect CNC runs the simulation in real time, by default. Use the **Simulation Parameters** area to change that speed if you want to slow down the simulation to check the details, or speed up the simulation to just make a final check.



To specify the scaling factors for the simulator:


- 1 If you want to synchronize the speed multipliers, select the **Use the same factor** check box.
- 2 Move the **Simulation move speed multiplier** slider to change the speed at which GoTo (or rapid) moves are performed. The multiplier is displayed at the right of the slider.
- 3 Move the **Simulation measure speed multiplier** slider to change the speed at which measurement (or touch) moves are performed. The multiplier is displayed at the right of the slider.


Viewing the machine parameters

The **Parameters** area enables you to view and change the current probing parameters of the measuring device when the document is connected to it.



To view or change the machine parameters:

- 1 Connect to the measuring device.
- 2 In the **Joystick retract** box, enter the distance that the probe automatically retracts when you use the joystick to take a touch point.
- 3 Click  to display the CMM Parameters. The **CMM Parameters** dialog is displayed.



- 4 Select the different tabs to view the parameters; position and hold the mouse cursor over a box for more information on a setting.
- 5 When you are finished, click **OK** to close the dialog.



*To maintain consistency, you are recommended to use **Probe** and **Parameters** items to specify the machine settings for each stage of an inspection.*

Importing and exporting probes

The probe head and probe tool settings on the **Machine** tab are saved with the PowerInspect document (.pwi file), so the next time the file is opened the details are remembered. You can export these settings to a file, and then import them into other inspection documents to avoid the need to set up the same settings for each new session.

To export the current settings to a file:

- 1 Click **Export** on the **Machine** tab to display the **Save As** dialog.
- 2 Enter a name for the settings file in the **File name** box. The settings are saved in a .prd file.
- 3 Click **Save** on the **Save As** dialog to return to the **Machine** tab.

To import settings from a file:

- 1 If you are importing the probe database from a measuring device, use the **Export** button to create a back up of the current settings.
- 2 Click **Import** on the **Machine** tab to display the **Open** dialog. If a warning message is displayed, click **Yes** to replace the current settings; click **No** to continue to use the current settings.
- 3 Select the .prd file that contains the settings you want to use.
- 4 Click **Open**. The settings in the .prd file are applied to the document and displayed in the **Machine** tab.

If the current **Machine model** and **Probe assembly** settings are the typical setup used for your inspections, click **Export as default**. When you next create a document, PowerInspect will automatically load your current settings so you don't need to repeat the configuration process each time you start a new inspection.

3. CAD Management



The manipulation of CAD data within PowerInspect CNC is very important. Using the **CAD File Manager**, you can add or remove CAD files, transform CAD data in relation to datums and indicate levels to be included in the inspection.


Coordinate Systems

When you create an inspection session, PowerInspect CNC automatically creates two coordinate systems:


- The Machine Datum is the X 0, Y 0, and Z 0 of the 3D coordinate measurement machine.
- The PCS Datum (Part Coordinate System Datum), is the X 0, Y 0, and Z 0 of the CAD model. If the PCS Datum is in the wrong location, you can transform it using translations and rotations.

When the part is aligned with the CAD model, PowerInspect CNC automatically converts the movements from the Machine Datum coordinate system to the PCS Datum coordinate system.

By default, these datums are not displayed in the CAD view. To display them, click the light bulb  icon next to their entries in the Sequence Tree. The icon changes to  to indicate the datums are displayed. In this example, the PCS Datum is shown at the corner of the part; the Machine Datum is shown above and left of the PCS Datum.





In addition to the datums, a graphical representation of the coordinate system of the active alignment (the PCS Datum, by default) is displayed at bottom left of the CAD view. It allows you to identify the axes of the active alignment when the active alignment is not visible on screen.




CAD File Manager



To display the **CAD File Manager**, select the **CAD** tab.



When you select the tab, the window displays the **Parts** folder and the **User Levels** area. Click the  icon to open folder and display the sub-items.



The coloured box indicates the colour with which each level is displayed in the **CAD View**. Change the colour by left-clicking the box, and assigning a new colour from the palette.

The light bulbs indicate whether the level is displayed  or not  in the **CAD View**, and the check box ☒ includes or excludes the level from the **CAD Context**. These can all be switched on or off by left-clicking on them.

When the **CAD File Manager** is opened, a toolbar is displayed at the top of the tab with a number of functions that can be used to manipulate the CAD data.



This toolbar enables you to:

- add or remove CAD files.
- reset the user levels.
- edit the CAD details.
- show or hide CAD files and the detailed view.


Transformations



Click the **CAD Details** button to open the **CAD Details** dialog. This dialog enables you to locate CAD files and apply transformations to them.


Transformations are used to orientate parts within the **CAD View**.

To transform any CAD data, you must first specify the part by using the **Browse** button in the **CAD Details** dialog.




You cannot use PowerInspect CNC to edit the CAD model. You can create, hide and edit levels, but they cannot be saved to the CAD model and they are only visible within PowerInspect CNC.

When the part is specified, click **Transformation Matrix** to open the **Transformation Matrix** dialog.




Use this dialog to specify any transformation (**Rotation**, **Translation**, **Mirror** and **Scale**), by clicking on the appropriate button and entering the desired values.

For example, clicking **Rotation** opens the **Rotation** dialog. In this dialog, you can specify the rotational axis (for example, the X axis) and the angle by which the part is rotated (for example, 90 degrees).




Click **OK** to close the **Rotation** dialog. The **Transformation Matrix** dialog is updated with the new value.




Click **Load** to read and load workplanes from multiple CAD formats (supported by **Autodesk Exchange**).

When a CAD model is selected, the **Select Workplane** dialog lists all the workplanes associated to the model.



When you select a workplane, its transformations are displayed in the **Transformation Matrix** dialog.




Click **OK** to apply the transformations to the model relative to the datum.

These transformations can be saved, deleted, edited and tested within this dialog. To edit or delete a transformation, left-click its entry in the **Transformation Matrix** dialog.

Summary and Detailed CAD View



Click the **Summary/Detailed View** button on the **CAD File Manager** toolbar to expand the CAD information area and display more information about the part files.




The information displayed includes any transformations, the levels, part locations and the number of entities that make up the part.



The extent values indicate the dimensions of the part in relation to the datum origin.



Click **Summary/Detailed View** again to return to the data summary.




When the **Levels** section is expanded, the sub-levels reveal the individual surfaces.

As before, the light bulbs hide  or show  the individual level or surface. The check box ☒ includes or excludes the level from the CAD context. These icons can be switched *ON* or *OFF* by left clicking on them.

The levels can also be managed from the Menu bar.


Select **Measures > CAD Levels for Inspection** from the Menu bar to display the levels section.




CAD Menu Options

As well as the **CAD File Manager**, CAD edits can be made using some of the options on the Menu bar.

The **Measures** menu contains two options that are relevant to the CAD management.




Select **Parameters** to open the **Measure Parameters** dialog. This dialog contains a series of tabs that relate to different areas of PowerInspect CNC.





Level Edits

CAD data within PowerInspect CNC can be transferred to other or new levels.


Click the **Surface Selector**  button in the **Mouse Context** toolbar to specify which surfaces you want to move, and to which level.

To create a new level:

- 1 Click the **Surface Selector**  button on the **Mouse Context** toolbar.
- 2 Use the left mouse button to box-select the surfaces that you want to add to a level.




When you release the mouse button, the selected surfaces are highlighted.




Alternatively, you can select individual surfaces by left-clicking the model.

- 3 Right-click anywhere on the highlighted selection and select **Group Surfaces** from the local menu.




The **Level Manager** dialog is displayed.




- 4 To add the selected surfaces to an existing level, select the level in the **Available levels** list, and select **OK**.

To add the selected surfaces to a new level, enter a **Name** for the level, and click **OK**. The level appears in the **User levels** area of the **CAD File Manager**.



This technique can be useful if there is a large quantity of data in a view. Each layer has an associated colour, which is used when colour shading the model. To change the shading colour of a level, left-click the small coloured box to the left of the level's name, and select a new colour from the palette.



4. Calibration

Within PowerInspect CNC it is vital that the probe is correctly calibrated as these will affect the results. Using the various wizards you are lead through the steps taken in order to calibrate your CNC CMM easily and effortlessly.

The process of calibration allows physical properties of the probe and the stylus to be calculated. Such values include the contact radius and effective length of the probe


Probe Head Calibration

The first part of the calibration process in PowerInspect CNC is to calibrate the probe head attached to the CNC CMM.

- 1 Select > File -> New Session.
- 2 Build the probe from the database of components ensuring that all parts specified match the physical probe used in the inspection. In this example we will be using the PH10T head with a TP20_2mmx20 probe setup



To refresh this process read chapter 'Machine tab'.



- 3 Select the PH10T in the machine tab probe view and click on the 'Calibrate selected item' icon



This initiates the probe head calibration wizard, which leads the user through the calibration in a step by step process.



It is important that the user is compitant in using the software and opertating the CNC CMM as this could potentially damage eqiptment

- 4 If the user accepts the warning message, press next to move on to the next dialog method
- 5 Enter the appropriate limits of the CNC in use, for this example the default limits predefined in PowerInspect CNC

Welcome to the Probe Head Calibration Wizard

This wizard will guide you through the steps required to fully calibrate a probe head

Please enter the valid limits of the CMM. This describe the volume in which the probe head can move


| | | | |
|-------|--|-------|---------------------------------------|
| X min | <input type="text" value="-5000.000"/> | X max | <input type="text" value="5000.000"/> |
| Y min | <input type="text" value="-5000.000"/> | Y max | <input type="text" value="5000.000"/> |
| Z min | <input type="text" value="-5000.000"/> | Z max | <input type="text" value="5000.000"/> |

- 6 Once defined select the diameter of the calibration sphere, in this instance the sphere is 20mm

Welcome to the Probe Head Calibration Wizard

This wizard will guide you through the steps required to fully calibrate a probe head

Calibration sphere parameters



Enter the diameter of the calibration sphere

 mm

Enter the direction of the stem (from the base to the centre of the calibration sphere)

| | |
|----|------------------------------------|
| Z+ | <input type="text" value="1.000"/> |
| I | <input type="text" value="0.000"/> |
| J | <input type="text" value="0.000"/> |
| K | <input type="text" value="0.000"/> |

Cancel < Back Next > Finish

- 7 Once defined select 'Next' and assign the appropriate probe build - This will be TP20_2mmx20
- 8 Follow the steps through until the following window in displayed and then follow the instructions step by step to calibrate the probe head. To move the probe into the required position, use the CNC CMM joystick.

Welcome to the Probe Head Calibration Wizard
This wizard will guide you through the steps required to fully calibrate a probe head

- 1 Move the probe to a safe position and set up the A and B angles of the probe head to be A=0, B=0
Or alternatively press on this button to do it in CNC
- 2 **Probe a point at the top of the Calibration Sphere**
- 3 Move the probe to a safe position and set up the A and B angles of the probe head to be A=90, B=0
Or alternatively press on this button to do it in CNC
- 4 Probe a point at the top of the Calibration Sphere
- 5 Click the NEXT button to go to the next page

The calibrated measuring speed is the feedrate, at which the probe is calibrated, it is very important that any measurements using the probe are taken at the calibrated speed. It is important as this ensures that the deflection of the stylus remains constant and therefore the results are consistent.

9 Once complete click finish to end the head calibration

Calibration is important as PowerInspect CNC will not run a program as a safety precaution because there is a high risk in damaging the probe head or the stylus due to incorrect movements.

Stylus Calibration


The second stage of the calibration process in PowerInspect CNC is to calibrate the the stylus with the probe head angles.

There are two methods of calibrating the probe head angles in PowerInspect CNC. The first one is to open the single probe head angle calibration wizard and then second is to calibrate a batch of probe head angles for time saving purposes.

- 1 In the same session, input a series of different probe head angles by selecting the 'Add new positions' icon.



- 2 Use the sliders to select the angles of rotation to set a number of probe orientations



- 3 These are then saved in the probe view but remain uncalibrated

When creating a sequence of inspection steps, a number of features of the part being measured may require different probe head angles. These will automatically be added to the list without the need to perform step 2.

- 4 To calibrate a single probe angle, select the probe head angle in question and click on the 'Calibrate selected item' icon.



- 5 Follow the onscreen instructions to calibrate the probe angle.

The second method is to calibrate a number of angles in a single process. To perform this method, simply repeat steps 1-3 and select 'Calibrate uncalibrated positions' icon and follow the on screen instructions



5. Alignments


Alignments enable PowerInspect CNC to match the positions and orientations of the CAD model to the part. The type of alignment selected is dictated by the component's shape and which features can be used to create it.

Alignments are accessed by selecting **Alignments** in the **Item** toolbar.




The most widely used alignments are described in this chapter.

Geometric PLP Alignment

The **Geometric PLP Alignment**  is based on the relationship of a physical **Plane**, **Line** and **Point** (PLP), and **CAD Defined Coordinates**, which define the part in the **X**, **Y** and **Z** axes. It is an accurate method of alignment because it works directly from CAD nominal values, and can be an easier method to understand.

Generating a Geometric PLP Alignment

For this example the DemoBlock2008 CAD file is going to be used.

- 1 In the **Main** toolbar, click  to open the **New Document Wizard**.
- 2 Select **Measurement with a single CAD Part** and click **Next**.
- 3 Click **New** and open **DemoBlock2008(CMM+Arm).ddz**.
- 4 Leave the **Offset** and **Tolerance** settings unchanged, and click **Next**.
- 5 In the **Variables** dialog, browse for any HTML Report Template (Excel could be used, but for this example HTML is to be used).
- 6 Click **Finish**. The new session is now ready for inspection.

Choosing the Geometric features

Before the alignment can begin, a decision needs to be made on where the Plane, Line and Point are going to be aligned to, and what will determine these elements.

The Plane

With any alignment, the results are better if a greater area spread is used to define the aligning elements. In this example, the CMM bed (or table) will be used to define the plane, because the model has a flat base, and all the planes in the model are small.

The Line


Lines can be defined from square edges (probed lines), or from the connection or intersection of measured features. In this example, the line is to be defined in the X direction, using the centres of two measured circles on the part.



The line direction in a Geometric PLP Alignment must be axial.

The Point

Because the circles will have already been defined, the centre position of one of these circles will be used for the point position.





The two circles chosen are indicated, and the plane will be the top flat face. The line will be between the centres of both circles, and the point will be taken from the centre of circle 1.

Both circles and line will be projected onto the same probed plane.

Defining the Geometric Items

When you have chosen the features to use for the alignment, you must now define the geometric items to probe.


- 1 In the **Machine** tab, create a 3 mm probe and select it in the Probe view.
- 2 In the **Mouse Context** toolbar, select the **Wireframe Checker**  button.
- 3 Right-click an empty area of the graphics window and select **Surface** from the menu.
- 4 Select the top plane as shown, and double-click the surface to create probe points shown below.




- 5 In the **Plane Inspect** dialog, click  to add the item to the Sequence Tree.

- 6 Select the **Wireframe Checker**  button.


- 7 Right-click an empty area of the graphics window and select **Wireframe** from the menu.
- 8 Move the cursor over the circle shown below. When the circumference is highlighted, left-click to select it.





- 9 Select the **Geometry Explorer** tab, and select **Plane 1** in the **Linked to** list.

- 10 Click  to add the item to the Sequence Tree.


- 11 Move the cursor over the circle shown below. When the circumference is highlighted, left-click to select it.



- 12 Click  to add the item to the Sequence Tree.




- 13 In the **Item** toolbar, select **Lines** , and click . The **Line: Two Points** dialog is displayed. Ensure that the reference points are set as follows:


- **Reference Point 1 — Circle 1::Centre**
- **Reference Point 2 — Circle 2::Centre**



- 14 Click **OK** to add the line item to the inspection sequence.
- 15 Select the **Run** tab and simulate the inspection.

Creating a PLP alignment

- 1 In the Sequence Tree, click  to close the group.
- 2 From the **Alignments** , select **Geometric PLP** . The **Geometric PLP Alignment** dialog is displayed.
- 3 In the **Plane** area, select **Plane1**.
- 4 In the **Line** area, select **Line 1**.
- 5 In the **Point** area, select **Circle 1::Centre**.




- 6 Click **OK** to save your changes and close the dialog. The alignment inspection sequence is now ready to be run.

RPS Alignment

The Reference Point System (RPS) alignment is a technique developed by Volkswagen and has now become an industry standard for inspection. As an alignment technique, its method lies somewhere between a **Free Form** alignment and a **Geometric** alignment, combining the benefits of both, with the ability to accept geometric positional data and surface points.


Generating an RPS Alignment


Using the methods previously described in the course for starting a new session:

- 1 In the **Main** toolbar, click  to open the **New Document Wizard**.
- 2 Select **Measurement with a single CAD Part** and click **Next**.
- 3 Click **New** and open **DemoBlock2008(CMM+Arm).ddz**.
- 4 Leave the **Offset** and **Tolerance** settings unchanged, and click **Next**.
- 5 In the **Variables** dialog, browse for any HTML Report Template (Excel could be used, but for this example HTML is to be used).
- 6 Click **Finish**.

Choosing the features


As with other methods, you must specify which geometric features can be used to determine the alignment. In this example, the part is aligned using a series of probed circles. The centres of these circles are then used to determine the RPS alignment. The **Geometry Explorer** is used to create these circles.

- 1 In the **Machine** tab, create a 3 mm probe and select it in the Probe view.
- 2 In the **Mouse Context** toolbar, select the **Wireframe Checker**  button.
- 3 Right-click an empty area of the graphics window and select **Surface** from the menu.
- 4 Create the probed plane shown below.



- 5 Right-click in the CAD View and select **Wireframe** from the menu.


- 6 Select the circle shown below.




- 7 Select the **Geometry Explorer** tab, select **Plane 1** in the **Linked to** list, and click



- 8 Create inspection items for Circle 2 and Circle 3, linking them all to Plane 1.



The Sequence Tree displays the four items, a plane and three circles, which can also be seen in the CAD View.





- 9 Select the **Run** tab and simulate the inspection.

Creating an RPS Alignment

An RPS alignment will now be used to align the CAD model to the part.

- 1 In the Sequence Tree, click  to close the group.










- 2 From the **Alignments**  toolbar, select **RPS Alignment** . The **RPS Alignment Definition** dialog is displayed.

RPS Alignment Definition

Name: RPS Alignment 1

Local Datum: Adjust coordinate system used for nominals. Edit Datum...

Offset: Adjust the position and orientation of the alignment. Edit Offset...


| | Lock | | | Offset |
|---|--|---|--|--------|
| | x/a | y/b | z/c | |
| Circle 1::Centre  | <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/>  | 0.000 |
| Circle 2::Centre  | <input type="checkbox"/> | <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/>  | 0.000 |
| Circle 3::Centre  | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/>  | 0.000 |

☐ Use transformed data

☐ Output in report

Standard Deviation:

OK Cancel Apply

- 3 Select **Circle 1::Centre** in the drop-down list to add it to the alignment. Click  to add further items to the alignment as shown.

The **Lock** columns are used to specify the translation and rotation axes that each feature is used to constrain. The selections shown are just enough to create a 3-2-1 alignment, so the part is said to be perfectly constrained.

If you add further locks to the alignment, the part is said to be over constrained. In this case, PowerInspect creates a best fit that minimizes the deviations between the part and the model for all the features.

- 4 Click **OK** to save your changes and close the dialog.

Best Fit From Points Alignment



The **Best Fit from Points** alignment can be used to align the part from three or more points for which the CAD coordinates are known. PowerInspect uses these points as geometric items to carry out a best fit to align the CAD data.


Before you use this alignment, you must create geometric items that provide at least three points. Points include centres of geometric items, such as the centre of a circle or sphere. You must also know the nominal position of the points: if you do not have this information, you can extract the coordinates using the **Geometry Explorer** tab.



*A **Best Fit** alignment can produce the same results as a **Three Spheres** alignment if spheres are used to supply the three points. A **Three Spheres** alignment uses tooling balls; it is predominately used in the aerospace industry.*

Generating a Best Fit from Points Alignment




- 1 In the **Main** toolbar, click  to open the **New Document Wizard**.
- 2 Select **Measurement with a single CAD Part** and click **Next**.
- 3 Click **New** and open **DemoBlock2008(CMM+Arm).ddz**.
- 4 Leave the **Offset** and **Tolerance** settings unchanged, and click **Next**.
- 5 In the **Variables** dialog, browse for any HTML Report Template (Excel could be used, but for this example HTML is to be used).
- 6 Click **Finish**.


Choosing the Geometric Items

As with the previous methods, you must decide which geometric features can be used to determine the alignment. It is best to choose points that create a triangle shape, to lock the part in place. In this example, the part is aligned using a series of probed circles. The centres of these circles are then used to determine the best fit points.






- 1 In the **Mouse Context** toolbar, select the **Wireframe Checker**  button.
- 2 Right-click an empty area of the graphics window and select **Surface** from the menu. Select the top flat plane as before and create 4 probe points on the surface.
- 3 Right-click the CAD View, and select **Wireframe** from the menu.


- 4 Select the three circles shown, and use the Geometry Explorer to link them to Plane 1.



- 5 Select the **Run** tab and simulate the inspection.

Generating a Best Fit From Points Alignment

- 1 In the Sequence Tree, click  to close the group.
- 2 From the **Alignments**  toolbar, select the **Best Fit from Points Alignment**  button. The **Best Fit Form Points Alignment** dialog is displayed with Point 1/3 selected.





- 3 Select **Circle 1: Centre** from the drop-down list. The nominal position values of the circle are displayed.


PowerInspect automatically uses the **X, Y and Z** coordinates for **Circle 1::Centre** because the nominal values have been extracted from the CAD model using **Geometry Explorer**. If you want to load the nominals yourself, deselect **Automatically use feature nominals**, and click **Load Nominal>>**.



*By default, PoweINSPECT creates a best fit for all the features in the alignment. If you want the alignment to leave the nominals of the first point unchanged, select the **Hard point** check box.*

- 4 Click  to display **Point 2/3**.
- 5 Select **Circle 2::Centre** and then click **Load Nominal**.
- 6 Click  to display **Point 3/3**.
- 7 Select **Circle 3::Centre** and then click **Load Nominal**.



A minimum of three points are required for the alignment. You can add more points by clicking .

- 8 Select **OK** to create the **Best Fit** alignment.


6. Controlling Machine Movements

PowerInspect CNC generates a series of probe paths from the user defined inspection sequence, which can be executed on the calibrated CMM. The probe paths are largely controlled by feature selection, and the order in which individual features are positioned in the Sequence Tree, but it is important to control the position of the probe head and the probe paths outside the selected features.

We have a variety of features available to allow us to do this within PowerInspect CNC. These features are covered in the following section.

Default Probe and Parameters

These parameters control the default distances and speeds associated with the probe movement.



Although the distances specified here are global settings, you can adjust them by creating a Probe and Parameters  item from the **Miscellaneous**  toolbar.

Probe and Parameters

Name: Default Probe and Parameters

Reference item
<No reference item>

Probe tool
☒ Set up probe tool
 Probe: TP20x20x2
 Sensor: No_Model:TP20x20x2:M2_20x2_SS
 Measure head touch: ☐ Undefined

Distances | Speeds | Accelerations

| | Name | Value | Units |
|-------------------------------------|-------------------|-----------|-------|
| <input checked="" type="checkbox"/> | Approach | 2.000 | mm |
| <input checked="" type="checkbox"/> | Search | 10.000 | mm |
| <input checked="" type="checkbox"/> | Retract | 2.000 | mm |
| <input checked="" type="checkbox"/> | GoTo blend radius | 5.000 | mm |
| <input type="checkbox"/> | Scan blend radius | Undefined | |
| <input type="checkbox"/> | Scan retract | Undefined | |

OK Cancel Help

Approach specifies the distance from the selected measure point along the probing vector, to which the probe is moved before the measure move begins (i.e. measure start position). Given that the physical part may not be in the exact location, or cut to the exact specifications of the part, the probe may not make contact with the part when it is driven to the specified contact location.

Search specifies the distance from the approach point to an arbitrary point along the probing vector in which the **measurement contact point** is expected.

Retract specifies how far the probe will retract from the theoretical contact position when the probe is triggered.


The **Goto** speed can be output to the CNC CMM to control the speed between features in the sequence tree. Measure speeds should be set to the calibrated probing speed for the probe used on the machine.

Approach, Search and Retract distances

Each measured point in PowerInspect CNC consists of a number of moves to complete the measurement. These are made up of:

- Connecting moves between the measured features
- If safe plane is enabled, connecting moves at the safe plane height to the approach point
- Approach moves, from the safe height to the target probe point
- Retract moves from the target point to the safe height.

The diagram below shows the various moves to measure a feature:



It is important these positions are known, and can be controlled. PowerInspect CNC lets you specify a number of default values, which enable each of the above positions to be calculated.

The default values can be overridden for each measured item in the Sequence Tree, to give full control of the different features and methods.


It is also possible to specify three different speeds for the movements which make up a measurement sequence, through the CNC option file, although all three may not be implemented in all CNC option files.

These are:

- Connecting move speed
- Approach speed
- Measure speed

Probe Safe Parameter


During probe path creation you can specify a position to which the probe will move before and after probing the points of a feature. This can be done by setting the **Probe Safe** distance on the **Feature** tab. The positions of the moves are calculated relative to the normal of a plane for 2D features, and normal to the initial probing vector for 3D features and surface inspection points.




Safe Plane

The **Probe Safe** parameter is used in the **SafePlane** probing method.


The Safe Plane is the height above the component to which the probe moves before performing the connecting move to the next inspection point, as shown in the diagram.




Collisions

Collisions can sometimes occur in a probe path and show up in the Sequence Tree as a brown star  on the inspection item.



Edit the feature using **Edit Geometric Item**  button in the **Features** tab to alter the probe paths so there are no collisions.


When there are no collisions, a green star  is shown instead.



Intermediate Paths


Intermediate Paths can be used to avoid collisions between features.

- 1 Import the DemoBlock2008(CMM+Arm) CAD file into a new session in PowerInspect CNC.
- 2 Create two probed planes as shown below.



- 3 Select the **View > Probe Paths > Show All** menu option.

This shows all the probe paths, including the transition moves between the probed features (shown in grey). No collision is shown in the Sequence Tree, but when you simulate the sequence, a collision is detected a warning is displayed.




This is where Intermediate Paths can be used to avoid these collisions.


- 4 Select the **Miscellaneous** toolbar and choose **Intermediate Paths**.





- 5 Enter a **Safe Plane** distance of **15**.



- 6 Double click on the CAD model to create two points, one on the top surface and one on the side surface as shown:



- 7 Click  to save your changes to the Intermediate Path.
- 8 In the Sequence Tree, drag the Intermediate Path item between planes 1 and 2.



- 9 Simulate the probe sequence and it will now run with no collisions.

7. CNC Geometric Inspection

PowerInspect CNC enables you to measure 2D and 3D geometric items either by manually defining the features, from the **Item** toolbar, or by using the Wireframe Checker and selecting features from the CAD model. Supported items are:

- 2D – Lines, Planes, Circles, Ellipses, Slots and Rectangles.
- 3D - Cylinders, Cones and Spheres.




2D items require a reference plane to calculate the projected points.

Wireframe Checker



The **Wireframe Checker** button enables you to pick features directly from a model in the CAD view. Details of the selected feature are automatically displayed in the **Feature Inspect** and **Geometry Explorer** tabs.


The type of feature identified by the Wireframe Checker depends on its selection mode. To change the selection mode, select the **Wireframe Checker** button; right-click in an empty space in the graphics window in the CAD View; and select an option from the menu:



When you select an item with a probe path from the CAD model, the **Feature Inspect** dialog opens.

Feature Inspect Dialog

When you create or edit a feature with a probe path, an Inspect dialog is displayed in the **Features** tab. This dialog contains information about the feature itself, such as the nominal values, and method used to create the probe path.





Different dialogs are displayed for different types of feature, such as **Plane Inspect**, **Arc Inspect**, and **Cone Inspect**; all the dialogs contain the following information:


Name and mode area



This specifies the name of the feature. Select:


- The **Create New Feature**  button to create a feature of the same type.
- The **Edit Geometric item**  button to edit the selected feature.

Feature parameters area




The parameters displayed in this area depend on the feature being created or edited. They can include X, Y, Z coordinates, start and end angles, and whether the feature is to be probed internally or externally.

Probing area



Use this area to select the probing method that specifies how the probe path is created. Settings related to the probe path can also be specified or changed.

Toolbar area





Use the buttons in the toolbar to save or cancel changes and, where applicable, to simulate a probe path and add or remove points from it.

Using the Features tab

The first time you add a new type of feature to the inspection sequence, PowerInspect CNC selects a probing method and uses it to create the probe path. If you change the probing method, PowerInspect CNC remembers the changes and applies these parameters to the next similar feature.


PowerInspect CNC supports several types of probing method. With the exception of a plane, which typically needs to be user defined, geometric items use **AutoTouchTrigger** methods by default.

To view and change the properties of a probing method, click the **Parameters**  button. The **Parameters** dialog is displayed.



Geometry Explorer

The **Geometry Explore** tab lies next to the **Features** tab. When you select an item from the CAD model, the nominal data for the item is displayed in the **Geometry Explorer**.






Using the Item Toolbar

When you create geometric items using the **Item** toolbar, instead of the Wireframe Checker, the **Geometry Explorer** tab enables you to specify the item you want to measure.



Feature Inspection Example

- 1 In the **Main** toolbar, click  to create a new document using the wizard.
- 2 Select **Measurement with a single CAD part**, and click **Next**.
- 3 In the second dialog of the wizard, click **New**.
- 4 In the **Open** dialog, select Demoblock2008.ddz and click **Open**.
- 5 In the **Machine** tab, select, or define, a **3 mm** probe.
- 6 Select the probe in the Sequence Tree's Default Probe and Parameters item.
- 7 Select the **Wireframe Checker**  button.
- 8 Right-click in the CAD and select **Surface** from the menu.
- 9 In the **Select View** toolbar, select **ISO1** and pick the surface shown.




Plane 1 is displayed in the sequence tree.


- 10 Select the **Features** tab. The toolbar's point counter shows that a minimum of three points are required to measure the plane. It is displayed with a red background to indicate you have not yet specified enough points to create the item.



- 11 In the CAD View, the cursor changes to a target. Double-click the surface to create three probe points as shown:




The counter increments each time you create a point. When you have specified at least three points, the counter background counter changes to green.


- 12 Click  to create the Probed Plane item.


- 13 Select **Plane 1** in the Sequence Tree, and, select the **Edit Geometric item** button in the **Features** tab.



- 14 Double-click the plane surface to add an extra probe point.
- 15 Position the mouse cursor over a probe point. When the cursor changes to a hand, left-click and hold the button to drag the point. Reposition the probe points the points as show:




- 16 Click  to save your changes.

- 17 Click the **Simulate Strategy**  button to simulate the probe movements in the CAD View.




*You can adjust the simulation speed using the **Simulation Parameters** area of the **Machine** tab.*


- 18 Ensure the **Wireframe Checker** button is still selected, then right-click in the CAD View and select **Wireframe** from the menu.
- 19 Select the circle shown below.





The **Arc Inspect** dialog is displayed in the **Features** tab.


- 20 Click the **Parameters**  button to open the **Parameters** dialog.

- 21 Change the number of **Points** to 4. Click  to save your changes.









The circle now requires 4 points to be probed.

- 22 Click  to save your changes, and click  to simulate the probe path.
- 23 Ensure the **Wireframe Checker** button is still selected, button and select the top edge of the next hole as shown.



The probe path settings are remembered from the previous feature.

- 24 Click  to create the item, and click  to simulate the probe path.
- 25 Right-click in the CAD view, and select **Surface** in the menu.
- 26 Select the cone. The **Cone Inspect** dialog is displayed in the **Features** tab.
- 27 In the **Features** tab, click  to open the **Parameters** dialog.
- 28 Change the number of **Slices** to **2**. This reduces the number of points required from twelve to eight.
- 29 To avoid the holes in the cone surface, change the vertical distance between the points to **20 mm** and click .



Another method of avoiding the holes in the surface is to create the probe path using an **AutoTouchTrigger** method, and then switch to the **UserDefined** method. This enables you to drag the points to a better location on the cone surface.


Feature Inspection Example 2

- 1 In the same document, hide or delete the previously created features.


- 2 In the **Item** toolbar, click  to create a Geometric group.

- 3 In the **Features** toolbar, select  to create a Probed Circle item.

- 4 Select the circle shown:



- 5 Select the **Geometry Explorer** tab.



The nominals are listed for the selected feature and any features linked to it.


- 6 Select the Arc and select  to create the item.




You could have done this for just the plane and only created it.


Probe orientation

Some model requires suitable alignment of the probe to the orientation of the feature being measured. You can do this manually by setting the probe angle in the **Machine** tab or automatically by selecting the **Auto-orientation** option in the Inspect dialog.


- 1 Select the **Wireframe Checker**  button, and select **Wireframe** in the menu.
- 2 Select the slot edge as shown.



A warning is displayed in the **Features** tab:





This warning is displayed if the approach or the retract distance is too great for the measured feature. This can be fixed outside the feature by creating a new Probe and Parameters item, or by editing the active/default Probe and Parameters item.

- 3 Click  to create the Slot item.




A new plane, Plane 2, is also created because the slot needs a reference plane to identify its orientation.


- 4 Open the **Miscellaneous**  toolbar and click the **Probe and Parameters**  button.
- 5 Name the item **Slot Parameters** and set the **Approach** and **Retract** distances to **2** mm.


| Distances | | | |
|-------------------------------------|-------------------|-----------|-------|
| Speeds | | | |
| Accelerations | | | |
| | Name | Value | Units |
| <input checked="" type="checkbox"/> | Approach | 2.000 | mm |
| <input type="checkbox"/> | Search | 5.000 | mm |
| <input checked="" type="checkbox"/> | Retract | 2.000 | mm |
| <input type="checkbox"/> | GoTo blend radius | 2.000 | mm |
| <input type="checkbox"/> | Scan blend radius | Undefined | |
| <input type="checkbox"/> | Scan retract | Undefined | |

- 6 Click **OK** to save your changes and close the dialog. The Slot Parameters item is added to the Sequence Tree.
- 7 Drag Slot parameters above Slot 3 in the Sequence Tree.






The brown icon on the slot and its reference plane indicate they have probe path collisions.

- 8 Select Slot 3 in the Sequence Tree and then select the **Edit Geometric item**  button in the **Features** tab.





The warning referring to approach and retract distances has been addressed but, because the probe remains in the vertical orientation required for the previous feature, a probe path to measure the slot in the side face cannot be created.


- 9 To orient the probe for the slot's reference plane:
 - a Select the plane in the Sequence Tree.
 - b Click in the **Features** tab to edit the feature.
 - c Select the **Orientation**  button to automatically orientate the probe for the plane.
 - d Click  to save your changes.
- 10 Repeat step 9 for the Slot item.



By setting the probe to Auto Orientate, a probe path is successfully calculated. Auto Orientate orientates the part or probe based on the surface normal of the first point in an inspection group, or the overall normal of a geometric item.

- 11 Select the Plane item and the **Edit Geometric item**  button.
- 12 Using the left mouse button, move the probe points into a better position as shown




- 13 Click  to save your changes.

Simulating an inspection


PowerInspect CNC allows you to simulate consecutive features from an inspection sequence. This enables you to identify potential probe collisions during connection moves between features. You can simulate the entire sequence, a specified range of features, or individual features.


- 1 At the top of the inspection sequence, select the **Run** tab, then select the **Simulate Program** tab.


The list at the top of the tab displays the inspection items in the Sequence Tree:



The buttons in the **Simulate Program** area are used to control the simulation:



- 2 Click the **Play All**  button to simulate the inspection. A warning message is displayed.



This warning is produced as the connecting move between the last point of the probed cone and the first point of the plane results in a collision between the probe and work piece. You can rectify this by inserting an intermediate path between the cone and plane features.

Intermediate Paths


When PowerInspect CNC creates probe paths to measure items in the inspection sequence, it automatically creates moves to link these paths. By default, link moves do not appear in the CAD View, but you can display them by selecting the **View > Probe Paths > Show All** menu option; they are shown as light grey lines.

Automatic links move the probe between features using the shortest route and cannot be changed. Because this may sometimes cause collisions, you can replace these links using Intermediate Probe Path items to control the movements of the probe.


- 1 Select the **Sequence Tree** tab.
- 2 Open the geometric group, and, in the **Miscellaneous** toolbar, click the


Intermediate Path  button.


- 3 In the **Intermediate Path** dialog, select the **UserDefined – Optimal** probing method, and type **100** in the **Probe Safe** box.






- 4 Create two intermediate points, running away from the cone feature, by double-clicking the left mouse button on the top face positioned as shown.



- 5 Click  to create the Intermediate Path item.
- 6 Move the Intermediate Path item between the Cone and Plane 2.




- 7 Select the **Run** tab.
- 8 Click  to rewind to the start of the sequence, and then click  to restart the simulation.





The probe path simulates without collisions, but leaves the probe in a potentially unsafe position.


- 9 Edit the Intermediate Path item, and create two intermediate points, running from the base of the part to the top face positioned as shown.





- 10 In the Probing method list, select **UserDefined – Surface Normal**.



- 11 Click  to open the **Parameters** dialog.
- 12 Select the **Orientate Every Point** check box.



13 Click  to save your changes.

14 In the **Intermediate Path** dialog, click  to save your changes, and simulate the inspection sequence from the start.



To avoid probe collisions at the start of the simulation, you may need to manually reposition the probe. To move the probe in the CAD View, select



*the **Manipulate probe** button in the **Mouse Context** toolbar, left-click the probe and drag it to a suitable location.*

8. CNC Inspection Groups

PowerInspect CNC allows you to compare the physical part against a CAD model by creating and measuring a surface inspection group. This will highlight the accuracy and error deviation outside the defined tolerance of the part.

The tolerances of inspection groups can be changed globally in the **New Document Wizard**, in the **Measures Parameters** dialog, or in each inspection group.

Surface Inspection


Surface point groups enable you to make free-form inspections of surfaces on a part. Use them when you want to specify the probe path for the inspection.

To create a surface inspection group:


- 1 In the **Inspection Groups** toolbar, click **On-the-fly surface points**.



The **Surface Inspect** dialog is displayed in the **Features** tab with the default Probing method. The cursor changes to a target in the CAD View.




- 2 Double-click the model to create points on the top surface as shown:




- 3 In the **Surface Inspect** dialog, click  to create the inspection group.

A collision icon is displayed in the Sequence Tree. This is due to the move between the upper and lower surface of the part:




- 4 In the **Surface Inspect** dialog, click  to edit the group.

The simplest method of correcting the problem is to change the probing method to **SafePlane**. This forces the probe path to use the safe height specified by the first probe position.



However, when a group contains a large number of points, this can produce a lot of unnecessary movements and so increase the probing cycle time. Instead, we will adjust the part of the path causing the problem.

- 5 In the Probing method list, select **Optimal**.
- 6 Right-click the path where the problem occurs and select **Split here** from the menu.





An intermediate point, indicated by a yellow diamond, is on the path mid-way between the probe points.



You may need to unshade the part to see this point.

- 7 Position the cursor over the point. When the cursor changes to a hand, left-click and drag the point to a safe position where there is no longer a collision. To restrict the movement of the point to one major axis, press the **X**, **Y** or **Z** keys while dragging it.




8 In the **Surface Inspect** dialog, click  to save your changes.

To insert additional probe points into the group:

1 Select the group in the Sequence Tree.


2 In the **Surface Inspect** dialog, click  to edit the group.


- 3 Right-click on the probe path between the points shown below, and select **Insert** from the menu.



The probe path changes to blue.

- 4 Double-click the part to insert a probe point.





- 5 In the **Surface Inspect** dialog, click  to save your changes.

Raster

In addition to specifying your own probe path for a surface inspection, you can use the **Raster** probing method to generate a set of regularly spaced probe points across all or part of a surface.

To create a raster probing pattern for a surface:


- 1 In the **Mouse Context** toolbar, select the **Surface Selector**  button.
- 2 Left-click the surface shown to select it:





- 3 Right-click and select **Group Surfaces** from the menu. The **Level Manager** dialog is displayed.



- 4 In the **Level Manager** dialog, type a **Name** for the level, such as **Srf1**, and click **OK**. A level is created containing the surface, and a colour is assigned to the level.




- 5 In the **Inspection Groups** toolbar, click  to create an On-the-fly Surface Points group.
- 6 Double-click the inspection group item in the Sequence Tree to open the **Inspection Group: Surface Points** dialog.
- 7 Select the **Page 2** tab, and then select the **Use custom levels** check box.





The **CAD Object Selection** dialog is displayed.


- 8 Select **User Levels**, and ensure only the level you created is selected.



- 9 Click **OK** to close the dialog and save your changes.
- 10 Click **OK** in the **Inspection Group: Surface Points** dialog.
- 11 In the **Surface Inspect** dialog, select **Raster** in the Probing method list:



- 12 Click  to save your changes. A raster probe path is displayed on the model:



To specify the limits of the raster path:

- 1 In the **Surface Inspect** dialog, click  to edit the group.
- 2 Click the **Parameters**  button. The **Raster Parameters** dialog is displayed.

Raster Parameters

Layout

☒ Specify layout by distances

Stepover Pitch

☐ Specify layout by intervals

Rows Points per row

Boundary

☐ From selected CAD levels

☒ Specify limits

| | Min | Max | Length |
|-------|------------------------------------|--------------------------------------|--------------------------------------|
| CAD X | <input type="text" value="0.000"/> | <input type="text" value="125.000"/> | <input type="text" value="125.000"/> |
| CAD Y | <input type="text" value="0.000"/> | <input type="text" value="110.000"/> | <input type="text" value="110.000"/> |
| CAD Z | <input type="text" value="0.000"/> | <input type="text" value="0.000"/> | <input type="text" value="0.000"/> |

Margin

☒ Use automatically calculated margin




Margin


Use two-way ordering to join rows ☒

Start corner



Angle



- 3 Select **Specify limits** and click . The **Edit Boundary** dialog is displayed, and a blue selection area is superimposed on the CAD model.
- To move the box, position the cursor over a yellow line, and, when the cursor changes to , left-click and drag.
 - To change the size of the box, position the cursor over a blue line, and, when the cursor changes to , left-click and drag. For example:




The positions and sizes of the boundaries are displayed in the **Edit Boundary** dialog. Any points outside these boundaries are excluded from the probe path.


- 4 Click  to save your changes and close the **Edit Boundary** dialog.
- 5 Click  to close the **Raster Parameters** dialog.

Edge Inspection


Edge points enable you to inspect the boundary of a surface. To measure an edge point you must take a point on the surface near the edge you want to inspect, followed by a point against the edge.

Guided Edge Points groups enable you to automate the inspection of a surface boundary. Use them to specify the probe path for the inspection.


- 1 In the **Inspection Groups** toolbar, click the **Guided Edge Points**  button. The **Edge Inspect** dialog is displayed in the **Features** tab.




- 2 To specify the probe points, double-click on the top surface, close the edge shown in red:



- 3 When you have created the points for the group, choose an entry in the Probing Method list to specify the order in which the points are to be taken. Select:
 - **SurfaceSurfaceProbing** to probe all the surface points before probing the corresponding edge points.




- **SurfaceEdgeProbing** to alternate between probing surface and edge points.





Because the probe path automatically adapts to the position of the surface, you are recommended to check the approach and retract distances for the group and adjust them if necessary.

- 4 Run the inspection to obtain data for the part. PowerInspect displays the inspection point with respect to the tolerances



In this example, the part is in tolerance and close to zero deviation.

Section Inspection

Section groups enable you to measure cross-sections through a part by specifying a plane along which the part must be probed. When you have measured a section group, you can view individual measurements by opening the group in the Sequence Tree, or you can use the **Section Group** tab below the CAD view to see a graphical representation of the section and the position and deviation of each point relative to the surfaces of the model.



- 1 In the Item toolbar, click the **Section Group** button. The **Section Inspect** dialog is displayed in the **Features** tab.
- 2 In the Sequence Tree, double-click the item's name, The **Section** dialog is displayed.

Section

Name: Section Group 1

Visible ☒ Output in report ☒

Page 1 | Page 2 | Report | Point Sources(0)

Coordinate System: <Active Alignment> Update existing points ☐

Cut Plane: Plane: X Coordinate: 100.000 Pick plane: [Pick plane icon] Colour: [Colour button] Transform ...


Point Names: Label: S Counter: 1 Incr.: 1 Update existing points ☐

Option: Minimum Points: 6 Auto-accept enabled ☐


Comment: [Text area]

OK Cancel


- 3 Select **X** in the **Plane** list, and type **100** in the **Coordinate** box to specify the location of the section.
- 4 Click **OK**. A guide line for the section is shown in the CAD View.





- 5 In the **Section Inspect** dialog, select **Raster** in the Probing Method list.






PowerInspect creates probe points at regular intervals along the section plane.




- 6 Click the **Parameters**  button. The **Raster Parameters** dialog is displayed.





- 7 Select the **Specify limits** option and click . The **Edit Boundary** dialog is displayed, and a blue boundary area is displayed around the CAD model. To restrict the limits of the probe path:

- position the cursor over a yellow line, and, when the cursor changes to , left-click and drag.
- position the cursor over a blue line, and, when the cursor changes to , left-click and drag.

A green line identifies points that are within the boundaries and a pink line identifies those that are outside.



- 8 Click  to save your changes and close the **Edit Boundary** dialog.
- 9 Click  to close the **Raster Parameters** dialog.

9. Modifying Elements


Many features created within PowerInspect CNC can be modified in several ways. Modifications can be made to items, probed points and even PowerInspect CNC itself.

This chapter briefly goes through the deletion and reordering of points, and some display modifications.


Accessing Modification

You can edit or modify items in three ways:

- Right-click an item in the Sequence Tree and select **Modify Item** from the menu.



- Select the item and click the **Modify**  button on the Sequence Tree toolbar.




- Press **Alt+Enter** on the keyboard.


When you modify geometric items, the dialog that specifies the item's parameters is opened. This enables you to change the constraints of the item. For example, in a Geometric PLP Alignment where a line is specified using the centres of two circles, the line can be altered to pass through different features.


Most modifications work on a similar principle. The next example shows how to delete unwanted results and how to rectify the point numbers to maintain a continuous set of results.


Modifying an inspection group

In this example, the DemoBlock2008 part was probed and during the inspection an anomalous point was taken. The anomaly was verified by taking a point at the same position and comparing the results. The deviation of the anomaly is greater than that of the surrounding results, so it will be removed from the group.





- 1 Select the inspection group in the Sequence Tree and click  to open it.
- 2 Right click on the anomalous result, in this case **SP11**, and select **Delete** in the menu. The point is removed from the inspection group.



This leaves a gap in the point numbers, so they need to be reordered.

- 3 Click the **Up One Level**  button.

- 4 Select the inspection group in the Sequence Tree, and click the **Modify** button. The **Surface Inspection Group** dialog is displayed.



- 5 To renumber the inspection points, in the **Point names** area:
- a Enter a **Counter** value of **1**.
 - b Enter an **Increment** value of **1**.
 - c Select **Update existing points**.
- 6 Click **OK**. The points names are updated in the Sequence Tree with point **SP11** being renamed to **SP10** and **so on**.

10. Multiple Alignments


PowerInspect enables you to use multiple alignments in a single inspection document. Multiple Alignments can be used in a variety of situations:

- To define a local coordinate system or datum to help in the measurement of features.
- Having a local datum for geometry on each side of the component.
- To use a different alignment for each item in the inspection sequence
- If the original location of the component is changed, it can be realigned without losing the previously measured results.
- When customer requirements require multiple alignments are used.


Multiple Alignment Example

The following inspection outlines how alignments can be used in combination. For this example, the DemoBlock2008 file is used.


- 1 Create a Geometric PLP alignment using the top, flat surface as a plane and the two circles indicated, with line between circle 1:centre and circle 2:centre.





- 2 In the **Inspection Groups** toolbar, click **On-the-fly Surface Points** to create a surface inspection group.
- 3 Double click over on the surface to create probe points for the inspection group.



- 4 Run the inspection on the measuring device.



The example shows the surface used for the alignment, Plane 1, is within tolerance. However, the other top surface is out-of-tolerance towards the other end of the block. We can attempt to improve the alignment by creating a Best Fit item that includes the results of the inspection group.

- 1 Select the **Alignments**  toolbar, and click the **Best Fit**  button. The **Edit BestFit Definition** dialog is displayed.

Edit BestFit definition

Name:

Output in report: ☐

Alignment:

Optimized Alignment: Geometric PLP Alignment 1

Fitting type:

Tolerances used

☐ Individual points
☒ Inspection groups
☐ Specify tolerances

Low Tol: High Tol:

Max. Iterations:


Threshold:


Method:

Points

| Available items | | Selected items | Weights |
|--------------------|-----|----------------|---------|
| Inspection Group 1 | > | | |
| | < | | |
| | >>> | | |
| | <<< | | |


OK Apply Cancel

- 2 Select **Inspection Group 1** and click . The inspection group is moved to the **Selected items** table.
- 3 Click **OK** to save your changes and close the dialog.
- 4 In the Sequence Tree, right-click the BestFit item, and select **Play Item** from the menu. The **Best Fit Analyser** dialog is displayed.



The graph shows the spread of results for Inspection Group 1

- 5 To perform the best fit, click the **Go Step** button. PowerInspect analyses the deviations of the inspection points and, using the **Method** allowed by the definition, adjusts the alignment to improve the fit of the points in the inspection group. The graph is updated to show the spread of point measurements after the Best Fit item has adjusted the alignment.



By using the Best Fit, PowerInspect determines the surface profile is correct, and when the calculated translations and rotations are applied, all the measured points are within tolerance.

From this we can conclude the machining program is correct for the form of the component, but we will need to investigate why the component has deformed from the centre to the lower outer edge, about its X axis.

