

The expert high-speed and multi-axis solution

Training Course









PowerMill 2017 Contents

	<u>Chapters</u>	Page Number
Day 1	1. Getting Started	1.1 - 1.26
	Machining Set Up in Detail	2.1 - 2.22
	3. Area Clearance Strategies	3.1 - 3.54
Day 2	4. Finish Machining Strategies	4.1 - 4.54
	5. Leads and Links	5.1 - 5.14
	6. Boundaries	6.1 - 6.32
	7. Levels and Sets	7.1 - 7.12
Day 3	8. Editing Toolpaths	8.1 - 8.22
	9. Tool Collision Checking	9.1 - 9.14
	10. Patterns	10.1 - 10.18
	11. Curve Editor	11.1 - 11.12
Day 4	12. 2D Machining	12.1 - 12.48
	13. NC Programs	13.1 - 13.10
	14. Setup Sheets	14.1 - 14.8
	15. Specialist Finishing	15.1 - 15.32
Day 5	16. Component Thickness	16.1 - 16.22
	17. Stock Models	17.1 - 17.18
	18. Macros & User Menus	18.1 - 18.10
	19. Tutorials	19.1 - 19.36





1. Getting Started

This course covers the 3-Axis functionality available in **PowerMill**. Additional **Five Axis** license options are covered on a separate course.

PowerMill can quickly create gouge-free cutter paths on imported component data. It supports Wireframe, Triangle, Surface, and Solid models. Translators can be purchased for **PowerMill** to directly import data created by other proprietary CAD packages.

Start PowerMill




1 Double-click the **PowerMill** shortcut on the desktop: PowerMill



On the training PC, the icon will be displayed as PowerMill.

The PowerMill screen is displayed:



The screen is divided into the following main areas:

a Main pulldown menus (Located top left above the graphics area).

File View Insert Draw Tools Help




Click one of the menu names on this bar (for example, **File**) to open a pull-down menu list of associated commands and sub-menus. A sub-menu is indicated by a small arrow to the right of the text (for example **File - Recent Projects >**). Highlighting this arrow generates a list of commands/names specific to that sub-menu (for example, **File - Recent Projects** displays a list of recently opened projects that open directly when selected).

b Main Toolbar (shown un-docked)



This provides quick access to the most commonly used commands in **PowerMill**.

c PowerMill Explorer (Left of the Graphics area).



The **PowerMill** *explorer* provides access and storage of **PowerMill** entities created during the session.

d Graphics area


This is the large, visual display area to the right of the **Explorer** (Look at the illustration on previous page).

In the top right corner of the Graphics area is the ViewCube.



This is used to quickly select a range of standard viewing orientations.

For an ISO1 view click the lower left corner of the ViewCube (arrowed).





To return to the default **Top** view select the **Home** symbol to the top left of the ViewCube (arrowed).



Another method would have been to select the central Top area (arrowed).



To enable 90 incremental rotation on the planer views select one of the circular arrows (arrowed).



e View Toolbar (shown as horizontal)



Provides quick access to standard view and shading options in PowerMill.

f Information Toolbar



This area provides a reminder of some of the active setup options.

g Tool Toolbar




Facilitates the rapid creation of tools in PowerMill.

Most available toolbars are not factory defaults, and are therefore not shown at initial start-up. To display any of these, select them under **View > Toolbar**.

For example, select **View > Toolbar > Toolpath** to display the **Toolpath Toolbar**.





The **Toolpath** toolbar appears (as shown below).




The **Toolpath** toolbar provides access to a comprehensive selection of essential **Toolpath** *editing* and *visualisation* options.




Changing the Background Colour.

To change the background colour of the graphics area, select **Tools > Customise Colours** and from the dialog select **View Background**.



The Top and/or Bottom colours can be changed independently and reset using **Restore Defaults** to restore to the original settings:



PowerMill remembers **Toolbar** and *colour selections* from one session to the next. For example, if a **Toolbar** is open when the session is closed, it will appear the next time **PowerMill** is opened.



Mouse buttons

Each of the three mouse buttons performs a different dynamic operation in **PowerMill**.

Mouse button 1: Pick and Select



This button is used for selecting items on menus, options on dialogs, and entities in the graphics area.

The method of selection is controlled by 2 options accessed from the **Viewing** toolbar, the default being Select using a **Box**.



Select using a box



If the cursor is positioned on an entity, such as part of a surface model, and if the mouse is clicked, then the item turns yellow indicating that it is selected.



If you select another surface, all currently selected items are de-selected.

- If you want to select more surfaces to add to the currently selected surface, then, while making selections, hold down the Shift key on your keyboard.
- If you want to remove a surface from your current selections, hold down the **Ctrl** key on your keyboard and click on the surface that you want to remove.

Select by dragging the cursor




Use this option to select multiple entities by dragging the cursor across the required items. This is ideal for quickly selecting multiple surfaces on a model. To deselect entities, press the **Ctrl** key when dragging across an entity.



Mouse button 2 (Middle): Dynamics



- Zooming in and out: Hold down the Ctrl key and mouse button 2. Move the mouse up and down to zoom in and out.
- Pan around the model: Hold down the **Shift** key with mouse button 2. Move the mouse in the required direction.
- Zoom Box: Hold down the Ctrl and Shift key, drag a box around the area to zoom into using the middle mouse button.
- Rotate mode: Hold down mouse button 2 and move the mouse, and the rotation is centred about the tracker ball.
- View Spinning: Dynamically rotate the view and quickly release the mouse. The faster the mouse movement, the faster it will spin. This feature is switched off by default. Select Tools > Options > View > 3D Graphics and select the Spin View option to enable it.



Mouse button 3 : Special Menus & PowerMill Explorer Options




When this button is pressed it brings up a local menu relating to whatever the mouse is over, such as a named item in the **PowerMill explorer** or a physical entity in the graphics area. If nothing specific is selected, the View menu appears.




HELP!

PowerMill provides you with help in a number of ways:

- Tooltips: Place the mouse cursor over a menu button. A description is of what the button does is displayed.
- Online Help: Select Help > Contents from the Main toolbar to access the online help documents. There is a full index and search facility provided.
- To see a summary of all new functionality available in the current version of PowerMill, select Help > What's New.



- Context Sensitive Help: Press the F1 key to display the help page for the currently active dialog. Click the button in the top right hand corner of a dialog, followed by a left click in any of the input fields to focus on the help topic for that part of the dialog.
- PowerMill User Forum: On the Main toolbar, select Help > Autodesk on the Web > PowerMill home page and then select Support/Services – Forums to participate in web-based user discussions on PowerMill issues.



 Telephone and Email Support: UK customers with up-to-date software maintenance can call 01216831010 or mail <u>uksupport@autodesk.com</u> to get help or advice on specific application problems.



Simplified PowerMill Example

This example provides a quick overview of the machining process. It shows how to create and output a couple of simple toolpaths on a model of a valve chamber using default settings wherever possible.


The basic procedure is:

- a Start up PowerMill.
- b Import a Model.
- c Define the **Block** that defines the material size (or 3D machining limits).
- d Define the cutting **Tools** to be used.
- e Define set up options (Rapid Move Heights Start and End Point).
- f Create a Roughing Strategy.
- g Create a **Finishing** Strategy.
- h Simulate the toolpaths.
- i Create an **NC Program** and output as a post-processed NC data file.
- j Save the PowerMill Project to an external directory.

Import a Model

2 From the Main menu select File > Import Model and browse for the model file:

.....\PowerMill_Data\Models\PmillGettingStarted.dgk




3 Select an ISO 1 view.



Blanking model entities


Use the **Blank Selected (Ctrl + J)** option available on the **Model** context menu to temporarily hide the selected model components.

In the illustrations below, the *light blue* surfaces are selected.




Use the **Blank Except (Ctrl K)** option available on the **Model** context menu to temporarily hide all model components except the selected ones.

The 2 selected items are light blue.



To re-display all model components, right-click in the graphics area and select **Unblank (Ctrl L)**. The blanked model components are displayed and selected (back to the left hand image above).

You can also toggle between the blanked and unblanked status of model components. Select the **Blank Toggle** (**Ctrl Y**) option to switch between the **Blanked** and **Unblanked** components of the model.





Defining a Block

The **Block** dialog is used to define the 3D working limits. This could be the actual raw material size or a user-defined volume, localised to a particular part of the component.


The settings on the **Block** dialog are set by default to **Defined by – Box**. Individual values in the dialog can be edited or locked (greyed out) as required. Enter a value in the **Expansion** field to include an offset in the block calculation.

Click the Calculate button to define a block around the model dimensions.


1 Click the Block



button on the **Main** toolbar to display the **Block** dialog.



- 2 Click the Calculate button.
- 3 Click Accept.





Defining a Cutting Tool

The **Tool** dialogs are accessed using the various tool buttons on the **Tool** toolbar. This is located to the bottom left corner of the graphics area.

For this example, 2 tools will be created, A **Tip Radiused** tool for roughing out and a **Ball Nosed** tool for finishing.

1 Click the down arrow to display all the **Tool** options




2 Place the cursor over a tool to view the description of the tool type (Tool tips).




3 Select the Create a **Tip Radiused** tool button

The **Tip Radiused Tool** dialog is displayed.





- 4 In the *Tip Radiused* Tool dialog, enter:
 - a Name D12TR1 It is recommended that the tool is renamed with a more relevant identification.
 - b Diameter 12 When you enter a value for the Diameter, the tool Length automatically defaults to five times this value. You can edit this value if needed.
 - c Tip Radius 1
 - **d** Tool Number 1, A Tool Number can be output to the NC Program. If the machine has a tool changer, this number will represent the location in the carousel.
 - e Click Close on the Tip Radiused Tool dialog.
- 5 Define another tool, this time, select the **Create a Ball Nosed tool** button and in the **Ball Nosed Tool** dialog, enter:
 - a Name BN12
 - b Diameter 12
 - c Tool Number 2
 - d Click Close on the Ball Nosed Tool dialog.
- In the **PowerMill** *explorer* panel on the left of the screen, open **Tools** and right mouse click **D12TR1** tool to raise the local menu and select **Activate**.





Only one tool can be active at any one time and the word Activate in the

tool context menu is prefixed with a tick————. The active tool is automatically included in a strategy dialog when the strategy is created.

In the **PowerMill explorer**, the **Active** tool is displayed in **bold text** and prefixed with '>'.


Rapid Move Heights

The **Rapid move heights** options provide safe control rapid tool movements across the component.

- Rapid height is the height above the job at which the tool can move at a rapid feedrate, clear of any obstructions such as the work piece or clamps.
- **Plunge height** is the height to which the tool will descend, at rapid feed rate prior to applying the plunge feed rate.


PowerMill displays rapid moves as dotted red lines, plunge moves as pale blue, and cutting moves as green.





Setting up Rapid Move Heights

1 On the Main toolbar, click the Rapid move heights button to open the Toolpath connections dialog.



- 2 Click Calculate.
- 3 Click Accept.

This sets the absolute **Rapid height** and **Plunge height** values to be above the **Model** or **Block** by the incremental distances, displayed in the **Calculate dimensions** area of the dialog.




Toolpath - Start and end point

The **Start and end point** dialog allows you to define a position where the tool travels to before and after a machining strategy.

1 Click the tool **Start and end point** button on the **Main** toolbar to display the **Toolpath connections** dialog.


By default, the tool **Start point** is set to **Block centre safe** and the **End point** is set to **Last point safe**.



Other **Start and end point** settings are configured by selecting the different options in the **Method** area on the dialog.

These include Block centre safe, First/Last point safe, First/Last point, and Absolute.

2 For now, click Accept to use with the default settings.



The **D12TR1** tool is placed at the **Block centre safe** position ready for you to create the first toolpath.




Creating a Roughing Strategy


1 From the **Main** toolbar select the **Toolpath Strategies** button.



2 From the left hand list select 3D Area Clearance




3 From the right hand list select the Model Area Clearance strategy. This displays the Model Area Clearance strategy dialog.





- 4 In the Model Area Clearance strategy dialog:
 - a In the **Toolpath** name field, enter **D12TR1-RGH1**.
 - **b** Select **Style Raster** with **Profile Climb** and **Area Any**.
 - c Edit the **Thickness** value to be **0.5** (This is the amount of material that will be left on the job).
 - **d** Edit the **Stepover** value to be **8** (This is the distance between each raster pass (the width of cut)).
 - e The **Stepdown** value (depth of cut) is left at the default value of **5**.
 - f Click Calculate to process the machining strategy and then Close the dialogue.




Creating a Finishing Strategy

- 5 In the **PowerMill** *explorer*, right click the **BN12** tool and select **Activate** (or double left click on the tool's, **PowerMill** *explorer*, icon).
- **6** From the **Main** toolbar select the **Toolpath Strategies** button.




7 From the left hand list select Finishing.






8 From the right hand list select the Raster Finishing strategy and click OK.



- In the Raster Finishing strategy dialog:
 - a For the Toolpath Name, enter BN12-FIN1.
 - b Edit the **Stepover** value to **0.3**
 - **c** Click **Calculate** to process the machining strategy.



The **Raster Finishing** pattern is projected down Z onto the component, taking into account tool geometry and machining settings.

10 Close the dialogue.



The toolpath link moves, clear of the job, are not displayed in this illustration for clarity.



Toolpath Simulation and ViewMILL

PowerMill provides two levels of options for simulating toolpaths:

- The first level Simulates the cutting tool movement along the toolpath.
- The second level (ViewMILL) includes a shaded image of the stock material being progressively reduced as the tool moves along the toolpath.

Toolpath Simulation

11 In the **PowerMill** *explorer*, right-click on the toolpath **D12TR1-RGH1** and from the local menu select **Activate**.



The **Active** toolpath is displayed in bold text and prefixed with a > symbol.


12 From the **PowerMill** *explorer* right mouse click on the **Toolpath**D12TR1-RGH1 and from the local menu select, **Simulate from Start**.



The **Toolpath Simulation** toolbar is displayed at the top of the screen. This displays the name of the toolpath and tool, together with buttons to control the simulation.



The options below allow further control of the **Step** simulation.




- 13 From the Simulation toolbar click the Play button to run the Simulation.
- 14 Activate the finishing toolpath BN12-FIN1 and repeat the simulation process.



ViewMILL

- 1 Activate the roughing toolpath D12TR1-RGH1 and from the local menu select Simulate form Start.
- 2 From the Main pull down menus, select View > Toolbar > ViewMILL to raise the ViewMILL Toolbar.




The ViewMILL toolbar is displayed. Initially, all the buttons are greyed out.



3 Click the button to toggle the graphics window into the **ViewMILL** mode (The **ViewMILL** toolbar buttons are now active).




4 Click the button to select a Plain Shaded I mage.






- 5 Click the **Tool** button to display the tool.
- 6 Click the **Play** button to start the **ViewMILL** simulation.



- 7 After the *simulation* has finished, select the toolpath **BN12-FIN1** on the **Simulation** toolbar, followed by the **tool** button.
- 8 Click the **Play** button again to view the continued simulation of material removal by the finishing toolpath.




9 In the **Simulation** toolbar, select the **Close** button to delete the **ViewMILL** session.




NC Programs (Post-Processing and NC data Output)


1 From the Main menu, select Tools > Customise Paths to open the PowerMill Paths dialog.



This displays the **PowerMill Paths** dialog.




In the PowerMill Paths dialog, select the option NC Programs Output.




This controls where the post-processed, NC data files are output ready to download to a machine tool controller.

- 3 Click the *Add path* to top of list button.
- 4 In the **Select Path** dialog which appears, browse to the required location **C:\Temp\NCPrograms** and click **OK**.
- In the **PowerMill** *explorer*, right-click **NC Programs** and select **Preferences** to display the **NC Preferences** dialog.






NC Preferences enables you to control the content of output files to download to a machine tool.




The **Output Folder** defaults to the location already defined in **Tools** > **Customise Paths**.

In the NC Preferences dialog, click Machine Option File button. This displays the Select Machine Option Filename dialog.





- 7 Select Heidenhain_3axis_ref.opt and click Open. This selects the option file and returns you back to the NC Preferences dialog.
- 8 Close the NC Preferences dialog.
- In the PowerMill explorer, right-click NC Programs and select Create NC Program.




An empty **NC Program** appears in the **PowerMill** *explorer* and the **NC Program** dialog is displayed.

10 Within the **PowerMill** *explorer*, use the left mouse to select and drag the toolpath **D12TR1- ModelAreaClear** onto the **NC Program 1**.



Alternatively, right-click on the toolpath **D12TR1-RGH1** and select **Add** to > **NC Program**.



A copy of the *toolpath name* will appear in the **NC Program** indicating that it has been assigned as part of the output file.

11 In the **PowerMill** *explorer*, click and drag the toolpath **BN12-RasterFinish** onto **NC Program** 1.


Click the small + box to expand and view the contents of the **NC Program**.





The toolpath names are listed in the NC Program ready to be post-processed.

12 In the **NC Program** dialog displayed in the graphics area, click the **Write** button to start the post processing operation. An Information dialog is displayed with a progress and confirmation summary.



- 13 Close both the NC Program and Information dialogs.
- 14 You can find the created NC data file 1.tap under C:\temp\NCPrograms on your computer.

Saving the Project


15 On the Main toolbar, click the Save button.





As this is the first time that this **Project** is saved, the **Save Project As** dialog will open.





If the **Project** has been **Saved** before, then it will simply be updated.

16 From the Main menu , select File > Save Project As:-

.....\COURSEWORK\PowerMill-Projects\PmillGettingStarted

17 From the *pulldown* menus, select File > Delete All, followed by Tools > Reset Forms.


The content of **PowerMill** *explorer* is deleted and all dialogs are reset to their default settings.

The externally stored copy of the **Project** (*PmillGettingStarted*) can be reopened as required.

Additional Exercise

1 Import the Model: -

.....\PowerMill Data\Models\facia.dgk



2 Save the Project as:

.....\COURSEWORK\PowerMill Projects\Facia-1

- 3 Use the same Tools and machining strategies to those in the previous Project (PmillGettingStarted).
- 4 Once this exercise is completed (and saved as a **Project**) locate the *pulldown* menus, and select **File** > **Delete All** followed by **Tools** > **Reset Forms**.



2. Machining Setup

In the previous section, the toolpaths were created using the default values wherever possible.


We will now look at the machining Setup options in more detail.

In particular:

- Setting up direct access to regularly used files using Customise Paths.
- Setting Feed rates.
- **Workplanes** (Positional datums) to create appropriate machining set ups.
- Tool with Shank and Holder definition.

PowerMill Panes

The **PowerMill** panes are located above the **PowerMill** explorer area.




- The first pane displays the **PowerMill explorer** (as shown above).
- The second pane ____ displays the HTML browser used for viewing Help files.
- The third pane opens the **PowerMill Recycle Bin**. Entities deleted from the **PowerMill explorer** can be recovered from the **Recycle Bin**.




Setting up direct access to regularly used folders

1 From the Main menu select Tools > Customise Paths. The PowerMill Paths dialog is displayed.



- 2 Select the File Dialog Button 1 option from the drop-down list.
- 3 Click the **Add path to top of list** button and browse to:

.....\PowerMill Data\Models



- 4 Click OK.
- 5 Repeat steps 2 and 3, but this time select the **File Dialog Button 2** option to link directly to:
 -\PowerMill_Data




Outside the training environment, the location of the **PowerMill_Data** directory will depend on where you have installed it!




Loading a model into PowerMill

1 To import a **Model** via the **Main** pull down menus, select **File** > **Import Model**.



The **Import Model** dialog is displayed.



- changes the directory to the current **Project** directory.
- changes the directory to the Examples directory.


This folder contains a selection of sample model files which are installed within the **PowerMill** installation in a directory called **Examples**.

- changes the directory to the first *user-defined* directory.
- changes the directory to the second **user-defined** directory.
- 1 From the Main menu, select File > Import Model.




2 Use **Shortcut Button 1** or browse to:

....\PowerMill_Data\Models





A variety of **Model** formats can be imported into **PowerMill**. Use the **Files of type** filter to widen or narrow your choice.





Please note: direct transfer - file formats (eg: CATIA, ProENGINEER, etc) are only available as a cost option.

- 3 Back in the main **Import Model** dialogue, select the file **WorkplanesExample1.dgk** and then click **Open**.
- 4 From the Viewing toolbar (Right of graphics area) select Resize to fit



The **model** is re-scaled to fit within the **PowerMill** graphic area.



Viewing the Model

Although the **model** is displayed, it is a good idea to look at it from all angles to fully understand its size and features.




Above is the **Views** toolbar (shown aligned horizontally).

By default, the **Viewing** toolbar is aligned to the right hand side of the graphics area. These options mainly include basic visual orientations along with several shading modes, many of which provide specialist analysis of the model.

5 From the **View** toolbar, select an isometric **ISO 1**



- 6 Right mouse click on the **Model** and from the local menu select **Transluceny**.
 - P Enter translucency (percentage) ×
- 7 Enter **50** into the data input box and select the **green tick** to accept.



In most cases, the X dimension of a machine tool table will be greater than Y; in which case, the longer side of the component may exceed of the travel limits in Y.

If this is the case, the component will have to be aligned with the longest side along X to ensure that it can be positioned within the travel limits.

Saving the Project

It is good practice to create a **Project** as soon as possible and then to **Save** it at regular intervals during the session.

8 On the Main menu, select File > Save Project As:


....\COURSEWORK\PowerMill-Projects\WorkplaneExample1-EX1



Setting Feed rates

The current **Feed rate** values are applied directly to a new **toolpath**. The **Feed rate** values can be stored in a **Tool** definition to update the **Feed rate** dialog accordingly on **Tool** activation. At this stage we will look at manually setting the

feed rate individually. Click the **Feeds and Speeds** button on the **main** toolbar to display the **Feeds and Speeds** dialog.



The default values (as shown above) can be modified as required and **Accept** selected for them to be the default for future toolpaths. **Apply** is used to update the **Feeds and Speeds** of an **active toolpath**. Note **Apply** is 'greyed out' if there is currently no **active toolpath**.

Creation and Application of Workplanes.

When a **model** is imported into **PowerMill** it is more than likely that the original global datum (**Transform**) will not provide a suitable position/orientation for tool setting or applying machining strategies.

Workplanes provide the ideal method of creating suitable machining datums and alignments without having to physically move the component **model**.


Workplanes are additional datums that can be moved and/or orientated within the global environment. Only one **workplane** can be active at any one time. If no **workplane** is active, then the original global **Transform** is the datum.

By deactivating a **workplane**, the original coordinate set-up can easily be reactivated for tasks such as checking original dimensions or for importing a 'new issue' updated model.



Workplane (1) - At Top of Selection

- 9 With the left mouse button depressed, drag a box over the entire model to select it.
- 10 In PowerMill explorer, right-click Workplanes and select Create and Orientate Workplane > Workplane at top of Selection.



A **Workplane** is created and appears at the top-centre of the selected model. The new **Workplane 1** also appears as an entity in the **PowerMill** *explorer*.

11 Right-click the newly renamed Workplane 1 and from the local menu select Activate.




The next step will be to rotate the new **Active** - **Workplane** - **1** to re-orientate the model such that the longer side is aligned to the **X-Axis**.

12 From the same local menu, select **Workplane Editor** to display the **Workplane** editing toolbar.




- 13 Double click the **Twist about Z** button. This displays the **Twist** dialog.
- 14 Enter Angle 270 and click Accept.




15 Click the **Green Tick** located to the right of the **Workplane** toolbar to accept the changes.





16 Select a **View from top (Z)** to see the effect of the rotated, **Active Workplane** providing a more suitable machining position for the model.




The **Workplane** is shown positioned on the top of the model, which has the longer edge aligned to X.

Workplane (2) - Positioned using the Block


Another method of creating a **Workplane** is from *key points* on the defined **Block**.

17 From the main menu, select the Block Icon the following form will appear select Active Workplane press Calculate followed by Accept.






18 In the **PowerMill explorer**, Right mouse click on **Workplanes** to access the following menus.




- 19 Select Workplane Positioned Using Block from the above menu.
- 20 Click the new **Workplane** on to the orange *sphere* located at the *centre* of the *bottom face* of the **Block**.






The new workplane will inherit the default name 2.

21 Right click on workplane 2 and from the local menu, select Activate.










Note that **Block** definition moves relative to the **active datum**.

22 Activate the new **Workplane** and from the local menu select the **Workplane Editor**.




- 23 Select **X Twist**, and in the dialog enter **180** degrees to make the new **workplane** normal to the underside of the model.
- 24 Select **Accept** for the new **workplane 2** to be updated.
- 25 Select an **ISO 1** view.



The **Block** returns to the correct position relative to the **model** which in this case is dimensionally the same for both **Workplanes 1** and **2** when either is **Active**.



26 De-activate Workplane 2.




The **Block** is now dimensionally positioned relative to the global **Transform**.

27 Select File - Save Project:-

The contents of the **Project** saved earlier will be updated.

Block Coordinate System

The above type of **Block** Co-ordinate, definition (**Active Workplane**) is ideal for 3 Axis applications. The physical re-positioning of the **Block** will provide a useful visual warning if the machining datum, Workplane is de-activated.




Other Coordinate System options become essential for advanced applications such as multi-axis, 3Plus2 set ups. In this case the Block definition can be fixed to either the Global Transform or a Named Workplane.



Workplane Aligned to Geometry

This option enables the user to create a **Workplane** perpendicular to a face using **Workplane aligned to Geometry**. The next example shows this in detail. (See original model orientation).

1 Select File - Delete all followed by Tools - Reset forms.




2 Import the Model:-

.....\PowerMill_Data\Models\InteriorTrim.dgk

3 With the centre mouse wheel held down, move the mouse to rotate the view of the **Model** so that the base of the pocket is fully visible.



4 Right click on **Workplanes** and select **Create and Orientate Workplane** followed by **Workplane aligned to Geometry**.







5 Left mouse click on the base of the pocket (as shown below) to locate a new **Workplane** (with its Z-axis normal to the surface).



In the **PowerMill explorer**, right click on the new **workplane** and select Activate.




- 7 Use the left mouse and click on the bottom face of the pocket to make it selected (shaded light blue below right).
- Then right click on **Workplanes** to open the local menus below.




- From Create and Orientate Workplane, select Workplane at Top of Selection.
- 10 The new **Workplane** will be centrally located at the base of the pocket.
- 11 Rename the new Workplane as Datum and make it Active.
- 12 Delete the original Workplane.





The new **Workplane** is central to the pocket base as shown below.



- 2 Save the Project as:-
 -\COURSEWORK\PowerMill_Projects\Workplane-Example2
- 3 Select File Delete all followed by Tools Reset forms.

Other local Workplane menu, creation options

- **a Create Workplane** produces a single **Workplane** on the current active datum and opens the **Workplane Editor** context toolbar.
- **b** Create and Orientate Workplane opens the following form, that provides a selection of specialised Workplane creation options.

Workplane at Point...

Multiple Workplanes...

Workplane From Three Points...

Workplane From Three Arc Points...

Workplane Aligned to Geometry...

Workplane Positioned Using Block...

Workplane at Top of Selection


Workplane at Centre of Selection

Workplane at Bottom of Selection



Speaker Core Example - Set Up

1 Import the Model:-



For this example it is required for the long side of the component to be aligned to the \mathbf{X} direction and not \mathbf{Y} as shown above.

- 2 Depress the left mouse key and drag a box across the whole model to select all Surfaces.
- 3 From the **PowerMill** *explorer*, select **Workplanes Create** and **Orientate Workplane Workplane** at **Top** of **Selection**.
- 4 In the **PowerMill** *explorer* right mouse click on the new **Workplane** and from the local menu select **Workplane Editor**.




5 In the above toolbar, click on the **Z-Twist** option and enter **90** in the form for the **Workplane** rotation angle.



- **6 Accept** the **Twist** form and then click on the **Green** tick on the toolbar to exit the **Workplane Editor** (and finally accept the changes).
- 7 Activate the new Workplane 1.



8 Select an ISO 1 view.



The long side of the component is now running along the \boldsymbol{X} direction.


Now that the component model is suitably aligned, the next stage is to create some suitable cutting **Tools** ready to carry out the machining process.

Tool and Holder Definition

For the cutting **Tools** in this example the **Shank** and **Holder** will be included as part of the overall definition.


Note it is also possible to store specific **feeds** and **speed** values in a Tool definition. Not a default setting, but **PowerMill** can be set to recognise these and automatically update the **Feeds and Speed** dialog on activation of the **Tool**.

9 From the PowerMill explorer select Tools - Create Tool - Tip Radiused.




10 In the Tip Radiused Tool dialog, input a Name D50TR6 - Diameter 50 - Tip Radius 6 - Length 160 - Tool Number 1.





11 In the Shank dialog, click Add a shank component Upper/Lower Diameter 50 and Length 100.




- 12 In the **Holder** dialog, click **Add holder component** and input:
- Upper Diameter 120
- Lower Diameter 90
- Length 50
- Overhang 200






The **Overhang** is the vertical distance from the bottom of the **Holder** to the bottom of the tool **Tip**.




- 13 In the Holder dialog, click the Add holder component button_s. Enter:
- Upper Diameter 120
- Lower Diameter 120
- Length 50



- 14 In the Holder dialog, click the Add holder component button Enter:
- Upper Diameter 150
- Lower Diameter 150
- Length 25






15 Close the dialog.




You can control the style in which the tool is displayed in the graphics window. In the **PowerMill explorer**, right-click on the **Tool** - **D50TR6** and from the local menu, select **Shaded**.





A **Tool** can be saved outside **PowerMill** as a permanently stored template (.ptf).





The tool must be the only item in the **PowerMill explorer** as all saveable entities will also be added to the template file.




Block Definition

The default option for **Block** is **Box** (A rectangular volume). Other options include **Cylinder** (a cylindrical volume), a **Triangle** model (eg Casting), and **Picture/Boundary** (Extruded 2D wireframe contours).


The dimensions of the **Block** can be entered manually or calculated directly to the Type of entity: **Model**, **Boundary**, **Pattern**, or **Feature**.

The **Opacity** slider controls the degree of shading (from the left, initially wireframe and then graduating from clear to dense).

16 Calculate a Block using Defined by - Box and Type - Model.



17 Move the **Opacity** slider fully to the left for a wireframe **Block**.






Rapid Move Heights

The Rapid Move Heights icon provides access to the **Toolpath connections** - Safe area dialog. This enables the control of rapid link moves between tool tracks that clear of the top of the **Model** or **Block** (whichever is the higher).

18 In the Toolpath connections dialog, click the Calculate tab to set Rapid Height and Plunge height to the default values of 10 and 5 respectively above the Model or Block.






The Rapid Height is calculated relative to the highest point on the Block or **Model**.



If parts of the **model** are selected, then the de-selected parts will be ignored when the **Rapid Height** is calculated!




By default the **Tool** will traverse across **Safe Z** and then drop to **Start Z** using a Rapid move (eg G0). It will then continue downwards at the Plunging Feed Rate (eg G1).




Start and End Point

The **Start Point** and **End Point** icon provides access to the **Toolpath connections – Start and End** point dialog. This enables control of the *first* and *last points* on a toolpath from a choice of 4 different positional options.



- 19 In the Start and End Point dialog, Accept the default settings :
- a Start Point Block Centre Safe
- **b** End Point Last Point Safe



Save Project

- 20 It is essential to regularly Save your work outside the PowerMill session. By saving to a Project the contents of the PowerMill explorer are saved into an external folder.
- 21 Select File Save Project As:-


....\COURSEWORK\PowerMill-Projects\Spkr-Core

<u>Do Not Close</u> the **Project** as it will be continued in the following chapter.



3. 3D Area Clearance


The main strategies for roughing a 3D component model are called 3D Area Clearance. These provide a choice of 2D material removal methods, which progressively machine the area (Slice), up to the component contour, down a sequence of user-defined Z Heights.



Thickness and Tolerance (Applied to 3D Area Clearance)

Suitable values are required to control the accuracy and amount of excess material to be left on a component by a toolpath. The parameters used for this purpose are preset and are called Thickness and Tolerance.

Thickness is the amount of extra material specified to remain on the work-piece after machining. This can be applied generally (as shown), or independently as separate Radial and Axial values within the machining options.






Raster - Model Area Clearance example

The **Raster** (**Model Area Clearance**) strategy follows a series of linear moves across the **Block** limiting to the component form at the active **Z height**. It then, (by default) performs a Profile pass around the component to leave a constant **thickness** around the **Slice**.

- 1 Ensure that the recently saved **Project** (**Spkr-Core**) is still active.
- 2 Activate both the Workplane and the tool D50TR6.
- 3 From the main toolbar select Block and using, Defined by Box Type Model select Calculate followed by accept.
- 4 From the main toolbar select Rapid Move Heights and in the dialog select Calculate followed by Accept.
- 5 From the main toolbar select Toolpath strategies and from 3D Area Clearance open a Model Area Clearance strategy.



6 Select **OK** to open the **Model Area Clearance** strategy form.






As soon as the **Model Area Clearance** dialog is opened, the unprocessed **Toolpath** appears in the **PowerMill explorer**.



- 7 In the Model Area Clearance dialog:
 - a Enter the Toolpath name as D50TR6-A1
 - **b** Select **Style** as **Raster**.
 - c For Cut direction Area select Any
 - d Set Thickness to 0.5
 - e Set Stepover to 20
 - f Set Stepdown to 10
- 8 In the **Model Area Clearance** local explorer select **Limit**.




- 9 In the Limit options, Block category, switch to limit tool centre to block edge.
- 10 Keeping all other values as default, **Calculate** the strategy.
- 11 After the **Toolpath** has been created, **Close** the dialog.





Double left mouse click on the explorer symbol (in this case *) to activate or de-activate the **Toolpath**.


Click the small + box to expand and view data used to create the toolpath.





Safe rapid move heights combined with Leads and Links

Rapid height and Plunge height values are set from the Safe Area dialog.




12 Click the Calculate button to set the Rapid height and Plunge height to be at safe distances above the top of the Model (whole or selected) or Block (whichever is the highest).




Rapid height is always above Plunge height.

- Rapid height specifies a fixed height at which safe rapid moves occur across the work piece.
- **Plunge height** specifies a fixed height at which the slower, plunge feed rate is applied before the tool finally drops onto a cutting move.
- **Rapid** and **Plunge heights** work in conjunction with the **Leads and Links** options providing a more comprehensive choice of **Toolpath** link options.







• **Safe** – Applies the **Plunging feed rate** from a fixed height above the job. This is more predictable and reassuring, but the non-cutting (air) moves takes more time and is inefficient, especially in the case of large, deep components.



• **Skim** - enables the downward, rapid feed rate to continue to a specified incremental **Plunge distance** above the full plunge depth before the slow plunge feed rate 'cuts in'. **Skim** then applies a rapid retract to an incremental **Axial clearance** above the highest point on the component 'in line' with a linear link move to the next plunge position. To cater for all types of machine tools, this move is a **Skim feed rate** (G1) (solid purple line), instead of a **Rapid** (G0) (dashed red line).



Incremental - applies the rapid feed rate all the way down to an incremental Plunge distance measured from the full plunge depth, at which point, the slow Plunging feed rate 'cuts in'. The Plunge option differs from Skim in that all rapid link moves occur at the absolute Rapid height.






The default **Link** move settings in the **Model Area Clearance** strategy template are **1st choice/2nd choice** = **Skim** and **Default** = **Incremental**.




Feed Rates

The **Feeds and Speeds** dialog uses the **Style** and **Colour** of elements along a toolpath to register the correct **Rapid Move** or **Feed Rate** values.

- Fixed **(G0) Rapid** moves = Red Dashed, Toolpath segments.
- Variable (G1) Feed Rate moves = Green/Orange, Toolpath segments.
- Plunge (G1) Feed Rate moves = Pale Blue, Toolpath segments.
- Skim (G1) Feed Rate moves = Purple, Toolpath segments.
- 1 From the **main** toolbar, select the **Feeds and Speeds** button and enter the values (shown below) in the **Cutting Conditions** area of the dialog.




- 2 Click Apply to assign these values to the active Toolpath (D50TR6-A1) and then select Accept to close the dialog.
- 3 In the **PowerMill explorer**, right-click on the toolpath and select **Settings...**.






The toolpath can also be activated or deactivated using the **Activate** option in the context menu.

- 4 This reopens the **Model Area Clearance** dialog.
- 5 Select the make a copy of the *Toolpath* button.
- 6 On the left of the Model Area Clearance dialog is a local explorer window.






When a local **explorer** option is selected the individual page is displayed in the main dialog. This makes it easier to navigate specifically through the pages for the required strategy.





- 8 In the **Links** page change the **1st choice**, **2nd choice**, and **Default** link moves to **Safe**.
- 9 At the bottom of the main dialog, select **Calculate** to create a new **Toolpath** with the modified settings. Once processing is complete, close the dialog.



The **Tool** now performs rapid moves (dashed red) at a fixed height (**Safe Z**) above the part (Default height is 10).

All **Plunge** feedrate (pale blue) moves start from a height between the **Safe Z** and the top of the part (default height is **5**).




Statistics

Provides you with essential information about the active toolpath and associated parameters.

1 In the **PowerMill** *explorer*, right-click the latest *Toolpath* **D50TR6-A1_1** and from the local menu select **Statistics**.

The dialog with information about the toolpath and its associated settings is displayed.



In this case, the total machining time is around 2hrs 10mins.

2 Right mouse click on the original *Toolpath* D50TR6-A1 and from the local menu select and view the **Statistics**.

In this case, the total machining time is around **1hrs 30mins**.

This large time saving is achieved simply by using **Skim** in the **Links** dialog. In the original toolpath, **Safe** was used, resulting in an excessive amount of the **Link** moves being in fresh air.

Simulating the toolpath

3 Right mouse click on the *Toolpath* D50TR6-A1 and from the local menu select Simulate from Start.



If not already displayed the above **Simulation** toolbar will appear automatically.

- 4 Use the **Play** button to run the simulation and control the speed with the slider bar.
- If the **ViewMILL** toolbar is not already open, from the **main** pulldown menus select **View Toolbar ViewMILL**.






In the **ViewMILL** toolbar, select the **Red** sphere to connect **ViewMILL** to the simulation controls (The sphere will now be **Green** and the current **Block** will be loaded into **ViewMILL**).



7 Select the **Plain Shaded Image** option and run the **simulation** again.



8 Switch the **ViewMILL** to **No Image** to return to the **PowerMill** session and then disconnect **ViewMILL** from the simulation process.

When you toggle back to **PowerMill**, the **ViewMILL** session still exists in the background, ready to include further toolpaths as required.

If the **ViewMILL** session is still connected, then, even though it is set to **No Image**, the **ViewMILL** session will continue to update in parallel with any further toolpath simulations.

Saving the Project

9 From the Main menu, select File > Save Project.

The **Project** (....\COURSEWORK\PowerMill-Projects\Spkr-Core) is now updated.


We will now *delete* the contents of the **PowerMill** *explorer* and return the **PowerMill** session back to the original default settings.

- 10 From the main menu, select File > Delete All.
- 11 From the main menu, select Tools > Reset Forms.



Other Model Area Clearance - Style examples

There are 4 different **Style** options in the **Model Area Clearance** strategy.




We have already used **Style** – **Raster** in the previous example. So for the next section we will simply show the basics of other 3 options (**Offset Model**, **Offset All**, and **Vortex**) on a single Z level.

Offset Model - Basic example

This variant of the **Offset Area Clearance** is primarily designed for **High Speed Machining**. It provides very consistent tool loading at the expense of increased number of rapid air moves across the component. This strategy, if applied correctly, can go a long way to minimise wear to both tooling and machine.

The strategy is based on the profile around the component at each Z Height, being continually offset outwards, to be trimmed to the limits of the material **Block**.


- 1 Import the Model:
 -\PowerMill Data\models\Handle.dgk
- **2** Save Project As:
 -\COURSEWORK\PowerMill Projects\Handle




- 3 Create a Dia 16, Tiprad 3, Tool named D16TR3.
- 4 Calculate a Block to the full model dimensions.
- 5 Lock the Z max and Z min values, enter an Expansion value of 10 and Calculate.




- 6 In the Rapid move heights dialog, select Calculate.
- 7 Select Toolpath Strategies , and from 3D Area Clearance open a Model Area Clearance strategy.
- 8 Input data into the pages of the form exactly as shown below.



9 Select the Offset page and tick the Spiral option.




10 Select the Flat machining page and select Machine flats - Off.





- 11 Select Unsafe segment removal and in the dialog *tick* Remove segments smaller than threshold.
- **12** At the bottom of the dialog, click **Calculate** to create the Toolpath.
- 13 Close the dialog and select an **ISO 1** view.



The above **toolpath** is displayed with the **Leads and Links** undrawn.

14 In **PowerMill** *explorer*, right-click the **Toolpath** and select **Simulate from Start** to display the **Simulation** toolbar.




15 On the **Simulation** toolbar, select **Play** to view the toolpath simulation. *To stop the simulation, press the* **Esc** *key on your keyboard.*


The tool continuously, climb mills, starting each tool track at a distance from the material **Block** to allow the tool to reach optimum **Feed Rate** before contact. The material removal rate in this type of strategy is generally very consistent. The strategy can be further improved using advanced settings to progressively smooth away sharp corners and straighten the toolpath geometry as it offsets further away from the component form.

- 16 In the **PowerMill** *explorer*, right-click the active **D16TR3-OffsetModel toolpath** and select **Settings** to reopen the **Model Area Clearance** dialog.
- 17 Click to create an active copy of the toolpath.
- 18 In the Model Area Clearance dialog, select the High speed page.





- g Select Profile smoothing and set Radius (TDU) to the maximum slider value of 0.2
- h Select Raceline Smoothing and set the slider value to 25 (%).
- i Click Calculate to create a new toolpath D16TR3_OffsetModel_HSM with the improved smoothing characteristics.




Compare the **Model Area Clearance** toolpaths. Note the progressive straightening of tool tracks on the second strategy with **Raceline smoothing** being applied.



Offset All - Basic example


This variant of the **Offset Area Clearance** is better suited to softer materials such as modelling foam, resins etc. It will remove material with a larger **stepover** and the minimum amount of lifts, but this is more than likely to result in the tool tracks containing sharp changes of direction and an inconsistent removal rate.

- 1 In the **PowerMill explorer**, right-click the active **D16TR3-OffsetModel** toolpath and select **Settings** to reopen the **Model Area Clearance dialog**.
- 2 Click to create a copy of the toolpath.
- 3 Rename the new toolpath as D16TR3-OffsetAll.
- 4 In the **Model Area Clearance dialog**, main page select **Style Offset All** and then input data as shown below.




5 In the **Model Area Clearance** dialog, select the **High speed** page and update the data as shown in the following illustration.





- 6 At the bottom of the dialog, click **Calculate** to create the **Toolpath**.
- 7 Close the dialog and select an **ISO 1** view.
- 8 Perform a toolpath **Simulation** to observe the tool movement in this strategy.




In the above **Offset-All** style toolpath, the tool plunges into the individual areas and profiles it's way outwards following both the component **model** and **Block** forms.



Vortex - Basic example


This specialist, variant of **Model Area Clearance** is primarily designed for use with solid carbide tools on hard materials. Wherever necessary the **Vortex** strategy applies complex, optimised trochoidal, movement to achieve the ultimate control over the loading on a cutting tool.

- 1 In the **PowerMill explorer**, right-click the active **D16TR3-HSM Toolpath** and select **Settings** to reopen the **Model Area Clearance** dialog.
- 2 Click and create a copy of the **Toolpath**.
- 3 In the Model Area Clearance dialog, main page select Style Vortex.




- a Input Thickness 0.5
- b Input Stepover 1
- c Input Stepdown 20
- 4 Select the **Flat machining** page and set *Machine flats* to **Off**.






5 Select the Vortex Page and set Minimum Radius (r) to 2.0




Increasing the **Minimum Radius** value will enlarge the inherent **Trochoidal** moves which should in turn enable a higher **Feedrate** to be used with the **Vortex** strategy.

6 Select the Unsafe segment removal page, tick Remove segments smaller than threshold and input a Threshold (TDU) value of 0.5



- 7 At the bottom of the dialog, click **Calculate** to create the **Toolpath**.
- 8 Close the dialog and select an **ISO 1** view.





- 9 Select File Save Project to update the contents of:-.....\COURSEWORK\PowerMill_Projects\Handle
- 10 From the main pull down menus, select File > Delete All.
- 11 From the **main** pull down menus, select **Tools > Reset Forms**.



Area Clearance – Unsafe Segment Removal

This option is designed to filter out machining of confined areas that involves a small movement of the cutting tool. In the following example, it is applied to prevent a relatively large tool attempting to plunge into a deep pocket area where a smaller tool would be a better choice.


12 Open the read-only **Project**:

.....\PowerMill Data\Projects\MountingBlock-Start

13 Save Project As:

.....\COURSEWORK\PowerMill-Projects\MountingBlock

14 Activate the Toolpath named No-AreaFilter.




The existing toolpath allows the cutter to machine into confined areas. This results in sudden sharp changes of cutting direction and excess loading on the tool.

- 15 Right-click on the **Toolpath** named **No-AreaFilter** and from the local menu, select **Settings** to open the original **Model Area Clearance** dialog.
- 16 Click the Create a new toolpath based on this one button, to create a copy of the toolpath.




- 17 Rename the copy of the toolpath as **AreaFilter**.
- 18 In the Model Area Clearance dialog, select the Unsafe segment removal page.
- 19 Tick the option, Remove segments smaller than threshold.
- 20 Input a Threshold (tool diameter units) value of 0.5
- 21 Un-tick the Only remove segments from enclosed areas option.





All tool tracks spanning a distance less than the Tool Diameter (TDU) are filtered out and will not appear in the final toolpath.

22 Calculate the **Model Area Clearance** dialog and once processing is complete, close the dialog.



Unsafe Segment removal has been applied to prevent the cutter attempting to plunge into and machine confined areas (Pockets).

However, there are a couple of undesirable spikes on the remaining toolpath. These can be reduced by applying the **High Speed** - **Profile Smoothing option**.


- 23 In the **PowerMill** *explorer*, right-click the toolpath named **AreaFilter** and select **Settings** to open the original **Model Area Clearance** dialog.
- 24 Click Create a new toolpath based on this one button, to create a copy of the toolpath.




- 25 Rename the copy of the toolpath as **AreaFilter-ProfileSmooth**.
- **26** In the **Model Area Clearance** dialog, select the **High Speed** page.



27 Select the **Profile Smoothing** option with the Radius (Tool Diameter Units) value set to **0.2**



28 Calculate the **Model Area Clearance** toolpath and once processing is complete, close the dialog.



The internal, sharp corners around the toolpath outer profile are now smoothed.

- 29 From the main pull down menus, select File > Save Project to update the stored data (.....\COURSEWORK\PowerMill-Projects\MountingBlock).
- 30 From the main pull down menus select File > Delete All.
- **31** From the **main** pull down menus select **Tools > Reset Forms**.




Model Rest Area Clearance example

It is generally good practice to use as larger diameter tool as possible for the initial **Area Clearance** operation. This ensures that the maximum amount of material is removed as quickly as possible. However, the large diameter tool may not have full access to certain internal corners or pockets within the component. As a result, these areas will require further roughing out with one or more, smaller diameter tools before running the **Finishing** strategies.

In the **Model Rest Area Clearance** options, a smaller **Tool** is referenced either to an existing **Toolpath** or a **Stock Model**, such that tool tracks will only be produced locally within the remaining material (stock).

1 Import the model:


 $...... \label{lem:lemonth} PowerMill_Data \label{lemodels} WingMirror Die.dgk$



2 Save Project as:


.....\COURSEWORK\PowerMill-Projects\WingMirrorDie-Ex1

- 3 Create a **Tip Radiused** tool of **Dia 40 tiprad 6** and name **D40TR6**.
- 4 From the **main** toolbar open the **Block** dialog and **Calculate** using the default settings, **Defined by Box** to and **Type Model**.
- 5 in the Rapid move heights dialog select Calculate.






6 Select Toolpath Strategies , and from 3D Area Clearance open a Model Area Clearance strategy.



- 7 In the Model Area Clearance strategy dialog:
 - a Enter Toolpath name D40TR6-D1
 - **b** Select **Style Offset Model**
 - c Input Thickness 0.5
 - d Input Stepover 20
 - e Input Stepdown 10
- In the local explorer, select the **Limits** page, and set the **Block Limit** to **Limit** tool centre to block edge.




In the local explorer, expand the **Leads and Links** options, and then select **Lead In**.






- 10 In the **Lead in** page, select **1st Choice Ramp** (Open the ramp options form).
- 11 Input the following Ramp Options:



- 12 Click Calculate to process the Model Area Clearance toolpath.
- 13 Select an ISO 2 view.




The **Offset Model** - **Area Clearance** strategy follows the model contours while gradually offsetting into the remaining material at each **Z Height**.


14 Right-click the toolpath and select **Simulate from Start** to display the **Simulation** toolbar.








Undrawing the tool will help to speed up the simulation. You can control the display of the tool by left clicking on the tool entity, light bulb in explorer.



The finished result indicates that in some areas of the model there is still too much material for the finishing strategies to cope with.




As a result, a further area clearance strategy is required using a smaller tool to continue locally into the remaining areas. This technique is known as Rest machining.

- 18 Click to suspend ViewMILL.
- 19 Click led to return to the **PowerMill** window.




Rest Roughing using a Reference Toolpath

- 1 Create a **Tip Radiused** tool of Diameter **16**, Tip Radius **3** and name it as **D16TR3**.
- 2 Select Toolpath Strategies, and from 3D Area Clearance open a Model Rest Area Clearance strategy.




- 3 By directly selecting **Model Rest Area Clearance**, the **Rest** machining options and the most suitable style, **Offset Model** will already be active in dialog.
 - a Enter a new Toolpath name D16TR3-D1
 - b Keep the Thickness as 0.5
 - c Enter Stepover as 1
 - d Enter Stepdown as 5
- 4 Tick **Rest machining** box to offer the **Rest** page in the strategy explorer.







5 Set the **Rest** machining type as **Toolpath**, enter **D40TR6-D1** as the reference toolpath, and input **Detect material thicker** than as **0.6**



In the local explorer, select **Unsafe segment removal** page and if set, un-tick the **Remove segments smaller than threshold** option.



- 7 Activate the **D16TR3** tool to be used in the new toolpath.
- 8 Click **Calculate** to process and create the additional **Offset Model Area Clearance** toolpath and then **Close** the dialog.



9 From the Main pull down menus select File - Save Project to update:

.....\COURSEWORK\PowerMill-Projects\Wing_Mirror_Die




- 10 Switch the ViewMILL On/Suspend button to a green sphere

- 11 Select the Rainbow Shaded Image
- 12 Right mouse click on the toolpath D16TR3-D1 and select Simulate from Start.
- button to start the simulation. 13 Press the Play



The ViewMILL simulation shows this toolpath shaded in a different colour where it has machined in areas the previous toolpath did not cover.



The Reference toolpath has successfully accessed material closer to the component form.

This will reduce the risk of excessive wear or damage to tools used for the subsequent finishing operations.

14 Click the **ViewMILL On/Suspend** button to a red sphere





to return to the **PowerMill** window.

Rest Machining using a Stock Model

An alternative method for rest roughing is the use of a Stock Model instead of a Reference toolpath.

The benefits of using a **Stock Model** compared to a reference toolpath are:

- The remaining surplus material can be visualised and registered along with the associated toolpaths.
- A rest machining strategy referenced to a **Stock Model** will include the effect of all previous toolpaths currently registered to that **Stock Model**.
- A toolpath that was created to a different workplane (for example, multi-axis) can be referenced to a Stock Model.



It is not possible to apply a rest machining strategy referenced to a toolpath that was created to a different workplane.




In this example a **Stock Model** is created to initially include the **D40TR6-D1** toolpath. Then, a copy of the toolpath, **D16TR3-D1** is created using the **Stock Model** for the rest machining reference.


1 In the **PowerMill explorer**, activate the toolpath **D40TR6-D1**.



In the PowerMill explorer, right-click Stock Models and select Create Stock Model.



- 3 Accept the above default values for the stock model triangle mesh creation.
- 4 In the PowerMill explorer, right-click the newly created Stock Model 1 and from the local menu select Apply > Active Toolpath First.




Both the currently active **Toolpath** and **Block** are added to **Stock Model**.



5 From the same menu, select **Calculate** to physically update the **Stock Model**.






A triangular mesh will appear representing the state of the material after the effect of the first machining strategy, **D40TR6-D1**.


In the next two actions, The Stock Model will be changed to:-

- a Visually remove the component form (**Show Rest Material**).
- **b** Visually change the style from triangle mesh to a shaded form (**Shaded**).
- 6 From the same menu, select **Drawing Options** > **Show Rest Material.**




7 From the same menu, select **Drawing Options > Shaded** to display the shaded view of the **Stock Model**.






- 8 In the **PowerMill** explorer, activate the toolpath **D16TR3_D1**.
- 9 Right-click on the toolpath D16TR3_D1 and select Settings to open the Model Rest Area Clearance strategy dialog.
- 10 Click to create a copy of the toolpath.
- 11 Select the **Rest** page and modify the settings as below using **Stock model 1**.




- 12 Click **Calculate** to create an alternative and more efficient rest machining toolpath named **D16TR3-D1_1**.
- 13 Close the machining strategy dialog.






Although the toolpath **D16TR-D1_1** appears (coloured purple) as a referenced entity in the **Stock Model** list, the resultant machining effect is not included.



14 In the **PowerMill** *explorer*, right-click the toolpath, **D16TR3-D1_1** and select **Add to** > **Stock Model**.






At this stage, the **Stock Model** will disappear from the screen.



15 Right-click the active **Stock Model** and select **Calculate** to update it.




- 16 From the main pull down menus, select File > Save Project to update:
 -\COURSEWORK\PowerMill-Projects\WingMirrorDie
- 17 From the main pull down menus select File > Delete All.
- 18 From the main pull down menus select Tools > Reset Forms.

Exercise

Area clearance with both unsafe segment removal and rest roughing

1 Import the Model:

.....\PowerMill Data\Models\Cowling.dgk




2 Select an **ISO 1** view.



Machining setup


- 3 Create the following tools:
- Tip Radiused tool Name D16TR3, Diameter 16 Tip Radius 3
- Tip Radiused tool Name D12TR1, Diameter 12 Tip Radius 1
- 4 Create a Workplane centrally position at the top centre of the Model, and then activate it.
- 5 Calculate a **Block** using **Defined by Box** and **Type Model**, then change the **Min Z** value to **-80** and lock it by selecting the adjacent padlock.
- **6** Calculate the Rapid Move Heights using the default settings.




Area Clearance Strategies

- 1 Create a **Model Area Clearance** strategy named **D16TR3-RGH1** using:
 - a The **D16TR3** tool.
 - b The Style as Offset All.
 - c A Thickness of 0.5
 - d Stepover 8 and Stepdown 12
 - e In the Flat Machining page use Level.
 - **f** Select the **Unsafe segment removal page**.
 - **g** Tick the box Remove segments smaller than threshold and leave the other settings as default.
 - h In the Leads and links Lead in set 1st choice as Ramp and in ramp options use Follow circle Max zig Angle 4.0 Circle diameter 0.65





- 2 Create another **Model Area Clearance** strategy named **D12TR1-RGH1** using:
 - a The **D12TR1** tool.
 - **b** The **Style** as **Offset Model**.
 - c Stepover 2 and Stepdown 3
 - d In the **Flat Machining** page use **Area**.
 - e Enable the **Rest** machining page and reference to the previous toolpath.
 - f Disable the Unsafe segment removal option.




3 Save Project As:


 $...... \\ COURSEWORK \\ PowerMill_Projects \\ Model Area Clear-Exercise$



ViewMILL Simulation










Do not close the **Project** as it will be continued in the following section.


Area Clearance using the Step option

If a large stepdown is used in the **Area Clearance** strategies then the bulk of the waste material will be removed as quickly as possible. This will inevitably leave large steps on the remaining stock that would normally be reduced using a separate **rest** roughing operation. However, if it is acceptable to use the same **Tool** then the **Step** option will provide rest machining within the same **Area Clearance** strategy. In this case additional passes are applied (where required) that step upwards between the original **Z Heights**.






- 1 Activate the existing toolpath **D16TR3-RGH1** to restore the settings used.
- 2 Run a new ViewMILL simulation (as shown above) on the toolpath D16TR3-RGH1.
- 3 Select Exit ViewMILL to close the current session.
- 4 Right mouse click on the active toolpath **D16TR3-RGH1** and from the local menu select **Settings**.
- 5 Select the 'Make a Copy' of the toolpath option
- 6 Rename the new toolpath as **D16TR3_Step-RGH1**.
- 7 In the main page of the dialog change the Style to Offset model.
- 8 In the Model Area Clearance, local explorer, select Step cutting.
- 9 Tick the Step cutting box and enter values exactly as shown below.




6 Select **Calculate** to create the toolpath **D16TR3_Step-RGH1**.




7 Run a new ViewMILL simulation on the toolpath D16TR3_Step-RGH1.





The above image shows the effect of the **Step cutting** option tracking upwards from the first slice to get closer to the model form.



The Component has been 'Roughed Out' with maximum efficiency, close to the final shape within the same strategy.

- 8 Save the Project.
- 9 From the main pull down menus select File > Delete All.
- 10 From the **main** pull down menus select **Tools > Reset Forms**.




Model Area Clearance – Vortex example

Vortex machining is an **area clearance** strategy which rapidly removes material from a 3D part while controlling tool load. **Vortex** is best suited to solid carbide tools and is frequently used in combination with **step** cutting.

The engagement angle never exceeds that produced by a straight line cut with a given **stepover**. This eliminates excessive tool load and all full-width cuts. This enables you to increase feed rates. As the tool approaches the maximum engagement angle, the strategy automatically changes to use a trochoidal path to avoid tool overload.

10 Open the (read-only) Project:-






11 Save Project As:-


.....\COURSEWORK\PowerMill_Projects\Vortex2

- **12** Activate the **workplane**, **TopCentre-datum**.
- 13 From the main toolbar select Block and using, Defined by Box Type Model select Calculate followed by Accept.
- 14 From the main toolbar select Rapid Move Heights and in the form select Calculate followed by Accept.
- 15 Select Toolpath Strategies , and from 3D Area Clearance open a Model Area Clearance strategy.






- 16 In the **Model area clearance** page of the strategy dialog:
 - g Enter Toolpath name D16TR3-Vortex-RGH1
 - h Select Style Vortex
 - Set **Cut direction** with both **Profile** and **Area** as **Climb**.
 - i Input Thickness 0.5
 - k Input Stepover 3.0
 - I Input Stepdown 12.0
- 17 Open the **Vortex** page of the strategy dialog:




a Input Minimum radius (r) as 3.0



18 Open the **Step cutting** page of the strategy dialog:




- a Tick the Step cutting box and then input a Stepup value of 1.0
- 19 Open the **Flat machining** page of the strategy dialog:




a Set Machine flats to Level.

20 Open the **Approach** page of the strategy dialog:




- 21 In the Helical ramp options window, select Max zig angle 4 with a Circle diameter 0.7 and Height 5.
- 22 At the bottom of the dialogue select **Calculate** to process the **Vortex Model Area Clearance** toolpath.





23 Perform a **ViewMILL simulation** on the toolpath to observe the **Vortex** strategy.



24 Save the Project.




Machining Flat features within Model Area Clearance

The **Model Area Clearance** strategies in **PowerMill** include options to control the way in which flat areas of the component model are machined. These are accessed from the **Machine Flats** page on the dialog.


- 1 Select File Delete All and Tools Reset Forms.
- 2 Import the Model:

.....\PowerMill Data\Models\Flats.dgk




- 3 Select File Save Project As:
 -\COURSEWORK\PowerMill-Projects\AreaClearFlats
- 4 Create a 12mm diameter End Mill tool named EM12.
- 5 Calculate the **Block** using the default settings.
- 6 Calculate default Rapid Move Heights.
- 7 Keep the **Start and End Point** settings as default.
- 8 Select Toolpath Strategies , and from 3D Area Clearance open a Model Area Clearance strategy.






- 9 In the Model Area Clearance strategy dialog:
 - a Enter the *Name* as **EM12-FlatsOFF**.
 - b Set Thickness to 0.5
 - c Set Stepover to 5
 - d Set Stepdown to 12
- 10 Select the **Flat machining** page and set **Machine flats** to **Off**.




11 Click **Calculate** to process the toolpath and then **Close** the dialog.





When the **Machine flats** option is set to **Off**, the toolpath totally ignores the flat surfaces of the model. It maintains the defined **Stepdown** value and performs area clearance across the material **Block** at each **Z Height**.

- 12 Right-click the active toolpath, **EM12-FlatsOFF** and select **Settings**.
- 13 Click to create a copy of the toolpath.
- 14 Change the new toolpath name to EM12-FlatsLEVEL.
- 15 On the **Flat machining** page, change **Machine flats** to **Level**.
- **16 Calculate** to process the toolpath and then Close the dialog.




When the **Machine Flats** option is set to **Level**, the toolpath machines the whole **Block** area for each flat area. The **Stepdowns** are reduced as required to be constant between individual flat areas.

- 17 Right-click the active toolpath and select **Settings**.
- 18 Click to create a copy of the toolpath.
- 19 Change the toolpath name to **EM12-FlatsAREA**.
- 20 On the **Flat machining** page, change **Machine flats** to **Area**.



21 Calculate to process the toolpath and then **Close** the dialog.



The **Model Area Clearance** toolpath now removes material locally on each individual flat area leaving a total of 0.6mm stock (The **Thickness** plus the **Tolerance**). The nominal stepdown remains constant with flat area machining occurring separately between these levels.

22 Select File - Save Project to update:-


.....\COURSEWORK\PowerMill-Projects\AreaClearFlats

Machining Flats separately using Slice Area Clearance

In **PowerMill Pro** it is possible to use **Slice Area Clearance** to separately machine the flat areas of a model to their exact height. This could be used:

- a As a finishing strategy, applied to the flat areas after a Model Area Clearance roughing strategy where Machine flats was set to Level or Area.
- **b** As a secondary roughing strategy, applied to the flat areas only, that follows on from a **Model Area Clearance** where **Machine flats** was set to **Off**.


There are several types of 2D entity that are supported in the **Slices** options:-




11 Right-click on the **EM12-FlatsArea** toolpath and select **Activate** to reinstate all settings and parameters used.



12 Select Toolpath Strategies , and from 3D Area Clearance open a Slice Area Clearance strategy.




- a Enter Name as EM12-SliceAC.
- **b** Set **Slices** as **Flat**.
- c Set Style as Offset All.
- d Set Tolerance 0.02
- e Set Thickness 0
- f Set Stepover 5
- 13 Select the **Flat machining** page (Available when **Slices Flat** is active).



- 14 Check that the Allow tool outside flat box is unticked.
- 15 Select Calculate to process the toolpath and then Close the dialog.





This Slice Area Clearance strategy is confined to the Flat areas only.

At the moment, the cutter profiles around the edge of the holes located within a flat area. If preferred, the strategy can be changed to Ignore Holes (below a specified Diameter) causing the tool to pass straight across them.

- 23 Right-click on the Active toolpath and select **Settings** to re-open the **Slice Area Clearance** dialog.
- 24 Click on to create a copy of the toolpath.
- 25 Rename the toolpath as **EM12-SliceAC-IgnoreHoles** and then select the **Flat** machining page.




26 Select Tick in the Ignore holes box.

The **Threshold** (tool diameter units) defines the maximum size of holes to ignore. With the tool **EM12** selected and the **Threshold** set to **2**, holes that are greater than Dia 24mm will not be ignored.

27 Select **Calculate** to process the toolpath and then **Cancel** the dialog.






The cutter now passes across the top of the holes without lifting, producing a smoother, more efficient, toolpath.




Ignore Holes refers to the area defined by the slice definition at the top of the holes. The flat base of any hole will still be machined.

- 28 Right-click the Active toolpath and select **Settings** to re-open the **Slice Area Clearance** dialog.
- 29 Click on to create a copy of the toolpath.
- 30 Rename the toolpath as **EM12-SliceAC-MultipleCuts** and then select the **Flat** machining page.



- g Select the Multiple cuts option and set the Number of cuts as 3.
- h Input the Stepdown as 2.0
- i Select the Final stepdown option and input 1.0
- 31 Select **Calculate** to process the toolpath and then **Close** the dialog.





If there is a large amount of material remaining above the flat areas, then the **Multiple Cuts** option is applied to reduce the tool loading during **Area Clearance**.



The 'D' shaped **Flat** area at the very top level does not use Multiple Cuts as the top of the **Block** is the overall Z limit for the strategy.

32 Select File - Save Project to update:-

(.....\COURSEWORK\PowerMill-Projects\AreaClearFlats)




Further information on Area Clearance Machining

The following is reference information for the many different options contained in the Area Clearance dialogs. This can also be found by using Help.

Restrict Tool Overload - Trochoidal moves

This option is available to Area Clearance strategies in which Style - Offset model is set. The dialog for activating and entering the Maximum overload value (%) is located on the High speed options page.





If the tool reaches a specified overload situation, **PowerMill** automatically inputs a trochoidal path to eliminate full width cuts. This will occur in corners, narrow channels, slots, etc. The degree of movement is controlled with the slider as a percentage value of the specified stepover.

Thickness

Click the **Thickness** button in strategy dialogs to enter separate **Radial** and **Axial** thicknesses.








- 1 Radial Thickness
- 2 Axial Thickness



Z Heights - Manual entry

To manually enter Z heights in a strategy, select **Manual** from the **Stepdown** list.



Click to display the **Area Clearance Z Heights** dialog.

Defined by defines how Z heights are specified. You can define a Z height by:

- Number divides the Block equally into the defined number of Z heights, the lowest of which will be at the base of the Block.
- **Stepdown** creates a Z height at the top of the block and then steps down a defined height in Z. The final Z Height will be at the bottom of the block.

If the **Constant Stepdown** option is selected, the distance between all Z height levels remain constant. To achieve this, the actual stepdown value will more than likely have to be automatically modified to be less than the nominal value.

- Value creates a single Z Height at the defined value.
- **Flat** Identifies flat areas of the model and creates a Z height (+ thickness) at these values. It can also be set to machine the specific flat areas instead of the whole of the slice.
- Intermediate adds a specified number of Z Heights between the current ones.

Append All - Z Heights can be also be appended from an existing Model Area Clearance toolpath using the Reference section of the Area Clearance Z Heights dialog.

Profiling

A profile move can be performed at each level to remove steps that are left by the cutter **Before**, **During**, or **After** a **Raster Model Area Clearance strategy**. Additional profile passes can be applied when machining either on every Z or the last Z level with **Offset**, **Profile**, or **Raster** strategies.

When

The **When** settings on a **Raster** page in an **Area Clearance** strategy dialog allow you to determine when the profiling pass occurs during machining.

- None No profiling pass is performed
- **Before** The profiling pass is performed before the Raster path.
- During The profiling is performed at suitable intervals during the Raster path.
- After The profiling pass is performed after the Raster path.



Cut Direction

The **Cut Direction** settings control the direction of the tool along the toolpath:

Any – This instructs the cutter to machine in both directions.

Climb – This instructs the cutter to profile such that the material is to the right of the direction of travel (Climb milling).

Conventional – This instructs the cutter to profile such that the material is to the left of the direction of travel (Conventional milling).

Wall Finishing

The **Wall Finishing** page in the **Model Area Clearance** strategy dialog allows you to make an additional, final profiling pass to further reduce tool wear.

Allow tool outside block

The **Allow tool outside block** setting is available on the **Limit page** of the **Model Area Clearance** dialog.

This enables the strategy to exist outside the **Block** by the **tool radius** value.



This option limits the strategy with the tool centre flush with the **Block**.



Flat Machining

The **Flat Machining** page of the **Model Area Clearance** dialog contains options to control if and how the flat areas of a component are machined. These include Off, **Area**, and **Level**.

Level - Flat Machining occurs across the whole area defined by the Block.

The nominal Stepdown value is locally reduced as required to accommodate each Flat area as part of an equally spaced group.

Area - Flat Machining is confined to the individual Flat areas.


The nominal Stepdown value remains constant (independent of the Flat areas).

Ramping

The **Ramp** option is available on the **Leads and Links** dialog to use where it is impossible to approach from outside the **Block** at the full machining depth (for example, within a pocket).

- There are 3 different options for the type of Ramp move Toolpath, Circle, and Line. These can be used to lead on to the start of a tool track.
- The Zig angle is the angle of descent along the machining direction as the tool ramps into the material. If the length of the Zig angle is limited to a finite distance, a ramp move in the opposite direction (Zag angle) can also be applied.





The **Ramp Length** is defined as **Tool Diameter Units (TDU)**. For example, A Ramp Length of **2 TDU** would equal 20 mm for a Dia 10 mm tool.

If **Add approaches from outside** is set, it will take priority over the **Ramping**.


If the defined geometry for a **Ramp** move is such that it would cause a gouge, then the tool approaches using a default **Plunge** move.



4. Finishing Strategies

Finishing strategies machine the actual component form, and where applicable, follow on from the **Area Clearance** operation. Suitable values are required to control the accuracy and amount of excess material to be left on a component by a toolpath. The parameters used for this purpose are called **Thickness** and **Tolerance**.


Thickness is the amount of extra material specified to remain on the work-piece after machining. This can be applied generally as an offset from the model (as shown), or independently as separate **Radial** and **Axial** values within the machining options.





It is also possible to assign additional **Thickness** values to selected surfaces on the model (**Component Thickness**).

Tolerance controls the accuracy to which the cutter path follows the shape of the work-piece. For roughing, use a coarse tolerance, and for finishing use a fine tolerance.





A positive **Thickness** value should always be greater than the **Tolerance** value.




Raster Finishing and Pattern Finishing

Raster Finishing works by projecting a wireframe, Pattern down the Z-axis onto the model. The standard pattern applied in **Raster Finishing** is obtained by entering values directly into the **Finishing** dialog. Two other types of standard pattern strategy (not covered in this course) include **Radial** and **Spiral**.

The **Pattern Finishing** strategy uses an existing, pre-defined **Pattern** or **Toolpath**, which is either projected down Z onto the model or used in situ as a **Drive Curve** to generate the toolpath.

Typical previews of all 4 available pattern strategies are shown below as viewed down Z.




The **Raster finishing** strategy is used as an example in the next section.


Raster Finishing

- 1 From the main pull down menus select **File Delete All** and **Tools Reset Forms**.
- 2 Then select File Open Project:
-\PowerMill Data\Projects\Handset Start






- 3 From the main menu , select File Save Project As:
 \COURSEWORK\PowerMill-Projects\Handset_PatternMC
- 4 Activate the existing toolpath D25TR3-RGH1 to restore all the Block and settings.
- 5 Activate the tool **BN12**.
- From the main toolbar, select Toolpath Strategies and from Finishing open a Raster Finishing strategy.




7 Click **OK** to display the **Raster Finishing** strategy dialog and enter the following settings and values.






- a Name the toolpath BN12-Raster-SEM1.
- b Enter the Tolerance as 0.1 and Thickness as 0.4
- c Select Ordering Style as Two Way.
- d Enter a Stepover of 2
- e Click the **Preview** tab to display the pattern (as shown below).






Several options exist to add **lead and link** moves at the start and end of each individual tooltrack. The aim is to reduce unnecessary lifta and to provide a smoother transition of the tool tangentially onto the component form instead of simply plunging directly down the Z-axis.

- 8 In the **Raster Finishing** dialog open the **Leads and Links** options (left click on the small box containing +).
- 9 Select the Lead in page and select 1st choice as Vertical arc, input Angle 90, Radius 6.0
- 10 Tick the **Apply constraints** box and set the **Distance** > **5.0** (Greater than).




- 11 At the bottom right of the same dialog, select **Lead out the same as lead**
- 12 Select the Links page (shown on next page) and input the 1st choice as Circular arc.
- 13 Tick the **Apply constraints** box and set the **Distance < 5.0** (less than).






14 Click Calculate to process the toolpath and then Close the dialog.




The above toolpath contains sharp corners along the vertical plane. These can be arc fitted within the **Raster Finishing** dialog using the **Arc fit corners** option.



- 15 In the **PowerMill** *explorer*, right-click the **BN12-Raster-SEM1** toolpath and select **Settings**.
- 16 Click to enable the toolpath **BN12-Raster-SEM1** to be edited and open the **High speed** page.




- a Select the Arc fit corners option and edit the arc radius to the maximum value 0.2
- **b** Click **Calculate** to process the toolpath and then **Close** the dialog.
- 17 Zoom into the toolpath to view the arc fitted tooltracks:




The value **0.2** (**TDU**), multiplied by the tool diameter (**12**) produces a radius of **2.4**

- 18 In **PowerMill explorer**, right-click on the toolpath **BN12-Raster-SEM1** and select **Settings**.
- 19 Click to create a copy of the toolpath and rename it as **BN12-Raster-FIN1**.
- 20 Change the raster finishing Angle from 0 to 135.
- 21 input more suitable finishing values as shown in the following image.



22 Click **Calculate** to process the toolpath and then **Close** the dialog.






If the *raster pattern* is projected downwards parallel to a steep wall then the actual distance between the tooltracks is likely to become unacceptably large.

For this reason the *raster pattern* in **BN12-Raster-FIN1** has been created at a **135 Angle** to minimise where the tooltracks run parallel to steep walls.

23 Run a full **ViewMILL** simulation on all 3 existing toolpaths.




24 Disconnect ViewMILL from the simulation process (Change the sphere from green to red) and then select No Image to return to the PowerMill view.



Pattern Finishing

This strategy requires a user-defined **Pattern** to be projected onto the model as a toolpath. This option can be used for applications such as scribe lines, text, and custom strategies. A **Pattern** is created either from within **PowerMill** or from imported wireframe CAD data.


25 In the PowerMill explorer, right-click Patterns and select Create Pattern.



A new, empty **Pattern** is created.




- 26 Right mouse click on the new empty Pattern and from the local menu select Insert - File to access the Open Pattern dialog.
- 27 Click button 2 on the lower left of the *Open Pattern* dialog:




28 Double click the Patterns folder to access it and then select the file Engrave1.dgk.





29 Click Open.


The imported **Pattern** is made up of 2D geometry and is positioned relative to the **Transform** (World co-ordinates).



Next this 2D geometry will be projected along Z onto the 3D model to create a single **Pattern Finishing** toolpath with a negative Thickness value.

- 30 Activate the tool BN1.
- 31 From the main toolbar, select **Toolpath Strategies** and from **Finishing** open a **Pattern Finishing** strategy.






- a Enter the Toolpath name BN1-Engrave
- b Input Pattern 1.
- c In 3-Axis applications the **Base position** can be set to either **Automatic** or **Vertical**, for the **Pattern** form to be projected down Z onto the model.
- d Enter a Tolerance 0.02 and Thickness -0.4
- 32 Select the **Lead in** page and select 1st choice as **None**.
- 33 Select the option Lead out the same as lead in.



- 34 Select the Links page set both 1st choice and 2nd choice to Skim, and Default to Incremental.
- **35** Select **Calculate** to process the toolpath then **Close t**he dialog.




The **Pattern** is machined to an offset depth of **-0.4** into the finished model form.





It is not possible to use a -ve thickness value that is greater than the Tool Tip Radius. There is, however, an alternative way to achieve this (Chapter 10 Patterns, page 20 - Deep Pattern Machining).

36 Simulate the engraving toolpath in **ViewMILL**.



37 Select File - Save Project to update the contents of:

.....\COURSEWORK\PowerMill-Projects\Handset_PatternMC




3D Offset and Constant Z Finishing

In this section, **3D Offset** and **Constant Z** finishing strategies are applied to a model that consists of a combination of flat and steep areas plus a pocket with vertical walls. In this example a **Boundary** will be created and used to limit the two strategies to where they are most effective.

- 38 Select File Delete All and File Reset Forms.
- 39 Select File Open Project and in the dialog browse to:

.....\PowerMill_Data\Projects\camera_start


The **Project** is locked and subsequent changes cannot be saved unless the included lock file is deleted.



- 40 Select **OK** to continue loading the Project into the **PowerMill** session.
- 41 From the main pull down menus, select File Save Project As:

.....\COURSEWORK\PowerMill_Projects\Camera_Example

The **Project** already contains a **Tip Radiused** tool and a **Model Area Clearance** toolpath along with the associated settings.





Creation of a Shallow Boundary to define specific machining areas


A **Shallow Boundary** creates segments around areas of the model that are defined by an Upper and Lower threshold angle. It is therefore specifically suited to steep walled and shallow surface machining techniques.




There are several other types of **Boundary** options available to suit various applications and these are covered later in Chapter 6.

In the following example, a **Shallow Boundary** is used to discriminate areas most suited to the individual machining strategies. This type of **Boundary** is calculated, taking the **Active Tool**, **Thickness**, and **Tolerance** into consideration.

- 1 Activate the existing toolpath RoughOP1 to restore the original settings.
- 2 Define a **Ball Nose** tool of diameter **10** named **BN10**.
- 3 In the PowerMill explorer, right-click Boundaries and select Create Boundary - Shallow.




4 In the displayed **Shallow Boundary** dialog:





- a Enter the Name as ShallowBN10
- b Enter Upper Angle 30 and Lower Angle 0
- c Enter Tolerance as 0.02
- d Enter Thickness as 0
- e Ensure the correct tool **BN10** is **Active**.
- f Un-tick the box, **Allow boundary to be private**.
- g Apply and Accept the dialog.

With the **model**, **Tool**, and **Toolpaths** undrawn, the **Boundary** can be viewed as shown:




This **boundary** is made up of numerous segments; each one dividing the model into **steep** and **shallow** areas. Any of these segments can be selected and individually deleted at any time, except when it is assigned to a toolpath and locked.




Constant Z Finishing

Constant Z Finishing projects each tool track horizontally onto the component at fixed heights defined by the **Stepdown**.



As the component surface becomes shallow, the actual tool stepover increases until it becomes non-existent on flat areas.


5 From the main toolbar, select **Toolpath Strategies** and from **Finishing** open a **Constant Z Finishing** strategy.



- 6 In the **Constant Z Finishing** dialog:
 - a Enter a Toolpath name, BN10-ConstantZ
 - **b** Tick the **Spiral** option.
 - c Enter a Tolerance of 0.02
 - d Set the Cut Direction to Climb.
 - e Enter a Stepdown of 0.5




7 On Constant Z Finishing dialog, select the Limit page and with the Boundary ShallowBN10 active, set Trimming to Keep outside.



8 Click **Calculate** to process the toolpath and then **Close** the dialog.

By using the **Boundary** - **Trimming** option as **Keep outside**, the toolpath is limited to the steep areas of the model.




Introduction to Leads and Links

The current toolpath (BN10-ConstantZ) has inherited circular Ramp lead moves (pale blue) from the previously activated toolpath RoughOp1. From the main toolbar we will open the Leads and Links dialogue and apply Horizontal Arcs to both the start and end of the Long link moves.



9 Click the Leads and Links button




- 10 Select the **Lead In** tab in the above dialog and:
 - a In Lead in, change the 1st Choice to Horizontal Arc, Angle 90 and Radius 5
 - **b** Un-tick the **Apply constraints** box.
 - Click the **Lead Out the same as lead in** button.



Overlap distance (tool diameter units) 0.0

11 Apply and Accept the dialog.




The tool now **leads in** and **out** of the active toolpath with a **Horizontal arc** move.



3D Offset Finishing

3D Offset Finishing creates the toolpath **stepover** relative to the **3D Model** providing consistency over both flat and steep areas. To produce an improved tool movement over the model a **Shallow Boundary** will be used to limit this strategy to where it is most effective.


1 From the main toolbar, select **Toolpath Strategies** and from **Finishing** open a **3D Offset Finishing** strategy.



- 2 In the **3D Offset Finishing** strategy dialog:
 - a Enter Toolpath name as BN10-3Doffset
 - b Tick the **Spiral** option
 - Set the Cut Direction to Climb
 - d Enter a Tolerance of 0.02
 - e Enter a Thickness of 0
 - f Enter a Stepover of 0.5




3 On the 3D Offset Finishing dialog, select the Limit page.



- 4 Select the Boundary ShallowBN10.
- 5 Select **Calculate** to create the toolpath and then **Close** the dialog.

The toolpath follows the contours of the **Boundary** segments and is produced only within the **shallow** areas of the model (**Inside** the **Boundary**).




This toolpath has inherited the current settings in the **Leads and Links** dialog, as applied to the previous toolpath **BN10-ConstantZ**. A more suitable option for bot **Lead in and Lead** out would be **Vertical arc**.

- 6 Click the Leads and Links button from the top of the screen.
- 7 Select the Lead in tab and:
 - Un-tick the Apply constraints box and change the 1st Choice to Vertical arc, with Angle 90 and Radius 5.
 - **b** Click the **Lead Out the same as lead in** button.
- 8 Apply and Accept the dialog.




The **toolpath** now is more efficient with the rapid moves at **skim height**, the **long links** using **Vertical arc** Leads, and the **short links** being linked along the surface.






To further improve this **3D Offset** strategy, you can tick the **Smoothing** option. This results in sharp corners being replaced with a smooth blend wherever possible.



9 Simulate all of the toolpaths in ViewMILL.




10 Select File - Save Project to update (but do not close):.....\COURSEWORK\PowerMill-Projects\Camera_Example




Optimised Constant Z Finishing

This strategy is a mixture of **Constant Z** and **3D Offset** machining; **Constant Z** is applied to steep areas and, **3D Offset** is applied to shallow areas.

- 11 De-activate the **Boundary**, **ShallowBN10** in the **PowerMill explorer**.
- 12 From the main toolbar, select Toolpath Strategies and from Finishing open an Optimised constant Z Finishing strategy.



- a Enter Toolpath name as BN10-OptCZ
- **b** Tick the **Spiral**, **Closed Offsets**, and **Smoothing options**.
- c Enter the Tolerance as 0.02
- d Set the **Cut direction** to **Climb**.
- e Enter a **Stepover** value of **1**
- f On the **Limit** page, make sure that the **Boundary** is not selected.




13 Select **Calculate** and when the toolpath is created, **Close** the dialog.



Note the consistent 3D Stepover across the whole component.





14 Select File - Save Project to update (but do not close):.....\COURSEWORK\PowerMill-Projects\Camera_Example




Steep and Shallow Finishing

This strategy includes the following additional options:-

The option to input a **Threshold Angle** to control the extent of the **Constant Z** and **3D Offset** areas of the toolpath.


The option to input a **steep shallow overlap** value between the **Constant Z** and **3D Offset** areas.

- 1 From the main toolbar, select Toolpath Strategies and from Finishing open a Steep and Shallow Finishing strategy.
- 2 Enter the values exactly as shown:



- a Enter Toolpath name as BN10-SteepAndShallow.
- **b** For the *Order* select **Steep first**.
- c For the Threshold angle input 30.
- **d** *Tick* both of the **Spiral** boxes.
- e For both the **Stepdown** and **Stepover** input **1**.
- f For Type (shallow) select 3D offset.
- g Tick the Smoothing box.
- 3 Select **Calculate** to process the toolpath and then **Close** the dialog.





4 Select File - Save Project to update:-

.....\COURSEWORK\PowerMill-Projects\Camera_Example

Steep and Shallow finishing with separate Shallow Stepover

Both **Optimised Constant Z** and **Steep and Shallow** strategies have an option to apply a separate, larger **Stepover** across shallow areas. This option is designed to enable a more efficient machining of shallow areas with a **Tip Radiused** tool.

The main advantage with the **Steep and Shallow** strategy is that the **Threshold Angle** is user defined. This can be set to **0** enabling a large stepover to be applied over flat areas only.

- 1 Select File Delete All and Tools Reset Forms.
- 2 Select File Open Project and in the dialog browse to:

.....\PowerMill_Data\Projects\ADV-SteepShallow-Start




- 3 Click **OK** to load the read-only **Project** into **PowerMill**.
- 4 Save Project As:

.....\COURSEWORK\PowerMill_Projects\ADV-SteepShallow-EX1


In the **PowerMill** *explorer*, right-click on the existing toolpath **D16t3-SteepShallow-FIN** and select **Settings**.



The component form includes 2 flat areas which are currently finished with the same small **stepover** as the angled walls. For more efficiency, an option is available for a larger stepover to be independently applied to the shallow flat areas.




- 6 Click **Recycle** to enable edits to the existing toolpath.
- 7 Update the main page of the dialog exactly as shown below.



- a Select Order as Top first.
- **b** Input the **Threshold angle** as **0**
- c Tick the Calculate using cusp box and input 0.01
- d Input a Stepdown of 0.01 and a Maximum stepdown of 0.3
- e For the shallow regions, enter a **Stepover** of **6**




8 Click **Calculate** to process the toolpath and then **Close** the dialog.



The **flat areas** are machined more efficiently using a large **stepover** while the **steep areas** use a small, variable **stepdown** based on the **cusp height**. This provides an efficiently produced, consistent finish over the whole form.

9 Run a **ViewMILL** simulation on both the *Roughing* and *Finishing* toolpaths.



10 Select File - Save Project, to update:-

.....\COURSEWORK\PowerMill_Projects\ADV-SteepShallow-EX1




Corner Finishing

Corner Finishing strategies identify and remove material in corners that are inaccessible to previously used, larger tools. There are 3 independent types of strategy: **Along**, **Stitch**, and **Automatic**.

All **Corner Finishing** strategies include a **Threshold Angle** option. This is the downward angle from the horizontal, where the steep and shallow portions meet.


The **Threshold Angle** can be defined to prevent the tool running up or down steep slopes. For example, you could apply a **Stitch** strategy to track across the steep areas, while using the **Along** strategy in shallow areas.





If the **Threshold Angle** is **90** then the steep area will not exist.

The **Corner Finishing** and **Multi-Pencil** strategies machine the areas that are inaccessible to the Reference tool (2) but are accessible to the active tool, as in the diagram.



In the following example, the **Corner Finishing** strategy uses a Dia 10 Ball Nose for the reference tool, and a diameter Dia 5 Ball-nose to perform the rest machining.

- 11 Select File Delete All and Tools Reset Forms.
- 12 From the main menu, Select File Open Project and select:

.....\PowerMill Data\Projects\CornerFinish start


13 From the main menu, select File - Save Project As:

.....\COURSEWORK\PowerMill-Projects\CornerFinish




Corner Along Finishing


14 Select an ISO 2 view.



- 15 Activate the **toolpath**, **D16T3-rghA1** to restore the settings.
- 16 Create a Dia 5 ball nose tool named BN5.
- 17 From the main toolbar, select Toolpath Strategies and from Finishing open a Corner Finishing strategy.




- a Enter Toolpath name as **BN5-CornerAlong_Shallow**.
- b Change Output to Shallow and Strategy to Along.
- c Set Cusp to 0.03
- d Set Cut direction to Climb.
- 18 On the **Tool** page, check that the **BN5** tool is active.






19 Select the **Corner detection** page and select the **Reference tool** as **BN10**.




- 20 Select the **Lead in** page and set the **1st Choice** to **None**.
- **21 Calculate** to process the **toolpath** and then **Close** the dialog.
- **22 Simulate** the **toolpath** and observe the order of the machining:



Note: With **Output** set to **Shallow**, the toolpath has stayed within the shallow areas of the model (between horizontal and a downward angle of 30 Degrees).




If the **Threshold Angle** is **90** then the **steep** area will not exist.






Corner Stitch Finishing

23 From the main toolbar, select Toolpath Strategies and from **Finishing** open a **Corner Finishing** strategy.



- a Enter Toolpath name as BN5-CornerStitch_Steep.
- **b** Change **Output** to **Steep** and **Strategy** to **Stitch**.
- c Check that the **BN5** tool is active on the **Tool** page.
- d Check that the **Reference tool** is **BN10** on the **Corner detection** page.
- 24 Calculate to process the toolpath and then Close the dialog.



This time, only the steep areas are machined.


25 From the main menu select File - Save Project to update:-

.....\COURSEWORK\Projects\CornerFinish




Corner Automatic Finishing

1 From the main toolbar, select **Toolpath Strategies** and from **Finishing** open a **Corner Finishing** strategy.



- a Enter Toolpath name as BN5-CornerBoth_Automatic.
- **b** Use **Strategy Automatic**.
- c Change Output to Both.
- d Change the *Threshold angle* back to 30.0
- 2 Click **Calculate** to process the toolpath and then **Close** the dialog.




This strategy automatically uses **Along** for the **Shallow** areas and **Stitch** for the **Steep** areas.



Corner Pencil Finishing

Corner Pencil Finishing creates a single toolpath along the actual intersection between non-tangential faces on the model.


3 From the main toolbar, select Toolpath Strategies and from Finishing open a Corner Pencil Finishing strategy.



- a Enter Toolpath name as BN5-CornerPencil.
- b Change Output to Shallow.
- c Change the Threshold Angle to 90

Note: With a **Threshold Angle** of **90** a **Steep** angle will not exist, so only the **Output** options **Shallow** or **Both** will enable a toolpath to be created.

- d On the **Tool** page, make the **BN5** tool active.
- 4 Select **Calculate** to process the toolpath, and then **Close** the dialog.







Corner Multi-pencil Finishing

Corner Multi-Pencil Finishing creates a multi-track, rest finishing, toolpath based on the Pencil Finishing strategy. On creation it visually looks similar to a Corner Finishing toolpath, but on closer inspection there are subtle differences to the toolpath order and that it includes tool tracks along the model intersections.

1 From the **main** toolbar, select Toolpath Strategies and from Finishing open a Multi-Pencil Finishing strategy.



- a Enter Toolpath name as BN5-CornerMultiPencil.
- b Change Output to Both.
- c Change the Threshold Angle to 90
- d On the **Tool** page, make the **BN5** tool active.
- e In the **Corner detection** page check that **BN10** is selected.
- 2 Calculate to process the toolpath and then Close the dialog.



3 From the Main menu select File - Save Project to update:-

.....\COURSEWORK\Projects\CornerFinish




Flat Finishing

These strategies apply to purely flat surfaces only. Flat areas within a variable height surface are not recognised. The minor discrepancies in the flatness of a surface is controlled by a **Flat Tolerance** value.

- 4 Select File Delete All and Tools Reset Forms.
- 5 From the Main menu, select File Open Project:
-\PowerMill_Data\Projects\FlatFinish_Start
- 6 Select File Save Project As:
-\COURSEWORK\PowerMill-Projects\FlatFinish-Example1


Offset Flat Finishing

- 7 In the PowerMill explorer, Activate the Toolpath D16TR3-RGH1.
- 8 Activate the Dia 16 End Mill (EM16) Tool.
- 9 De-Activate Boundary 1.
- 10 From the main toolbar, select Toolpath Strategies and from Finishing open an Offset Flat Finishing strategy.




11 Select **Calculate** and when completed, **Close** the dialog.






The imported **Project** contains both an **Offset Area Clear** roughing strategy and an **Optimised Constant Z** finishing strategy. It is recommended that **Offset Flats** (**EM16-OffsetFlats-FIN1**) is run directly after the **3D Area Clearance** (**D16t3-RGH1**). For this reason, it is necessary to move it up the toolpath order in the **PowerMill** *explorer*.

12 In the PowerMill explorer, hold the left mouse key down on the toolpath EM16-OffsetFlats-FIN1 while dragging and releasing it onto D16TR3-RGH1.



13 Perform a **ViewMILL** simulation on all 3 toolpaths to check that the **Toolpath** order is acceptable.




The **ViewMILL** simulation after the **Offset Flat Finishing** strategy is shown above.




Raster Flat Finishing

1 From the main toolbar, select Toolpath Strategies and from Finishing open a Raster Flat Finishing strategy.



2 Using the above settings, select calculate and when completed, Close the dialog.



3 From the main menu select File - Save Project to update:-


.....\COURSEWORK\PowerMill-Projects\FlatFinish-Example1



Flat Machining example

- 4 Select File Delete All and Tools Reset Forms.
- 5 Select File Import Model:-


.....\PowerMill_Data\Models\Flats.dgk



6 Save the Project as:-

.....\COURSEWORK\PowerMill_Projects\FlatFinishing-Example2


- 7 Create a 20mm diameter End Mill tool named EM20.
- 8 Calculate the (default) **Block** and then **Calculate** the **Rapid Move Heights**.
- 9 Open an Offset Flat Finishing strategy and:-




- a Name the toolpath EM20-FlatFin.
- **b** Untick the **Rest machining** box.
- Click the use Axial Thickness button and enter separate Thickness values for Radial 0.5 and Axial 0
- d Calculate to process the toolpath and then Close the dialog.



Most of the **Flat** areas are finish machined, apart from the gap between the Upstands and inside the holes due to the **20mm** diameter tool being too large. We will now use a smaller tool to **Rest** machine these areas.




- 10 Create a Dia 10 End Mill, named EM10.
- 11 Activate the **Toolpath**, **EM20-FlatFin** and then select **Settings**.
- 12 Click to create a copy of the strategy.
- 13 In the main **Offset flat finishing** page of the strategy dialog:



- a Enter Toolpath name as EM10-FlatFinRest.
- b Enter Stepover as 3.0
- c Activate the EM10 tool.
- d Tick the **Rest machining** box.




14 Select the **Rest** page, and input the reference Toolpath as **EM20-FlatFin**.



15 Calculate the toolpath and when created, **Close** the dialog.

The final finishing passes at the base of the holes and the area behind the boss are now created:



16 From the main menu select File - Save Project to update:-

.....\COURSEWORK\FlatFinishing-Example2




Surface Finishing Example 1

The **Surface Finishing** strategy creates tool tracks that follow the natural, **surface curves** on a single, selected, **Surface**.




The tool tracks in a **Surface Finishing** strategy will not run parallel to the edges of a trimmed, surface.

- 1 From the main menu, select File Delete All and Tools Reset Forms.
- 2 Open the read-only Project:-
 -\PowerMill_Data\Projects\EditToolpaths_3
- 3 From the main menu , select File Save Project As:
-\COURSEWORK\PowerMill-Projects\PunchForm 3



4 Activate the toolpath **D10TR1-FIN1** to reinstate all the original settings.


All you need from the original settings is the original; **Active Workplane**, **Block**, **Rapid Move Heights**, and the *Tiprad tool* named **D10TR1**.




- 5 De-Activate both the **Toolpath D10TR1-FIN1**, and **Boundary 1**.
- 6 Select the *upper surface* on the punch model (as displayed above).



7 Open a **Surface Finishing** strategy and enter values as shown below.




8 Select the Pattern page:




- a Set Pattern direction U
- b Un-tick Spiral, and then select Ordering Two way
- Select Start corner Min U max V
- 9 Select the **Preview** tab to display the **Pattern** along its start point (arrow)
- 10 Select Calculate to create the toolpath and then Close the dialog.





- 11 From the main toolbar, click the **Leads and Links** button.
- 12 On the **Links** page:




- In 1st choice select Circular arc and then tick Apply constraints with a
 Distance < 3.0
- b Select 2nd choice Skim
- c Select **Default Incremental**
- **13 Apply** the dialog to update the active toolpath.






Where the **Link** move from the end of a tool track to the start of the next is within 3 mm, an (orange) arc move will be applied.



In the resultant toolpath, the natural order of the tool tracks and link moves across the 2 narrow areas is not very efficient.

This can be fixed by applying suitable **toolpath**, **Edit - Reorder** options.

- 14 Right-click on the **toolpath** and from the local menu, select **Edit Reorder**.
- 15 In the **Toolpath Listing** dialog, click **the Automatic reorder and reverse** button.




The toolpath follows the curves of the selected surface.



The illustrated toolpath is created with a **1 mm Stepover** to help with visualisation. It has also been edited using the **Automatic Reorder and Reverse** option to eliminate as many air moves as possible.

To further improve the efficiency of this strategy, several of the tool tracks on the upper flat area can be deleted to take advantage of using a bigger **Stepover** for the **Dia 10 mm** flat area of the active **Tool**.

- 16 From the **main** menu, select **Draw** > **Cursor** > **Tool** to provide a visual guide when selecting a suitable number of tool tracks.
- 17 Using the **Shift key** and **left mouse key** select groups tool tracks leaving a single pass within the tool diameter range, outside each set as shown below:




The **Tool** outline is displayed above to visualise suitable **Stepover** (**Draw** > **Cursor** > **Tool**).



If it is necessary to de-select tool tracks form the current selection use the **Ctrl Key** and **left mouse key**.

- **18** Right-click the toolpath and select **Edit** > **Delete Selected Components** to remove the selected tool tracks.
- 19 In the Links dialog change the 1st choice (with Apply constraints still ticked) to Distance < 15 before selecting Apply.



20 From the main menu select File > Save Project to update:-

.....\COURSEWORK\PowerMill-Projects\PunchForm 3




Toolpath Z-Limits

All **Toolpath** types, except drilling, can now be limited to applied maximum and minimum **Z** values within the defined **Block**.


- 1 From the main menus, select File Delete All and Tools Reset Forms.
- 2 Open the read-only Project:-

.....\PowerMill_Data\Projects\Zlimits-Start



3 Save Project As:-

.....\COURSEWORK\Zlimits-EX1




The **Project** already contains **8 Toolpaths**, 6 of which have been put in a **subfolder** named **OP1**. The 2 remaining **Toolpaths** require modification as they are both duplicating areas already included in other strategies. This will become evident during a **ViewMILL** simulation.




- 4 Activate the toolpath **D20TR3-ConstantZ-FIN1** to reinstate the original **Block** and settings.
- 5 Run a ViewMILL simulation on the existing NC Program OP1.







The **angled face** and **lower recesses** have yet to be finish machined. The 2 remaining toolpaths both operate over the full extent of the **Block**.



D20TR3-ConstZ-FIN1 needs to be localised to operate down the **angled face** to the top of the lower recesses.

BN8-OptConstZ-FIN1 needs to be localised to operate inside the 2 **lower recesses**.

This will easily be achieved for both toolpaths within the strategy dialog using the **Z-Limits** option.






7 Return to the **PowerMill** (**No Image**) view and disconnect **ViewMILL**

from the simulation (Switch the *Green* Sphere to *Red*).




8 In the PowerMill explorer, right mouse click on the toolpath D20TR3-ConstZ-FIN1 and from the local menu, select Activate followed by Settings to open the strategy dialog.



9 Select **Recycle** followed by the **Limit** page and **tick** both the **Maximum** and **Minimum** boxes.








11 Snap the *key-point* (shown above) at the top corner of the angled face to collect and insert the value **-11.82394**.






12 For The Minimum select Pick the lowest Z Value option.



- 13 Snap the **key-point** (shown above) on the top of the flat area to collect and insert the value **-40**.
- 14 Back in the dialog select **Calculate** to re-process the updated **Constant Z** finishing strategy and then **Close** the dialog.
- 15 In the PowerMill explorer, right mouse click on the toolpath BN8-OptConstZ-FIN1 and from the local menu, select Activate followed by Settings to open the strategy dialog.
- 16 Select **Recycle** followed by the **Limit** page and this time tick just the Maximum box.




- 17 Input the value -40.02 in the Maximum box.
- 18 Back in the main form select Calculate to re-process the updated Optimised Constant Z finishing strategy and then Close the dialog.





19 Re-connect **ViewMILL** and continue the simulation with the 2 updated toolpaths; **D20tR3-ConstZ-FIN1** followed by **BN8-OptConstZ-FIN1**.



The Component is now fully machined.

20 Select File - Save Project to update:-

.....\COURSEWORK\PowerMill_Projects\Zlimits-EX1



Toolpath Processing Options

Calculate

When all the settings and values are input ready to create a toolpath, the Calculate button can be clicked to start the toolpath calculation process.






You cannot use other PowerMill options while the toolpaths are being calculated.

Queue

If the **Queue** option is applied the user can continue working in **PowerMill** while the toolpath is processed in the background. Several strategies can be put in the queue to be calculated sequentially in the background.

To **Queue** a toolpath for calculation, you can, either:

- Click the Queue button in a strategy dialog, or,
- Right-click on a toolpath and select Queue from the local menu.





The 'Calculator' symbol changes to the 'Queue' symbol while the toolpath is being processed.


Batch Process

Once all data has been entered into a strategy dialog, click the **OK** button to save the settings and close as an un-processed toolpath.

You can save one or more un-processed, machining strategies to be sequentially calculated at a later time.

To **Batch Process** toolpaths, right-click a toolpath and select **Batch Process**.






Toolpath Processing Queue

The **Toolpath** - **Queue** option allows you to continue working in **PowerMill** while one or more toolpaths are processed in the background in sequential order.

The following 'start up' **Project** contains two unprocessed toolpaths. The dialog for each one will be opened in turn, but **Queue** will be used instead of **Calculate**. This enables you to continue to work on a new **Corner finishing** strategy while the original toolpaths are being processed in the background.

- 1 Select File Delete All and Tools Reset Forms.
- 2 Select File Open Project:

.....\PowerMill_Data\Projects\ToolpathProcessing-start





3 Select File - Save Project As:

.....\COURSEWORK\PowerMill-Projects\ToolQueue-ex1


- 4 In the **PowerMill explorer**, right-click the toolpath named **D25t3-rgh** and select **Queue**.
- 5 Repeat this on the toolpath named **BN16-fin1**.








- 6 While the original toolpaths are being processed in the background, activate the tool BN6.
- 7 Open a Corner Finishing strategy and set the Strategy to Along. Enter the other values exactly as shown below.



8 Select the Corner detection page and select the Reference tool as BN16




9 Click Calculate to process the toolpath and then Close the dialog.



The latest **Corner Finishing** strategy starts processing immediately and is likely to be completed before the **Steep and Shallow finishing** strategy currently pending in the **Queue**.



When a toolpath is added to the **Queue**, and is in an unprocessed status, the **Calculator symbol** on the toolpath in the **PowerMill explorer** changes to the **Queue** symbol .



10 Select File - Save Project to update:

 $...... \\ COURSEWORK \\ PowerMill-Projects \\ \\ Tool Queue-ex1$




5. Toolpath Leads & Links

If a tool is allowed to start machining directly at the start of a tool track, it first plunges down into the remaining stock, and then suddenly changes direction to run along the tool track. This is likely to result in machining marks, vibration, and excess wear on both the tool and machinery.

To avoid sudden loading on the tool, appropriate **Lead** moves (at cutting feedrate) on and off tool tracks can be applied.

Air moves (**Link**) between individual tool tracks can add significant amount of extra time to a machining operation. This can be greatly reduced by applying alternative, **Link** move options.



Default Leads and Links

Click on the main toolbar to display the **Leads and Links** dialog and options. You can also access the **Leads and Links** dialog from within a strategy dialog. Note that **Leads and Links** can be retrospectively applied to an existing toolpath.

Links using Skim

Skim - Provides variable control of rapid move heights within a component. These operate in conjunction with **Moves and clearances** settings to minimise slow and unnecessary air moves while machining the component form.

Moves and clearances – In this dialog incremental **Clearances** can be input where rapid feed moves occur from the end of one tool track to the start of the next. The tool traverses at a high feed rate across the model, clearing the highest point along its route by the defined **Axial clearance** value (Note **Radial clearance** is also available).

Incremental Plunge distance – An incremental distance above the component form where a downward *rapid* movement of a tool switches to a *plunge feed* move.




Lead In/Lead out Moves

Lead In controls the tool movement onto the start of a tool track and **Lead Out** controls the movement away from the end of a tool track.

Available Lead In and Lead Out moves are:

- None
- Surface normal arc
- Vertical Arc
- Horizontal Arc
- Horizontal Arc Left
- Horizontal Arc Right
- Extended Move
- Boxed
- Straight
- Ramp
- Pocket centre



In the above illustration:-

- 1 Lead In = Vertical Arc
- ② Lead Out = Vertical Arc
- ③ Link move = Skim

Toolpath colour codes:

- Purple Rapid Skim Feed Rate G1
- Pale Blue Plunging Feed Rate G1
- Green/Orange Cutting and Lead Move Feed Rates G1
- Dotted Red Full Rapid G0

Leads and Links are effectively extensions to tool tracks and must be gouge protected. **Gouge check** is set as default and any **Lead** that would otherwise result in a gouge is not created.

On tooltracks where the **1st Choice** cannot be applied, then the **2nd Choice** is used. If it is not possible to apply either then the **Lead** options are applied as **None**.




Example

The following example illustrates the retrospective addition of suitable Leads and Links to finishing toolpaths. The project contains one Roughing toolpath and three Finishing toolpaths.

- 1 Select File Delete All and Tools Reset Forms.
- 2 Select File Open Project:

...\PowerMill_Data\Projects\LeadsLinks-Start




3 Select File - Save Project As:


.....\COURSEWORK\PowerMill-Projects\LeadsLinks-example

4 Select an **ISO2** view.



5 Activate the toolpath, **BN6-fin1**.









Vertical Arc Leads

Vertical Arc - Leads create a circular movement downward at the start and upward at the end of each individual tool track. By default, with the Gouge check option selected, the additional moves are not made if a gouge might occur.




- 1 Toolpath segment
- 2 Radius
- 3 Tangent angle
- 4 Lead
- 6 On the main toolbar, click to open the **Toolpath connections** dialog and the **Lead In** page will be open as the default.



- From the 1st choice list select Vertical arc.
- Enter an Angle of 90.0 and a Radius of 6.0
- 7 Click Apply.



There is now a **Vertical arc** leading onto most of the tool tracks.




The new (gouge protected) **Vertical** leads have not been created on the tool tracks that stop close to a raised area of the model.

8 From below the **2nd choice** options click the **Copy to Lead Out** button.




9 Click **Apply** to update the active toolpath.




If gouge free, a **Lead Out** move is applied at the end of each tool track.





- 10 Select Vertical arc from the 2nd choice list.
 - a Enter an Angle of 90.0 and this time a reduced value Radius of 4.0
 - **b** Click the **Copy to Lead Out** button.
- 11 Click Apply.



Wherever it is gouge free on the above toolpath the **1st choice** of **Lead In/Out** with a **Vertical arc** is attempted.

If this is not possible without a gouge occurring, then the **2nd choice** of a **Radius 4**, **Vertical arc** is attempted.


If neither the **1st** or **2nd choice** is possible without a gouge occurring, then no **Lead In/Out** is applied to that part of the toolpath.



Links

A **Link** move is the movement of the tool from the end of a tool track to the start of the next. For efficient tool moves across the model, you can reduce the height of the link moves to be closer to the local model form.


- Apply constraints This allows the user to define the distance within which the 1st or 2nd choice toolpath Links apply.
- For 1st choice, the available options include Safe, Incremental, Skim, On Surface, Stepdown, Straight, and Circular arc.
- For 2nd choice, the available options include Safe, Incremental, and Skim.
- For Default (first and last links) the available options include Safe,
 Incremental, and Skim.
- 1 Activate the toolpath BN6-fin1.
- 2 Click and open the Toolpath connections dialog.
- 3 Select the **Moves and clearances** tab to view the default settings for the **Axial** and **Incremental plunge distance** options.



- **Skim** occurs at an incremental height **Axial clearance** (default **5**) for the tool to locally clear the highest point on the model between tool tracks.
- Rapid plunge moves change to Plunge Feed Rate at the incremental plunge distance (default 5) above the local, model surface.




4 Select the **Links** tab.



5 Select 1st choice as Circular arc, tick the Apply constraints box, and input Distance < 3</p>

Link moves with a distance of less than the **3** threshold will use the **1st choice** options and those greater will use the **2nd choice** options.


6 Click Apply.



In some areas of the toolpath the distance between the ends of adjacent tool track **leads** are is greater than the **3** threshold value (In these instances **Skim** moves apply instead of **Circular arcs**).

- 7 For the **1st choice** constraints increase the threshold value to **8**.
- 8 Click Apply.








By increasing the value of the constraints **threshold distance** to **8**, the number of occurrences of 1st choice - Circular arc links has increased.


The above **1st choice** circular arc **Links** do not need to occur at the ends of the existing **Vertical Lead** moves. For the **1st choice Links** it will be far more efficient if the **Vertical arc**, **Lead** moves are completely removed.

- 9 Open the **Lead in** page.
- 10 For both 1st choice and 2nd choice tick Apply constraints with Distance > 8



11 Click Apply.





The **Vertical arc** Lead moves exist on the **2nd** choice (long) links but not on the **1st** choice (short) links.

12 Select File - Save Project to update.


.....\COURSEWORK\PowerMill-Projects\LeadsLinks-example



Do not close the **Project** yet as it will be continued in the next section.

Horizontal Arc Leads


This type of **Lead** is frequently applied where the tool tracks run parallel along steep areas of a component.




- 1 Toolpath segment
- 2 Radius
- 3 Lead
- 4 Tangent angle



- 13 From the main menu, select **Tools Reset Forms** to return the **Leads and Links** settings to default.
- 14 In the **PowerMill** *explorer*, right-click the **BN6-fin2 toolpath** and select **Activate**.
- 15 Select an **ISO1** view.
- 16 Click and open the **Toolpath connections** dialog.



- 17 Select the Lead In tab, and set the 1st Choice to Horizontal arc with an Angle of 45 and a Radius of 5.
- 18 Click Copy to Lead Out and then Apply.






There is no need to utilise the **2nd choice** options as the **1st Choice** of **Horizontal arc** - **Leads In/Out** have appeared on all of the tool tracks.




19 In the Lead in page 1st Choice, input a Linear move of 5 and select Apply.




Extensions

Extensions are additional lead options that are applied outside of the existing **Lead In/Out** moves.

- 20 Select an ISO 4 view.
- 21 In the **Toolpath connections** dialog, select the **Lead in** page, and locate the **Lead in extension** area.
- 22 For the Lead in extension use a Vertical arc with Angle 90.0 and Radius 6.0



23 Click on the *Copy to outward extension* icon and Click **Apply**.




A Vertical Arc - Extension is added to all of the Lead In/Out moves.




Exercise

- 1 From the main menu, select **Tools Reset Forms** to return the **Leads and Links** settings to default.
- 2 Activate the **BN6-fin3** toolpath and **Apply** the following **Leads and Links**:
 - c Links: 1st choice/2nd choice/Default Skim.
 - d Lead in: 1st Choice Ramp using the Ramp Options , Follow
 Toolpath, Max Zig Angle 4, and Ramp height using Type Incremental
 at a Height of 1.
 - e Lead out: 1st Choice Vertical Arc with Angle 90 and Radius 3



The **Links** have been visually removed to enable a clearer view of the **Leads**.

- 3 In the **Leads and Links** dialog select the **Lead in** page and input **0.5** in the box named **Overlap distance** (Located in the lower right corner of the dialog).
- 4 Apply the Toolpath connections dialog.



Overlap Distance causes the cutter to continue beyond the natural end point along the original toolpath by a specified distance based on the Tool Diameter (TDU). In this case the distance is 3mm (0.5 TDU).

5 Select File - Save Project to update.

.....\COURSEWORK\PowerMill-Projects\LeadsLinks-example




Arc fit rapid moves

Leads and Links

This is ideal for applications where you want to avoid all sharp changes of direction including the none machining part of the link moves. **Arc fit rapid moves** applies to both **Rapid** and **Skim** moves



Not all machine tool controllers will support this option.



- The Arc Fit Rapid Moves option is located in the Toolpath connections dialog
 Moves and clearances page.
- The Arc fit rapid moves box must be ticked.
- The **Arc radius** is a proportion of the active, Tool Diameter (TDU).

Other Information for Toolpath connections



Toolpath connections options such as **Leads** and **Links** can be applied independently to one or more selected **Link** moves.



The very first downward move onto a toolpath will default to use a **Plunge feed rate** all the way from the absolute **Plunge Height**. To make this work incrementally relative to the model open the **Start and end point** page and tick the **Incremental plunge** box.




6. Boundaries

A **Boundary** consists of one or more closed wireframe segments. **Boundaries** are mainly used to limit machining strategies to specific areas of the component.

Earlier in the course, **Boundaries** were utilised to limit machining strategies, so that they occur in more compatible areas of the component.


For example, **Constant Z finishing** is more effective on steep sidewalls and Raster finishing on shallow areas.

There are several options available for creating boundaries. Most involve interaction with other **PowerMill** entities (eg **Tools**, **Thickness**, **Stock Model**, etc), while User Defined will access a separate dialog for direct input of existing geometric, entities.



Switch off the Private Boundaries creation option

- 1 From the main menu, select File Delete All and Tools Reset Forms.
- 2 From the main pulldown menus select Tools Options and in the dialog browse to Boundaries Private boundaries.




- 3 Un-tick the box named Allow new boundaries to be private.
- 4 Select Accept to close the Options dialog.



User Defined Boundary

To access the **User Defined** – **Boundary** options, go to the **PowerMill** *explorer*, and select **Boundaries** > **Create Boundary** > **User Defined**.

This will access a separate sub-menu in which the range of options, generally involve direct input of existing wireframe entities.



Insert File - Opens the browser to locate an externally stored geometry file.

The Boundary, Pattern, and Toolpath buttons are disabled unless a compatible entity is selected in the adjacent input box.



Model - Inserts the edge of the selected model.



Sketch - Opens the Curve Editor toolbar.




Composite curve - Opens the Create Composite Curve toolbar.

Wireframe Modelling - Provides access to the **PowerShape** wireframe constructor.


- 5 Select File Save Project As:
 -\COURSEWORK\PowerMill Projects\BoundaryBasics
- 6 Select File Import Model...

.....\PowerMill Data\Models\cowling.dgk






7 Select the surfaces defining the central pocket and fillet.



- 8 In the **PowerMill explorer**, right-click **Boundaries** and select **Create User Defined**.
- 9 In the User **Defined Boundary** dialog, click the **Model** button.




A **Boundary** segment is created around the edge of the selected part of the model.






10 Select a **View from top (Z)** and switch off the **shaded** view but retain the **wireframe** view.



- 11 In the **PowerMill** *explorer*, right-click **Boundaries** and select **Create Boundary User Defined**.
- 12 In the **User Defined Boundary** dialog, click the **Sketch** button open the **Curve Editor** toolbar.




- 13 On the **Curve Editor** toolbar, click the following button to open the **Options** dialog.
- 14 Un-tick Intelligent Cursor Snapping Options Use the Intelligent Cursor to enable 'free form' sketching.



- 15 Click **Accept** to keep the changes.
- 16 From the Curve Editor toolbar, select Create a Bezier curve
- 17 Using the left mouse key, click points within the model to sketch an oval shaped **Boundary**.








If required, use **Undo** to sequentially remove any invalid points.




While the **Intelligent cursor** is switched off do not attempt to close the segment by trying to snap the 'final span' back on to the start point.

- 18 On the **Curve Editor** toolbar click to open the **Options** dialog.
- 19 Select Intelligent Cursor Snapping Options and tick Use Intelligent Cursor.
- 20 Then snap the final span of the **Bezier Curve** onto the original start point.
- 21 On the **Curve Editor** toolbar click to accept the changes and close the session.
- 22 If the **Boundary** segment is not smooth enough, right mouse click on it and from the local menu, select **Edit Spline Selected** to open the **Spline** fitting tolerance dialog.



23 Enter the value 2 and click 1 to apply and close the dialog.



The **Boundary** segment is splined through the polyline points as a curve maintaining the original form to within a maximum deviation of 2.


In instances where the required deviation would be greater than 2, a tangency will remain either side of the affected points.




Selected Surface Boundary

A **Selected Surface Boundary** defines one or more segments around where the active tool would fully machine the selected surfaces. The segments represent the tip position of the active tool.

- 1 Create a Block Defined by Box using Type Model.
- 2 Create a **Ball Nosed** tool of diameter **16** with the Name **BN16**.
- 3 Select the **surfaces** defining the central pocket, including the fillet.



4 In the **PowerMill** *explorer*, right-click **Boundaries** and select **Create Boundary** - **Selected Surface**.




5 Using the above settings, click Apply to create a single segment, Selected Surface Boundary.



Shallow Boundary

A **Shallow Boundary** defines one or more segments where the model drops through a specified **Upper Angle** downwards from the horizontal plane. It is designed to differentiate steep and shallow areas allowing appropriate machining strategies to be applied where they are most effective. The **boundary** is calculated relative to the active **Tool** and **Thickness** parameters.

In the **PowerMill** *explorer*, right-click on **Boundaries** and using the default settings, **Create Boundary** - **Shallow**.




- ① **Shallow** area more suited to **Raster Finishing** (above 30 degrees).
- ② **Steep** area more suited to a **Constant Z** Finishing (below 30 degrees).
- 7 **Apply** the form to create the above **Boundary** segments.

Silhouette Boundary

A **Silhouette Boundary** defines the outline around the maximum dimensions selected model, offset by the tool radius.

1 Select the following surfaces on the model:






Use the Shift key on your keyboard to select multiple surfaces.



- 2 Right-click the Model and select Edit Delete Selected Components.
- With the selected areas now deleted, in the **PowerMill explorer**, right-click **Boundaries** and select **Create Boundary Silhouette**.




Rest Boundary

A **Rest Boundary** defines the area inaccessible to a specified reference tool. It also requires a smaller active tool to be specified otherwise it will not generate segments.


- 1 Create a **Ball Nosed** tool of diameter **8** with the **Name BN8**.
- 2 In the **PowerMill** *explorer*, right-click **Models** and select **Delete All** to remove the incomplete component.
- 3 Import the original Model back into the Project:

.....\PowerMill Data\Models\cowling





4 In the **PowerMill** *explorer*, right-click **Boundaries** and select **Create Boundary** - **Rest** to open the **Rest Boundary** dialog.




- 5 Input Expand Area 0, select Tool BN8, and Reference Tool BN16.
- 6 Set with Limit tool centre to block edge.



- 7 Click Apply to create the following Rest Boundary.
- 8 Click Accept to close the dialog.
- 9 Save the Project to update:-

.....\COURSEWORK\PowerMill Projects\BoundaryBasics

10 Select a **View from top** and un-draw the model.



The above **Boundary** identifies areas on the component that are inaccessible to the **BN16** tool geometry to be locally machined with the **BN8** tool.


On closer inspection, the central pocket area would be more effectively machined with a flat bottomed tool and a smoother, more continuous toolpath, can be created if the 2 spurs are removed from the outer segment (to be machined later as a separate toolpath).



Editing Boundaries

It is often necessary to edit the original geometry defined by **Boundary** segments. The best way to achieve this in **PowerMill** is via the dedicated **Curve Editor** tool. As it is not exclusive to **Boundaries**, a more detailed range of **Curve Editor**, options and applications are covered in chapter 11.

- 1 In the **PowerMill** explorer, right-click the **Rest Boundary** (6) entity and in the local menu select **Edit Copy Boundary** to create a copy named (6_1).
- 2 In the **PowerMill** *explorer*, right-click the original **Rest Boundary** (6) and Rename it as **Master**.
- 3 Rename the new copy of the **Rest Boundary** (**6_1**) as **Rest**.
- 4 Activate the **Boundary** named **Rest**.
- 5 Select the 2 inner segments on the **Rest boundary** (**Rest**) by dragging a box over them, and then press the **Delete** key on your keyboard to delete them.



The next stage will be to Offset the **Boundary** and then remove the two spurs, which will be carried out after an explanation of the **Boundary Editor** dialog.

Boundary – Access to the Curve Editor

Once created, you can modify a **Boundary segment** using the options available on the **Boundary** toolbar.



6 Click on the **Boundary** toolbar to activate the **Curve Editor** toolbar.



You can also double-click a **boundary** segment to activate the **Curve Editor** Toolbar.




Edit > Transform


- 7 In the PowerMill explorer, right-click on the boundary Rest and from the local menu, select Curve Editor.
- 8 In the **Curve Editor** toolbar select the **Offset** option



9 In the Offset toolbar, select the 3D Smooth button, input a Distance of 1 and then press the Return key.



10 Click in the **Curve Editor** toolbar to accept the changes and exit.






Curve Point - editing


The Point editing options are located towards the right hand side of the Curve Editor toolbar.

- 1 In the PowerMill explorer, right-click **Boundaries** and from the local menu select **Toolbar**.
- 2 On the Boundary toolbar, click the Curve Editor button to display the Curve Editor toolbar.
- 3 Select (Left click) the outer **boundary segment** in the graphics area.



The points are displayed on the selected boundary segment.

Zoom into the area of the selected segment and select all the points that define the spur.






To select multiple points, hold down the **Shift key** while individually selecting or dragging across the points with the mouse.

on the **Curve Editor** toolbar, click **Delete** points to remove the spur from the segment.

6 Repeat the procedure on the other spur.






7 Click , to accept changes and exit the **Curve Editor**.

Other boundary editing options


Right-click on a **Boundary** in the graphics area or in the **PowerMill** explorer and from the local menu, select **Edit** to view other boundary editing options.






Review the modified Boundary

8 In the **PowerMill** *explorer*, click the light bulb next to the copy of the original boundary **Master** created earlier. The original boundary is displayed alongside the edited **boundary**, **Rest** illustrating the effect of the 1mm 3D Offset.




Create a 3D Offset strategy limited to the modified Boundary

- 9 Activate the BN8 tool and Boundary named Rest.
- 10 On the main toolbar, click to display the **Strategy Selector**.
- 11 From the **Finishing** options, select the **3D Offset Finishing** strategy dialog and enter the data as shown below.




12 Click **Calculate** to process the toolpath and then **Close** to exit the dialog.





Create a Boundary for the original side branches.

- 13 Undraw the **Toolpath** BN8-FIN1 and **Boundary** Rest by switching off the respective light bulb symbols in the **PowerMill** explorer.
- 14 Switch on the respective light bulb to display the **Boundary** named **Master**.
- 15 In the graphics area, select the **outer segment** of the displayed **Boundary**.
- 16 In the PowerMill explorer, right-click the Boundary Master and select Edit Copy Boundary (selected only) to create a new boundary Master_1 consisting of the outer segment only.
- 17 Rename the boundary Master_1 as Spur1.
- 18 Select a view from top Z.
- 19 In the **PowerMill** *explorer*, turn off the light bulb adjacent to the *boundary* **Master** to remove it from view.



- 20 In the PowerMill explorer, right-click the boundary Spur1 and select Activate.
- 21 In the graphics area, double-click the **boundary segment** to activate the **Curve Editor** toolbar.
- 22 Select all **points** along the **boundary segment** except those which define the rectangular part of the upper spur.






Use the **Shift** key on your keyboard to select multiple points on the boundary segment.



Use the **CTRL** key on your keyboard to deselect one or more of the selected points on the boundary segment.





If preferred it is okay to select and delete the points in stages.

23 On the Curve Editor toolbar:




24 Click the **Delete Points** button points.

to delete all the selected

- 25 Select the **points** along the base of the rectangular segment.
- 26 On the status bar (below the graphics area), click the **Relative Move** button and enter **0 -2** (for the X and Y move, values) in the data box and press **Return** on your keyboard.




The selected points are moved by a distance of Y-2.



- 27 Click to exit the **Curve Editor** toolbar.
- 28 Click the light bulbs on to display both **boundaries** Rest and Spur1, and then Resize the View






- 29 In the graphics area, double-click the boundary Spur1 to activate the Curve Editor toolbar.
- 30 From the **Curve editor** toolbar, select the **Transformations Mirror** option
- 31 On the Mirror toolbar select Origin at the active workplane.



32 Ensure that the **Keep Original** option is set.




- 33 From the Mirror toolbar, click the Mirror in ZX button
- 34 Click on the Mirror toolbar to accept and close.
- **35** On the **Boundary Transform** toolbar, click to accept and exit the toolbar.




The Boundary named Spur1 now contains 2 segments.

- 36 Make sure that the *tool* BN8 and *boundary* Spur1 are both Active.
- **37** From the **Strategy Selector**, **Finishing** options, select the **Raster Finishing** strategy and enter data as shown on the following page:






38 Click Calculate to process the toolpath, and then Close the dialog.



The machining strategies are localised with the help of edited **Boundaries** originating from the original **Rest Boundary (Master)**.





39 Save the Project to update:-

.....\COURSEWORK\PowerMill Projects\BoundaryBasics

Creating Blanking Surfaces using Boundaries

Blanking surfaces are used to cap holes and pockets in a model to prevent the tool from machining into those areas. You can create three types of planes in **PowerMill**.

- Block creates a plane, at a specific Z Height, after the material block is defined.
- Best Fit Provides the options to create two planes, one touching the boundary at its highest point, and the other through its lowest point. The planes are parallel to the best fit plane (the plane that has the smallest maximum distance from the boundary).
- **Projected** creates a plane parallel to the XY axis of the active workplane. The plane will have the Z Height of the highest point of the boundary.



Example


- 1 Select File Delete All and Tools Reset Forms.
- 2 Import the Model:

.....\PowerMill Data\Models\pockets.dgk

3 Calculate the Block defined by Box to the Model Min/Max limits.




- 4 Select the top surface of the **model** (shown shaded).
- In the **PowerMill** *explorer*, right mouse click on **Boundaries** and from the local menu select **Create Boundary User Defined**.





- 6 Click the **Model** icon and then select **Accept** to close the dialog.
- 7 Un-draw the model to provide a clear view of the boundary.
 The Boundary produced has 4 segments. For this example, only the two smallest segments are required.
- 8 Select the two highlighted segments by dragging the cursor over them.





- 9 In the **PowerMill** *explorer*, right-click **Models** and from the local menu select **Create Plane Projected**.
- 10 Switch on the Plain Shade model option.





No need to Save the Project this time!

12 Select File - Delete All and Tools - Reset Forms.




Exercise

1 Import the Model:-

 $.... \backslash PowerMill_Data \backslash Models \backslash bucket.dgk$

2 Create 4 surface planes to cover the foot recesses on the upper base surface.





No need to Save the Project this time!




Block defined by Boundary

An existing Project will be opened that contains multiple components that will be roughed out using a complex Block arrangement defined by Boundary segments.

- 1 Select File Delete All and Tools Reset Forms.
- 2 Open the (read-only) Project:-

 $.... \backslash PowerMill_Data \backslash Projects \backslash MultiBlock_Start$



3 Save the Project as:-

....\COURSEWORK\PowerMill Projects\MultiPart Block

- 4 Select all of the component models (Drag a box over all surfaces).
- 5 In the **PowerMill** *explorer* right mouse click on **Boundaries** and from the local menu select **Create Boundary User Defined**.
- 6 In the User Defined Boundary dialog ensure that the Allow Boundary to be

private box is un-ticked and then click on the Model icon




- 7 Select Accept to close the User Defined Boundary dialog.
- 8 Activate the new Boundary.




- 9 From the main toolbar select the **Block** options
- 10 In the dialog select *Defined by* Boundary and *Type* Model followed by Calculate.






11 Select **Accept** to close the **Block** dialog.



The complex **Block** is as shown above consisting of localised triangle models around each individual component.




- **12** De-activate the **Boundary**.
- 13 In the PowerMill explorer right mouse click on the existing, un-processed toolpath D12TR1-RGH1 and from the local menu select Edit Set Named Parameter.




Input **Block** and select the *green tick* to accept.

- 14 The current **Block** definition will now be active in the unprocessed **Model Area Clearance** strategy.
- 15 In the **PowerMill** *explorer* right mouse click on **Toolpaths** and from the local menu select **Batch Process**.



Batch Process will sequentially calculate all valid, un-processed strategies.



16 Select File - Save Project to update:-

...\COURSEWORK\PowerMill Projects\MultiPart Block



Private Boundaries


All **Boundary** types will (by default) be created as **private**. This makes the **Boundary** exclusively owned by the machining strategy that it is first applied to. If the parameters or entities used in the strategy are modified, then the associated **private boundary** will automatically match these on calculation.

Private Boundaries are of particular use in **Templates** as they will automatically regenerate when the host toolpath is **calculated** on a new model.

A **private boundary** is not suitable in cases where the segments will need to be deleted or geometrically edited once assigned to the host strategy. It is however possible to create a copy on which you can switch off the **Allow boundary to be private** option within the dialog.

It is also possible to prevent Boundaries from being created as private:-


From the main pull down menus select **Tools** – **Options** – **Boundaries** - **Private Boundaries**, and un-tick **Allow new boundaries to be private**.



Private Boundaries – Example:-

- 1 Select File Delete All and Tools Reset Forms.
- 2 Open the (readonly) Project:-

.....\PowerMill Data\Projects\PrivateBoundaries Start



3 Save Project As:-

.....\COURSEWORK\PowerMill_Projects\PrivateBoundaries-EX1




The **Project** includes a **Constant Z** and a **3DOffset** *finishing* toolpaths both of which currently apply over the whole of the **Block** area. To localise the 2 finishing toolpaths to areas of the model where they are most effective both strategies will be recycled to include a **Shallow** – *private boundary*.


4 From the main pulldown menus select **Tools** - **Options** - **Boundaries** - **Private boundaries**:-

Allow new boundaries to be private 🔽

- 5 Tick the box named **Allow new boundaries to be private**.
- 6 Select **Accept** to close the **Options** dialog.
- 7 Activate the toolpath, BN10-CZ-SEM1.
- 8 From the toolpath, BN10-CZ-SEM1 local menu select Settings, followed by the Recycle option.
- 9 In the Constant Z dialog select the Limit page.



10 From the **Boundary** pull down options select **Create a shallow boundary**.





11 Using the default settings Apply and Accept the Shallow Boundary dialog.




Initially the new **Boundary 1** will exist in the **PowerMill** *explorer* until the toolpath is calculated. At that point it will disappear (become invisible) from the **Boundary** folder. However, the folder name, **Boundary** will still be displayed in bold text to identify the existence of the hidden *private* **Boundary 1**




The **private** Boundary will be displayed in the **PowerMill explorer** if the above option is ticked in the local **Boundaries** menu.

12 Select the Limit page and set Trimming to Keep outside.



13 Calculate (but do not Close) the Constant Z Finishing strategy.




The **Constant Z strategy BN10-CZ-SEM1** is now limited to be outside the segments of **private Boundary 1**.




14 Select the 'create a copy' option



in the Constant Z Finishing dialog.




- 15 Modify the Toolpath Name to BN10-CZ-FIN1, input Tolerance 0.01, Thickness 0, and Minimum stepdown 0.3
- **16 Calculate** the new toolpath and **Close** the dialog.



17 A new *private* Boundary will automatically, be created with the same parameters (**Tolerance**, **Thickness**, etc) as used in the main page of the Constant Z Finishing dialog.




18 In the **PowerMill** *explorer*, right mouse click on **Boundaries** and from the local menu tick the option **Display private Boundaries**.



19 With the 2 existing *private* Boundaries displayed, right mouse click on either and from the local menu select Edit – Copy Boundary.




20 Right mouse click on **Boundaries** and from the local menu untick the option **Display private Boundaries**.



Only the new *private* **Boundary** will be displayed in the **PowerMill** *explorer* but will later become hidden once it has been applied in a new toolpath calculation.


Exercise

- 21 In the **PowerMill** *explorer*, activate the toolpath **BN10-3Doff-SEM1** and then select **Settings** to open the dialog.
- 22 Recycle with the new *private* Boundary 1_1_1 active, and with the *Trimming* set to Keep inside.






23 Calculate a copy of the above toolpath with the new Name BN10-3Doff-FIN1 and with Tolerance 0.01, Thickness 0, and Stepover 0.3



- 24 From the main pulldown menus select **Tools Options** and in the dialog select **Boundaries Private boundaries**.
- 25 Tick the box named **Display private boundaries** in the **explorer**.



This demonstrates that if a **toolpath** containing a **Private Boundary** is copied then the new one will contain a separate **Private Boundary**.





7. Levels and Sets

Levels and **Sets** allow you to control the selection and display of model components in the **PowerMill** graphics area.


You can **Acquire** components from the currently imported **Model** to a **Level** or **Set**. Once acquired you can select, de-select, display, or hide **Model** components by using the individual **Level** or **Set** context menus.

The subtle differences between **Levels** and **Sets** are illustrated in the following examples.

Creating Levels

- 1 From the Main menu, select File > Delete All and Tools > Reset Forms.
- 2 Select File > Import Model:

.....\PowerMill_Data\Models\CowlingWithClamps.dgk




The imported **Model** includes clamps, which:

- Must be avoided by all machining strategies created in the Project.
- Must not be included in the calculation of the Block.

To make the model selection easier, a new **Level** named **Clamps** will be created and all clamp surfaces assigned to it. Another **Level**, named **Splits** will be created and all 6 split surfaces assigned to it.

3 In the PowerMill explorer, right-click Levels and Sets and select Create Level.





4 Rename the new Level as Clamps.



5 Create another new Level and Rename it as Splits.



All model components are currently acquired to the default General Level.


If the original CAD model has components already assigned to different **Levels**, then this will still be the case when the **model** is imported into **PowerMill**.

Acquiring model entities to a Level

6 In the **PowerMill** *explorer*, click the 'light bulb' off next to the **Level** named *Clamps*.


Any items acquired to this level will no longer be displayed.

7 In the graphics area, use the *left mouse* and *Shift* keys to select all surfaces except the clamps.



8 On the keyboard select **Ctrl J** to **blank** the selected **Surfaces**.







- 9 Select the Clamp surfaces (Hold down the left hand mouse key while dragging a box over them).
- 10 In the PowerMill explorer, right-click on the level named Clamps and select Acquire Selected Model Geometry.

The clamps disappear from the view (The **Level** *Clamps* is switched off).

11 On the keyboard select **Ctrl L** to **unblank** all eligible **Surfaces**.



- 12 Select the 6 **Surfaces** defining the split face and **Acquire** them to the level named **Splits**.
- 13 Switch off the **level** named **Splits** to visually check that the correct **surfaces** have been acquired.




14 Switch on all levels (The clamps and split surfaces reappear).



A **Selected Surface Boundary** will now be created to **limit** the clamps from being machined.

- 1 Create a Dia 12 Ball Nose tool named BN12.
- 2 In the **PowerMill** *explorer*, right-click the **Level**, *General* and choose **Select Surfaces**. The main component **surfaces** excluding the split faces are selected.
- 3 While still in the PowerMill explorer, right-click the Splits level and choose Select Surfaces. The split face surfaces are added to the current selection.
- 4 Calculate a Block using the default Box and Model options.
- 5 Use the default Rapid Move Heights and Start and End Point options.



The **Block** is created to the dimensions of the selected surfaces.


- 6 Left mouse click in the graphics area away from the **model** to deselect all entities.
- 7 In the PowerMill explorer, click on the Level, General, and with the Ctrl key held down, click on the Splits level.


Both the selected **levels** will be highlighted in the **PowerMill** explorer.



- 8 Right-click on one of the highlighted levels and choose Select Surfaces. All surfaces excluding the clamps are selected.
- 9 Right mouse click on **Boundaries** in the **PowerMill** explorer.
- 10 From the local menu select Create Boundary Selected Surface Boundary with Radial Thickness 2, Limit set to Block Edge, with Allow boundary to be private un-ticked.









- 11 Check that both the **Tool BN12** and **Boundary 1** are **Active** so that they will be automatically included when a new machining strategy is created.
- 12 From the main toolbar, select **Toolpath Strategies** and from **Finishing** open a **Steep and Shallow Finishing** strategy.
- 13 In the **Steep and Shallow Finishing** dialog, enter data exactly as shown in the following illustration.





14 Click **Calculate** to process the **toolpath** and then **Close** the dialog.




The **Radial Thickness** of **2** used in the outer **Boundary** *segment* provides a suitable clearance around the clamps.




Switching Off a Level

15 In the **PowerMill** *explorer*, switch off the light bulbs on both the **General** and **Splits** levels.



Only the *Clamp* Surfaces are displayed in the graphics area.

- 16 Right-click the **toolpath** and select **Settings** to re-open the dialog.
- 17 Select create a *Copy* and click **Calculate** to process a new **toolpath**.
- 18 Close the Raster Finishing dialog.





Even if a **level** is switched off, **PowerMill** will still create a toolpath over all (including un-displayed) parts of the model.




Sets

A **Model** entity will always exist on a **Level** but not on more than one at the same time. You cannot delete a **Level** while **Model** entities are acquired to it.

A **Model** entity can co-exist on more than one **Set** at the same time. You can delete a **Set** while **Model** entities are acquired to it.

- 19 From the Main menu, click File > Delete All and Tools Reset Forms.
- 20 From the **Main** pulldown menus **File** > **Import Model** and select:


.....\PowerMill_Data\Models\YogurtTray.dgk



- 21 In the PowerMill explorer right mouse click on Levels and Sets.
- 22 From the local menu, select **Create Set** and rename it as **AllPkts-Set**.




23 Manually select all **surfaces** defining the 9 pockets.




24 With the 9 pockets still selected, right-click **AllPkts-Set** and select **Acquire Selected Model Geometry**.



25 Manually select all **surfaces** defining the bottom left pocket.



- 26 Create a new **Set** and rename it as **Pkt1-Set**.
- 27 Right-click Pkt1-Set and select Acquire Selected Model Geometry.
- 28 On the keyboard select Ctrl L to unblank all invisible Surfaces.
- 29 Switch off both the level *General* and the **Set** *Pkt1-Set*.
- 30 Switch on AllPkts-Set.



The **surfaces** currently acquired to **AllPkts-Set** are displayed, including those that exist on the visually 'switched off' **Set**.


31 Switch off the **Set** *AllPkts-Set* and then switch on the **Set** *Pkt1-Set*.




The **surfaces** acquired to **Pkt1-Set** are displayed. They are also displayed when the **AllPkts-Set** is switched on and **Pkt1-Set** is switched off. This illustrates that model entities can be acquired to more than one **Set** at the same time.



- 32 Switch off both **Sets** and switch on the **Level General**.
- 33 In the **PowerMill** *explorer* right-click on **Pkt1-Set** and from the local menu click **Select Surfaces**.




- 34 Create a new Level and rename it as Pkt1-Level.
- 35 Switch of the light bulb symbol next to the new Level Pkt1-Level.
- 36 In the PowerMill explorer, right-click Pkt1-Level and select Acquire Selected Model Geometry.



The **surfaces** defining the bottom left pocket disappear from the view on being acquired to the (switched off) **level Pkt1-Level**. This illustrates that unlike **Sets**, it is not possible for **model** entities to co-exist on more than one **Level** at any one time.

37 Switch on the **level Pkt1-Level** and the bottom left pocket surfaces are displayed again.







When using a combination of **Levels** and **Sets** it is good practice to keep the **Sets** visually switched off. If you want to select items from a particular **Set**, then, right-click on it and use one of the **Select** options from the context menu.




This prevents confusion if you switch a **Level** off only to find the included items are still visible due to a **Set** containing the same items being switched on.





8. Editing Toolpaths

There is a large selection of **Toolpath** editing options that can be applied retrospectively.



Many of the **Toolpath** editing options are accessed from the local menus (as shown above). Most of these edits will no longer apply if a **Toolpath** is subsequently recalculated.

Edit > Transform

The **Transform** option allows you to **Move**, **Rotate**, and **Mirror** toolpaths relative to the active datum.

To access the options right-click on a **toolpath** and select **Edit** > **Transform**.



Transform > **Move** - The **Move** function allows a selected toolpath to be moved by a user-defined **Distance** along a selected axis.





Transform > **Rotate** - The Rotate function allows the rotation of a selected toolpath by a user-defined **Angle** around a selected **X**, **Y**, or **Z** axis.



Transform > **Mirror** - This provides 3 options to **Mirror** a selected toolpath across the **XY**, **XZ**, or **YZ** planes. When a toolpath is mirrored, **PowerMill** identifies the gouge status as unknown, so it is advisable to check for gouges.


It is important to note that when a toolpath is mirrored, the cutting direction effectively becomes reversed.



In the following example a single toolpath is created and then the **Transform** > **Move** option applied to copy toolpaths into the remaining cavities.

- 1 Select File Delete All and Tools Reset Forms.
- 2 Open the read-only Project:-

.....\PowerMill_Data\Projects\EditToolpaths_1



The **Project** contains a multi-cavity die and a **Dia 10 Ball Nosed** tool.

A toolpath will be created in the lower left cavity that is limited to be inside a **Selected Surface** Boundary.


3 Save Project As:

.....\COURSEWORK\PowerMill-Projects\Transform


- 4 Create a Block using Defined by > Box and Type > Model.
- 5 Calculate the Rapid Move Heights using the default settings.




6 Select all of the **surfaces** (including the fillet) that define the bottom left pocket.



7 In the PowerMill explorer, right-click Boundaries and select Create Boundary > Selected Surface.



8 In the Selected Surface Boundary dialog, tick Roll Over and enter a *Tolerance* 0.02 and un-tick, Allow boundary to be private.





9 Click Apply and Accept the dialog.

A **Selected Surface Boundary** defines the limit where the active **Tool** and associated parameters would fully machine the selected surfaces.




10 Open the **Optimised Constant Z Finishing** strategy and enter the values and settings exactly as shown in the 2 dialog pages below:





11 Click **Calculate** to process the toolpath and then **Close** the dialog.



12 In the **PowerMill** *explorer*, right-click the toolpath **BN10-Pocket** and select **Simulate from Start**, and click **Play** in the **Simulation** toolbar.



Transforming toolpaths

Before transforming toolpaths, it is advisable to create a master copy of the original.

- 1 Right-click the **BN10-Pocket** toolpath and select **Edit** > **Copy Toolpath** and then **Rename** the copy **BN10-Pocket_1** as **BN10-Master**.
- 2 In the PowerMill explorer select the toolpath BN10-Master and with the left mouse key depressed, drag it onto Toolpaths to move it to the top of the list.



3 In the PowerMill explorer, right-click on the toolpath BN10-Pocket and select Edit > Transform to display the Toolpath Transform toolbar.




4 Check that the **append toolpaths** option is switched off



- 5 On the **Toolpath Transform** toolbar, click **Move**
- 6 On the Move toolbar, click Keep original with No. of Copies as 2.




7 In the data entry box located below the graphics area, enter the relative **distance** along X as **80**, and press *Enter* on your keyboard.



XYZ values (separated by a space) are entered into this box as required.

8 In the **Transform** toolbar, click \checkmark to close and accept the changes.

Two new copies of the original **toolpath** named **BN10-Pocket_1** and **BN10-Pocket_2** are created and transformed along **X** by a relative distance of **80**.






Note: It is possible to directly append all of tool tracks into a new, single toolpath **BN10-Pocket_1**.



This is achieved by selecting the **Automatically append transformed toolpaths** option before applying the transform values.




Gouge checking a toolpath

A next to the toolpath indicates that it has not been gouge checked directly to the model.



- 1 Activate the toolpath **BN10-Pocket_1**.
- 2 Right-click on the toolpath BN10-Pocket_1 and from the local menu select Verify > Toolpath.
- 3 In Check select the Gouges option.






4 Apply the **Toolpath Verification** dialog.

A **PowerMill information** box is displayed to inform of the gouge checking status. In this instance, **No gouges were found**.



In the **PowerMill** *explorer*, the style of the icon also updates indicating that the **toolpath** is gouge free.




5 Repeat the Verify > Toolpath process on BN10-Pocket_2

Multiple Transform

- 6 Delete both toolpaths BN10-Pocket_1 and BN10-Pocket_2.
- 7 Right mouse click on toolpath BN10-Pocket and from the local menu select Edit > Transform.
- 8 Select the option Automatically append transformed toolpaths.




9 Select the option **Multiple Transform** to open the following dialog.




10 Enter 3 for number of copies and a pitch of 80 for both in X and Y before selecting Accept.



11 In the **Transform** toolbar, click \checkmark to close and accept the changes.



A new toolpath (BN10-Pocket_1) is created that machines all 9 pockets.



- 12 Activate and Verify the new toolpath BN10-Pocket_1 to check for gouges.
- 13 Select File Save Project to update:

.....\COURSEWORK\PowerMill-Projects\Transform

Edit > Limit...

Edit > **Limit** provides a series of options to retrospectively, trim a toolpath to a **Plane**, **Polygon**, or **Boundary**.

These types of retrospective limiting will be undone if the **Strategy** is re-calculated.


For more permanent toolpath limiting use a **Boundary** within the original **Strategy** calculation.

A typical application for retrospective **Toolpath** limiting would be the (one off) remachining of a local area that has been welded.




Edit > Limit > To a Plane

Edit > **Limit to** - **Plane** allows the user to select a plane at specified distance along the **X**, **Y**, or **Z** axis.



The **Edit** > **Limit to** - **Arbitrary** option allows the user to specify an **X**,**Y**,**Z Point** and a user defined, **Normal** vector for the limiting plane.






Edit > Limit > to a Polygon

Using the mouse, you can sketch polygons with any number of sides.

This allows complex areas to be defined, with the option to save the Inside, Outside, or Both sides of the polygon.




Before making a polygon ensure that the Intelligent cursor is switched off.




Edit > Limit > to a Boundary

This provides the option to retrospectively limit a **toolpath** to an existing **Boundary**. This is okay if a temporary, quick solution is acceptable, otherwise the Boundary should ultimately be included within the strategy calculation for a permanent solution. A typical application for this would be the 'one off' machining of an area that has been welded due to a previous gouging error.







If the **Delete Original** option is selected, it causes the deletion of the original toolpath once the new toolpath is created.

If the toolpath is re-Calculated any retrospective limiting will not apply to the new or edited strategy.




Changing the Order and Direction within Toolpaths – EX1

For toolpaths containing internal link moves, the **order** and **direction** of the tool tracks can be changed. For example, if a machining sequence starts at the bottom of the part, and progresses upwards, reversing the order will change the tool track sequence to start at the top of the part and make it progress downwards.

- 14 Select File Delete All and Tools Reset Forms.
- 15 Open the read-only Project:-


.....\PowerMill_Data\Projects\EditToolpaths_2



16 Select File > Save Project As:


.....\COURSEWORK\PowerMill-Projects\EditToolpaths-EX1

17 In the **PowerMill** *explorer*, right mouse click on the toolpath **bn12-finish-a1** and then from the local menu select **Simulate from Start**.




The tool *Climb Mills* across the form, stepping downwards to the base before stepping up the other side.





- 18 Left-click to select all tool tracks on **bn12-finish-a1** beyond the centre of the form (Yellow in the illustration above).
- 19 In the **PowerMill** *explorer*, right-click the active toolpath, **bn12-finish-a1** and from the local menu select **Edit** > **Reorder** to open the following dialog.



The selected segments are shown highlighted (blue) in the dialog.

Each segment is listed in the order of execution. If a toolpath segment is selected on the list, the corresponding segment is highlighted in the graphics area (and vice versa). You can modify or move the selected toolpath to another position in the pecking order.

You can use the buttons on the left hand side of the dialog for changing the order and direction of selected segments. If no segments are selected, the whole of the toolpath will be edited.




The 2 buttons to the lower left of the dialog are **Automatic Reorder** and



Automatic Reorder and Reverse . These can only be applied to the whole toolpath and not on selected tool tracks. They are designed purely to minimise unnecessary air moves.

- to reverse the sequence of the selected 20 Click on the Reverse Order button tool tracks.
- 21 Click on the Reverse Direction button selected tool track.
- 22 Open the Leads and Links dialog and Apply with the following settings:-Vertical arc:- Lead in with Angle 90 and Radius 6 and



The order and direction of the toolpath has been edited so that it tracks from the outer edges of the form downwards towards the centre of the base.



Lead In - Vertical Arc and Lead Out - Extended Move has been applied to the above toolpath to identify the directional differences.


23 Save Project As:

.....\COURSEWORK\PowerMill-Projects\EditToolpath-EX1



Changing the Order and Direction within Toolpaths - EX2

- 1 From the main menu, select File Delete All and Tools Reset Forms.
- 2 Open the read-only Project:-




3 Save Project As:

.....\COURSEWORK\PowerMill-Projects\EditToolpaths-EX2

The **Project** includes a **3D Offset** finishing toolpath **D10TR1-FIN1** controlled by both **Boundary** and **Pattern** segments.

4 **Simulate** the **Toolpath** using a slow setting.



Observe the current direction and ordering of the strategy considering potential improvements.


For example, the lower area machining would benefit from climb milling inwards towards the component form and the pocket machining could start central and climb mill outwards towards the sidewall




5 From the main menu, select View > Toolbar > Toolpath to display the Toolpath toolbar.



- 6 Select the **Reorder toolpath** option \blacksquare .
- 7 Select all tool tracks in the lower area and select Reverse Order . This part of the strategy should now climb mill inwards, towards the main component dialog.
- 8 If it is not climb milling, then apply Reverse Direction 롣



9 Select the tool tracks in the central pocket and again select Reverse Order followed by Reverse Direction. This part of the strategy should now climb mill from the centre of the pocket outwards.






Moving Start Points


Start points on the tool tracks can be moved to provide a more suitable position for applying leads. This is achieved by defining a line that crosses the new start positions on the toolpath.

- 1 Select File Delete All and Tools Reset forms.
- 2 Select File Open Project:
 -\PowerMill_Data\Projects\limiting-example
- **3** Save Project As:
 -\COURSEWORK\PowerMill-Projects\MoveStartPoint-EX1
- 4 Select an **ISO1** view.



The toolpath start point 0 needs to be moved to position 2.

- 5 Select a **View from top (Z)**.
- 6 Right-click toolpath 1 and select Edit > Move Start Points and from the toolbar select Move start point by clicking a toolpath segment .





7 Click a point along the toolpath segment and then \checkmark to accept the change.



This has moved the toolpath start point.

8 Select Save Project to update:-

.....\COURSEWORK\PowerMill-Projects\MoveStartPoint-EX1

Moving multiple start points

It is possible to apply the **Move start points** options on the toolpath to multiple positions.


- 1 Select File Delete All and Tools Reset Forms.
- 2 Open the Project:

.....\PowerMill_Data\Projects\PunchForm10-Start

3 Save Project As:

.....\COURSEWORK\PowerMill_Projects\PunchForm10

4 Select a View from top (Z).




5 Right-click the active toolpath and from the local menu select Edit > Move Start Points (The Move Start Points toolbar will appear).




If not already active on the toolbar, click the **Move Start Points by drawing a line** button (shown arrowed above).




- 7 On each of the three locations shown below, in the listed order, click and select 2 Key-points on both sides of the tool tracks.
 - 1 First move point selection points.



2 - Second move point selection points.




3 - Third move point selection points.





The final output looks similar to this:






The tool tracks are coloured blue while the Move Start Points toolbar is active.

- 8 Click on the Move Start Point toolbar to accept the changes.
- 9 Save the Project to update:-

.....\COURSEWORK\PowerMill-Projects\ PunchForm10

Feeds and Speeds


You can modify the values in the **Feeds and Speeds** dialog and retrospectively **Apply** them to the **Active toolpath**.





- 10 Select File Delete All and Tools Reset Forms.
- 11 Select File > Open Project:


.....\PowerMill_Data\Projects\ExtraFeedrates-Start




12 Select **File** > **Save Project As**:

.....\COURSEWORK\PowerMill-Projects\ExtraFeedrates-Example

13 Undraw the Model, Block, Workplane, and Tool to display just the Toolpath and 3 Boundaries.



- **14 Activate** both the **Toolpath** and **Boundary 2** (The middle one of the 3).
- 15 Right-click the **Toolpath** and select **Edit** > **Update Feed Rate Inside Boundary**.
- 16 Enter value as **50** and click **v** to apply the percentage difference to the Feed Rate within the **Active Boundary**.




The **Toolpath** is split into two different coloured areas that are allocated a separate **Feed Rate** as a percentage of the original. The colour coded **Feedrates** are displayed in an Information dialog that appears automatically.






The Feedrates Information dialog can also be opened by:-

- Selecting View Feedrates from the local toolpath (BN10-A1) menu.
- b By double-clicking on a Light bulb adjacent to a toolpath (BN10-A1) in the PowerMill explorer.




The original Cutting Feedrate assigned to the toolpath was 450 mm/min.

- 17 Activate both the Toolpath and Boundary 3.
- 18 Right-click the **Toolpath** and from the local menu select **Edit** > Update Feed Rate Inside Boundary.
- 19 Enter the value **100** and click to apply the percentage difference to the **Feed Rate** within the **Active Boundary**.



The central part of the **Toolpath** area, clear of the side wall, has now changed back to the nominal **Feed Rate** value.



In this case, the nominal **Feed Rate** is **450 mm/min**, and the modified section (near the intersection of the Base and Sidewall of the pocket) is reduced by 50% to **225 mm/min**. The colour of the values displayed in the Information dialog is the same as the colours displayed on the toolpath.



9. Tool Collision Checking

Collision Checking


Collision Checking can either be applied retrospectively or directly during toolpath creation, as long as a tool Shank and Holder are defined with the *Active* Tool.

Retrospective Collision Checking (Verify -Toolpath)

If the **toolpath** menu option, **Verify > Toolpath -** (*Collisions*) is applied, two additional toolpaths will be created from the original, one being collision safe, and the other being in collision. At the same time a copy of the **Tool** complete with appropriate modifications will be substituted into the *Original* and *Collision* status toolpaths.


- 1 Select File > Delete all and Tools > Reset Forms.
- 2 Import the Model:-

.....\PowerMill_Data\Models\cowling.dgk




- 3 Calculate the **Block** to **Min/Max** limits.
- 4 Calculate both the Rapid Move Heights and the tool Start and End Points.
- 5 Create a Dia 5mm Ball Nose tool named BN5-Short with a length of 10 and tool number of 1.






- 6 Select the Shank tab.
- 7 Select Add a shank component 🗐.
- 8 Fill in the dialog exactly as shown in the image below.




- 9 Select the **Holder** tab.
- 10 Select **Add** holder component •••.
- 11 Fill in the form for the first **Holder** element exactly as shown in the following image.





- 12 Select Add holder component
- 13 Enter an Upper Diameter of 22, Lower Diameter of 20, and Length of 10.
- 14 Select Add holder component .
- 15 Enter an **Upper Diameter** of **30**, **Lower Diameter** of **30**, **Length** of **10**, and an **Overhang** of **15**.





If it is required to modify or delete a Holder element, select (left click) on one of them in the assembly illustration and it will turn pale. The current values for that element will be displayed and available for modification.




The same procedure applies to modify a Shank element.

16 Click Close.



17 From the main toolbar, select Toolpath Strategies and from Finishing open a Raster Finishing strategy.




- 18 Enter Toolpath name as BN5-RasterFinish, Angle 45, and Stepover 1.
- 19 Select Start Corner Lower Left.
- 20 Select Style Two way.
- 21 In the Leads and Links , set both Lead in and Lead out with 1st choice as Surface normal arc with Angle 90 and Radius 3, with Apply constraints set to Distance > 4.
- 22 In the **Links** page:-
- For 1st choice enter Circular Arc with Apply constraints set to Distance <
 4.
- Set 2nd choice to Skim, and Default to Incremental.
- 23 Click **Calculate** to process the toolpath and then **Close** the dialog.
- 24 In the **PowerMill** *explorer* hold the cursor over the small box to the left of the toolpath lightbulb symbol.






The **Safety Status** window will appear.



The new **toolpath** is **gouge free** as far as the **Tip** (cutting part) of the tool is concerned, but up to this stage no **collision checking** has been applied in relation to the **Shank** and **Holder**.

25 From the main toolbar select Toolpath Verification 🕏.




The two available, independent **Check** options are **Collisions** and **Gouges**.

Shank Clearance and **Holder Clearance**, allow the user to specify a value for an additional, safe thickness around the tool **Shank** and **Holder** elements.


- 26 In the Check box select Collisions.
- 27 Input the values **Shank Clearance 2** and **Holder Clearance 3**.
- 28 Click Apply.






The above **PowerMill Information** box appears with information on the status of the original tool and required dimensional changes. The default settings will result in a modified **tool** (**BN5_1**) being created along with 2 new **toolpaths** (The collision and non-collision parts of the original). The new **tool** (**BN5-Short_1**) will then automatically exist in both the original and new (collision warning area) toolpath. The original **tool** (**BN5-Short**) will remain in the new (collision safe area) toolpath.

- 29 Click OK.
- 30 Click Accept on the Toolpath Verification dialog.



PowerMill has created two new toolpaths, BN5-Raster Finish_1 and BN5-RasterFinish_2. A new tool named BN5_1 has also been created in the Tools area of the PowerMill explorer. This new tool has been created with the new valid adjustments made i.e. Overhang 26.4


31 Activate the toolpath RasterFinish_1.



This **toolpath** contains the 'collision free' segments of **RasterFinish**, along with the original tool **BN5**.




32 Activate the toolpath **RasterFinish_2**.



This **toolpath** contains the 'collision' segments of the **Raster Finish** if it were machined with the original **BN5** tool.

33 Activate the original toolpath, **BN5-RasterFinish**.





PowerMill has substituted a newly created **Tool**, **BN5-Short_1** (with an extended overhang) into **BN5-RasterFinish** and **BN5-RasterFinish_2**.

34 Select **File** > **Save Project As**:

.....\COURSEWORK\PowerMill-Projects\ToolCollisionExample




Direct Collision Checking (Automatic Verification)

Tool Holder Collision Checking can also be applied during **Toolpath** calculation.

If the **Toolpath** is calculated with a **Tool** definition that includes a **Shank** and **Holder** any part of the toolpath segments that would otherwise be in a collision condition will not appear. These missing segments can then be machined later using a modified **Tool** in conjunction with a **Collision Safe Boundary**.

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Select an **ISO 2** view.
- **3 Open** the **Project**:

.....\PowerMill_Data\Projects\ToolCollision_Start




4 Save Project As:

.....\COURSEWORK\PowerMill-Projects\ToolCollision-Auto


- 5 Right-click on the RasterFinish toolpath in the PowerMill explorer.
- From the local menu, select **Activate** followed by **Settings** and in the **Raster**Finishing dialog select the *Copy* toolpath icon

 .
- 7 Select the **Automatic Verification** page ¹ to open the following dialog:





- 8 Tick the Automatic collision checking box, then input Holder Clearance 3 and Shank Clearance 2.
- 9 Calculate the Raster Finishing strategy to directly create a collision free toolpath, RasterFinish_1.






This method does not produce any information for the user or automatically create a new collision free tool (**BN5_1**).

Machine maximum stock


If the additional option **Machine maximum stock** is ticked then a full toolpath will be created with a varying increased **thickness** over the previously inaccessible areas.

- 10 Right-click on the toolpath RasterFinish_1 in the PowerMill explorer.
- 11 From the local menu, select **Activate** followed by **Settings** and in the **Raster**Finishing dialog select **Copy** toolpath ...
- 12 With the **Raster Finishing** dialog open, select the **Automatic Verification** page to access the following dialog:





- 13 Tick Automatic collision checking, input Shank Clearance 2, Holder Clearance 3, and tick Machine maximum stock.
- **14 Calculate** the **Raster Finishing** dialog to directly create a continuous, collision free toolpath, **RasterFinish_1_1**.






An additional strategy with a compatible (collision free) tool is required to remove the remaining stock.

Collision Safe Boundary

A toolpath for the remaining areas will require a new Dia 5 Ball Nosed tool with increased **Shank** length. The additional **Toolpath** will be calculated to limits set by a **Collision Safe Boundary** based on the current tool (**BN5**).


- 15 Ensure that the tool **BN5** is **Active**.
- 16 In the **PowerMill** *explorer*, right-click Boundaries, and from the local menu select Create Boundary > Collision Safe.



17 Use the above settings and **Apply** the dialog.



18 Select and **Delete** all segments except the 2 shown below.




19 Create an empty **Pattern** and copy the outer **Boundary** segment to it.



With the outer **Boundary segment** selected, use **left mouse key** and **CTRL key** to drag and drop **Boundary** (1) into **Pattern** (1) from within the **PowerMill explorer**.

20 Right mouse click on the new **Pattern** and from the local menu select **Instrument** to display the direction with an arrow.




21 Select the **Pattern** segment and if necessary, select **Edit** – **Reverse selected** to set it to comply with a climb milling direction.




22 In the **PowerMill** *explorer*, right-click the **Tool**, **BN5**, and from the local menu select **Edit** > **Copy Tool** (to create **BN5-1**).



- 23 Right-click over the new tool BN5-1 and from the local menu, select Activate followed by Settings to open the Ball nosed tool dialog.
- 24 For the **Tip** change the length to **15**.
- 25 Select the **Holder** tab and change the **Overhang** to **30**.
- 26 Close the form.
- 27 Activate the new 'long reach' tool, BN5_1
- 28 Select **Toolpath Strategies** on the main toolbar.
- 29 From the **Finishing** options select a **3D Offset Finishing** strategy and enter data as shown in the following form.




30 Select the Limit page and select Boundary 1 with Trimming as Keep inside.






31 Select the Automatic Verification page and tick Automatic collision checking, input 1 for both Shank and Holder clearances, un-tick Machine maximum stock.



32 Calculate the toolpath and then Close the dialog.





The new toolpath does not exhibit any fragmentation, showing that the active Automatic Collision Checking has not detected any problems.

33 Select Save Project to update:

.....\COURSEWORK\PowerMill-Projects\ToolCollision-Auto






10. Patterns

Introduction

Patterns are 2D or 3D Wireframe entities used primarily for the control and creation of toolpaths. A selection of **Pattern** creation and manipulation options are provided in a dedicated **Toolbar** (as shown below).





Below is a summary of the Pattern - toolbar options:





- Pick curves to add to the active Pattern.
- Automatic Pattern Generation (Open the Pattern Maker form).
- Insert File into Active Pattern (eg. dgk, pic, dxf, iges).
- Save Active Pattern as a file (dgk pic dxf).
- Insert Boundary into Active Pattern.
- Insert Active Toolpath into Active Pattern.
- Insert Model into Active Pattern (Selected Model).
- 거 Curve modelling.





- Transform pattern



- Curve Editor.



Clear



The **Pattern** segments can be edited directly from local menu options, or via the **Curve Editor**. Unlike **Boundaries**, **Patterns** can contain open segments.

When an empty **Pattern** is created it is automatically assigned a number and made **Active** as shown in the **PowerMill** *explorer*.




Automatic Pattern Generation

The **Automatic Pattern Generation** icon opens the **Pattern Maker** dialog. This provides options for the user to construct a range of wireframe layouts that can be used in the **Pattern Finishing** strategy.

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Import the Model:

.....\PowerMill_Data\Models\phone.dgk


- 3 Select **Block** and **Calculate** using the default settings.
- 4 Define a dia 12mm Ball Nose tool named **BN12**.
- 5 Reset the Rapid Move Heights
- 6 Select an **ISO1** view to display the **model**.




7 Select the 'shutout' surface as shown above (light blue).



In the **PowerMill explorer**, right-click on **Boundaries**, and from the local menu select the option Selected Surface and enter the values shown below.



Apply the dialog to create 2 **Boundary** segments.




10 In the PowerMill explorer, right click on Patterns and from the local menu select Toolbar.



- 11 In the Patterns toolbar select, Create a new (empty) Pattern
- 12 In the graphics area, select the inner **Boundary** segment.
- 13 In the Patterns toolbar select the option to Insert Boundary into Active Pattern 🔽
- 14 Delete the Boundary.



Once the selected **Boundary** segment is copied as a **Pattern** segment the **Boundary** is no longer of use.



15 Right-click on the Pattern segment and from the local menu, select Curve Editor.




16 In the toolbar move the cursor over **Transformations** and from the attached vertical toolbar, select the **Offset** option.



- 17 Select **Keep Original** , the **Round Corners** option, and input **Distance 50** before clicking the **Enter** key.
- 18 In the **Curve Editor** toolbar, click to accept.






- 19 Right-click on the **Pattern** and from the local menu, select **Instrument** to display the direction arrows on the segments as shown in the image above.
- 20 Select the inner Pattern segment and from the local menu select Edit > Reverse Selected (Both Pattern segments should now run in the same direction).

The **Automatic Pattern Generator** will be used to create a new **Pattern** with a series of segments merged between the 2 segments from the original **Pattern**. The resultant **toolpath** will follow the contour of the component form as well as creating corner free, tool tracks with a constant material removal rate.

21 From the Pattern toolbar, select Create Pattern to create a new Pattern.




- 23 With the new (empty) **Pattern** activated and the original **Pattern** displayed, select both visible segments.
- 24 Select Create Pattern along 'one-way curves' with a Stepover 1.0.



The form allows the user to create a range of multi-segment **Pattern** styles from either 1 or 2 drive curves.

25 Click **Apply**, followed by **Accept**.






The new **Pattern** has been generated independently; between the two selected segments of the original, de-activated **Pattern** (the above illustration shows a larger 2mm Stepover for visual reasons).


The new **Pattern** will now be used in a **Pattern Finishing** strategy.

26 In the Strategy Selector, Finishing options, select a Pattern Finishing strategy.



27 Enter the data into the above form exactly as shown above, click **Calculate**, and then **Close** the form.





The **Pattern Finishing** toolpath is limited to exist within the defined material **Block**.

Exercise


- 28 Right mouse click on the new toolpath and from the local menu select Edit > Reorder.
- 29 Use both the Reverse Order and Reverse Direction editing options for the toolpath to start from the outside, Climb Milling towards the centre of the model.
- 30 Save the Project.




Patterns applied to 3D Offset machining

A **Pattern** can be used as a curve to be offset across the area of a **3D Offset Finishing** strategy.

- 1 Select File > Delete All and Tools > Reset Forms
- **2 Import** the model:
 -\PowerMill_Data\Models\speaker.dgk
- 3 Save Project As:
 -\COURSEWORK\PowerMill_Projects\SpeakerPattern-EX1
- 4 Define a Dia 6 Ball Nose tool with the name **BN6**.
- 5 Define a **Block** to the default **Min/Max limits**.
- 6 Calculate the Rapid Move Heights to the default settings.
- 7 Select an ISO3 view.
- 8 Select the 3 shaded **Surfaces** as shown in the following diagram.



9 Create a **Selected Surface**, **Boundary** with **allow boundaries to be private** un-ticked, and with a **Tolerance** value of **0.02**.








10 From the Pattern toolbar click Create Pattern followed by Insert

Boundary into Active Pattern (Input Boundary name into the dialog).

11 Undraw the **Tool**, **Block**, **Model** and **Boundary** to visually isolate the new **Pattern**.



Only the leading edge of the **Pattern** is required. The remaining parts are to be removed.

- 12 Select the **Pattern** segment using the left mouse key.
- 13 Right mouse click on the **Pattern** and from the local menu, select **Curve Editor** to open the following toolbar:




14 Select the option **Cut Item**.




While performing the next operation it is essential to zoom in as close as possible to the end of the pattern segment!

15 Move the cursor over the left hand end of the leading edge to locate the **Key**Point and then left click to cut the segment at this point.







16 Select the leading edge, segment again, locate the **Key Point** and cut exactly at the right hand end of the leading edge.



- 17 Click on the option **Cut Item** again to de-select it.
- 18 Select the **Pattern** segments away from the leading edge, and **Delete** .




- 19 Click the green tick to save the above new segment and close the **Curve Editor** toolbar.
- 20 Re-draw the **Tool**, **Model**, and the **Active Boundary**.






21 Select a 3D Offset Finishing strategy and enter data into the dialog exactly as shown below.




22 Click Calculate to create the toolpath and then Close the dialog.



Leads and Links are not displayed to provide a clearer view of the **toolpath**.

The above toolpath starts at the lowest point following the **Pattern** while offsetting across the limiting **Boundary** in a **Climb Milling** direction. With the addition of suitable **Lead In** and **Lead Out** moves this is an ideal strategy for **High Speed Machining** applications.





If a **Pattern** is not selected in the **3D Offset** dialog, machining strategy follows the shape of the **Boundary** segment, as shown above.


23 Save the Project.

Exercise - 3D Offset Finishing controlled by Pattern

It is not compulsory for the **Pattern** for controlling the toolpath to be coincident with the limiting **Boundary**. In the following exercise a **3D Offset Finishing** will be controlled by a **Pattern** that runs centrally along the base of a curved recess:

- 1 Select File > Delete All and Tools > Reset Forms
- 2 Open the Project:






- 3 Click **OK** to close the **PowerMill Warning** and **Save Project As**:
 -\COURSEWORK\PowerMill-Projects\PatternBlock_ex1
- 4 Calculate the Block using the default settings.



5 Calculate the Rapid Move Heights to the default settings.



- In the **Viewing** toolbar switch on display **Wireframe**
- Create a Pattern using Insert Model on the wireframe arc (included with the Model) running centrally along the recessed form.
- Select the 5 surfaces that define the recessed form and create a **Selected** Surface Boundary using a 0.01 tolerance, with the BN16 tool active.
- Create a **3D Offset Finishing** strategy that is limited **Inside** the **Boundary** with the order and shape of the tool tracks controlled by the Pattern.



10 Save Project As:

.....\COURSEWORK\PowerMill_Projects\PatternBlock-EX1



Deep Pattern machining

If **Pattern Finishing** is applied with a -ve **Thickness** it will only create **tool tracks** where the -ve **Thickness** value is less than the **tool**, *tip radius*. As an example, this makes it impossible to use a -ve **Thickness** value less than zero where an **End Mill** is being used.


It is, however, possible to produce a **Pattern Finishing** strategy that machines deeper into the model if **Axial Offset** is used in place of a -ve **Thickness** value. This is achieved by first projecting the **Pattern** onto the surface (relative to the tool geometry). **Pattern Finishing** is then applied using the **Drive Curve** option with a -ve, **Axial Offset** value while **gouge checking** is unticked.



The strategy produced will not be based on a 3D offset of the model form but a series of copies of the Drive Curve stacked downwards.

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Open the read only Project:

.....\PowerMill_Data\Projects\DeepPattern_Start



3 Click OK to close the PowerMill Warning and Save Project As:

.....\COURSEWORK\PowerMill-Projects\DeepPattern-EX1


The **Project** consists of component surfaces and a **Pattern** on **Z0** representing the text 'RH' ready to be engraved into the component form to a depth of **-3**.

- 4 Calculate a Block, Defined By Box, using Type Model.
- 5 Create a Dia 5 Ball Nosed tool with the name **BN5**.
- 6 Calculate the Rapid Move Heights to the default settings.
- 7 In the **PowerMill explorer**, right-click over the **Pattern 1** and from the local menu select, **Edit** > **Drop** to project it downwards onto the model.

This projects the **Pattern** down Z, while compensating for the tooling parameters.




- 8 From the main toolbar, select Toolpath Strategies and in the dialog select Finishing followed by the Pattern Finishing option.
- 9 Enter the data into the dialog exactly as shown, using Base Position Automatic with Thickness -3 and then click Calculate.






The Thickness of -3.0 exceeds the Tip Radius of the Dia 5 Ball Nosed tool hence instead of a toolpath appearing, the following PowerMill Error form is displayed.



10 Click **OK** to close the **PowerMill Error** message and recycle the **Pattern Finishing** toolpath using the data as shown in the following image.






Base Position - Drive Curve

Axial Offset -3.0

Gouge Check - un-ticked

Thickness 0

11 Select the **Multiple cuts** page and input data exactly as shown below.




Mode - Offset down

Upper limit - Ticked with value -1.0 (First pass at 1mm below the Pattern)
Maximum Stepdown 1.0



12 Click Calculate to create the toolpath and then Close the dialog.



The Reversed lettering, Pattern 'RH' is now recessed into the Punch form to a depth of 3mm.



The Toolpath will initially be identified in the PowerMill explorer with a yellow warning.



- 13 Right mouse click on the **Toolpath** and from the local menu select **Verify** > **Toolpath**.
- 14 In the **Toolpath Verification** dialog (with the default **Check Gouges** set) select **Apply**.

Once verified for **gouges**, the above **Toolpath BN5-Engrave** will then be identified in the **PowerMill explorer** with a **red warning**.



15 Save the Project.






11. Curve Editor

Introduction

This is a *wireframe constructor* within **PowerMill** that provides the user with a powerful set of tools for the creation and modification of **Boundaries** and **Patterns**. It is accessed via the local **Boundary** or **Pattern** menu option, **Curve Editor...** During construction, the **Intelligent Cursor** option allows geometry items to be snapped onto **key points** on a displayed CAD model.


Input of Drawing detail as a Pattern using the Curve Editor

An empty **Pattern** can be inserted into the **Curve** editor thereby providing the user with an effective way to input **Drawing Detail** which could in turn be used in the creation of 2.5D **Feature** Sets.







- 1 Select File Delete All and Tools Reset Forms.
- 2 In the PowerMill explorer select Workplanes Create Workplane.



3 The **Workplane** editor toolbar will become active as soon as a new **workplane** is created on the global datum.



- 4 Select the *green* tick to exit the **Workplane Editor** toolbar.
- 5 Activate the Workplane.
- 6 Select a view down Z.
- 7 From the PowerMill explorer, right mouse click on Patterns and from the local menu select Curve Editor.



8 From the Curve Editor select Rectangle option.




9 Input **0** in the **Command Input** box (located to the right and below the graphics area) and press the return key to accept.



This will fix the corner of the **Rectangle of Lines** to the active XYZ datum.

10 Input **155 100** in the **Command Input** box and press the return key to accept the X and Y dimensions of the rectangle.





11 Select the corner **Radius** option and input **10**.






- 12 Create a new **Rectangle of lines** using **100 25** to define the start corner.
- 13 In the data input box, switch from **Absolute** to **Relative** input and enter **40 50** for the X and Y dimensions.






14 From the **Create a circle** options select the **full Circle** option.




- 15 Input a Radius value of 25.
- 16 Input **50 50** in the **Command Input** box followed by the return key.






- 17 Create another Circle of radius 3 centred at 50 90.
- 18 Click on to close the **Circle creation** options.
- 19 Select the Dia 6 Circle.
- 20 With the new Dia 6 Circle selected, open the **Transforms** options and select **Create pattern of objects**.






21 On the dialog, select the **Circular** tab and enter **Angle 30**, **Number 12** and select **Reposition rotation axis**, and drag it to the centre of the large circle.



22 Select Accept on the Multiple Transform dialog.






The geometry creation is now complete and is ready to be returned to the **PowerMill Project** as the contents of the **Pattern**.

23 Left click in the graphics area away from the segments to deselect them.



If any segments are selected then the remainder will no longer exist on return to the main PowerMill window.

24 Select to accept changes and export the wireframe back to **PowerMill** to replace the original boundary.



25 Select File > Save Project As:

.....\COURSEWORK\PowerMill-Projects\2DModel




Boundary modifications using the Curve Editor


A **Shallow Boundary** will be created in the following example and although correct to the settings applied, it will benefit from further modification to provide improved machining strategies. The modifications aim to make the toolpaths, continuously follow the lower, component contour by bridging the gap between the 2 outer segments as well as smoothing any jagged sections of the segments. The easiest and most effective method is to make use the **Curve Editor**.

- 1 Select File Delete All and Tools Reset Forms.
- 2 Import the Model:

.....\PowerMill_Data\models\cowling.dgk



- 3 Calculate a Block using **Defined by Box** and **Type Model**.
- 4 Create a Ball Nose cutter of Diameter 10mm named **BN10**.
- 5 Calculate the Rapid Move Heights using the default settings.
- 6 Use the default **Start and End Point** values.
- 7 In the PowerMill explorer, right-click Boundaries and from the local menu select Create Boundary > Shallow




8 Input *Tolerance* 0.02



9 Set limit tool centre to block edge.




- 10 Un-tick Allow boundary to be private.
- 11 Select **Apply** followed by **Accept**.
- 12 Undraw the **model** to view the new **Boundary**.



The **Boundary** will be modified so that the gap is removed between the 2 outer, closed, segments to form separate inner and outer segments. In addition to this, two of the other segments, which contain jagged sections, will be smoothed.

13 Right-click Boundary 1 in the PowerMill explorer and from the menu options select Curve Editor.

The **Curve Editor** toolbar will appear above the graphics area.





Some options are currently greyed out, only becoming available when a related entity is selected.



- 14 Select a **view down Z** for a top view of the inserted boundary.
- 15 Click Line from the toolbar then select Create a single line.



Note: It is essential that the **Intelligent Cursor is active** (ticked):-


If not, this is set in the Curve Editor > Options menu:-



-- Intelligent Cursor -- Snapping Options -- (Tick all boxes).

16 Using the left mouse button, snap (**Key points**) to create single lines across the ends of the four gaps, as shown in the image below.






- 17 Select the **Single Line** option I to switch it off.
- 18 To remove redundant spans on the curves, click the **Limits** option to access **Interactively limit wireframes**.



19 Click **Interactively limit wireframes** and using the left mouse button, select the parts of the curve (arrowed) to be removed.




- 20 Select the **Interactively limit wireframes** option again to switch it off.
- **21 Zoom** into the middle of the area covered by the 3 inner segments.



Note the jagged effect along these curves.






22 Create 4 **single lines**, snapped to key points and pointing outwards from the curve outside the jagged regions (as shown above).

These will be used as markers to provide a start and end point for new, replacement smoothed curves along the jagged sections. The markers will then be used as the limit to trim away the unwanted, jagged sections of the original curve.

- 23 Click Curve on the toolbar then select Create a Bezier Curve from the Curve toolbar.
- 24 For the upper section, generate a new, smoother, **curve** by snapping strategically placed key points within this region, starting and ending by snapping to the ends (**Key Point**) of the marker lines.



The selection of suitable key points requires a certain amount of skill on the part of the user. Where it is required to follow the original form closely input several, equispaced points. Where the original shape needs to be smoothed out input the minimum of equispaced points along the form.



- 25 Repeat this process for the lower section.
- **26** Select the upper, original curve and select the **Cut Item** option.




27 Click the **key points** at the lower end of each line to cut the original curve.






- Repeat the above process on the lower, original curve then select and **Delete** all the unwanted segments between the 2 pairs of **lines**.
- 29 Then, select and **Delete** the 4 vertical lines.



30 Create a new smooth **Bezier Curve** to replace the one indicated below.







The **Curves** used in the above wireframes will consist of open or closed segments, but if they are to be used to recreate a **boundary** they must form single entity, closed loops. Only closed forms will appear as **boundary** segments when returned to **PowerMill**.



- 31 Select all **boundary** segments by dragging a box over them with the left hand mouse key depressed.
- 32 Select the option **Merge** selected segments to join together all groups of **curves** that butt up to each other.








The wireframe will now consist of five single segments as reported in the **PowerMill Information box** (above right).

33 Left click in the graphics area away from the segments to deselect them.



If any segments are selected then the remainder will no longer exist on return to the main **PowerMill** window.

34 Select to **Accept** changes and export the wireframe back to **PowerMill** to replace the original boundary.




The modified **Boundary** is positioned back over the model close to its original 3D form. The new smoothed contours are now a more suitable shape for use in the **3D Offset Finishing** strategy.

- 35 Generate a Constant Z Finishing toolpath with Stepdown 1 and in the Limit page set the Boundary Trimming option to Keep outside (Steep areas).
- 36 Generate a **3D Offset Finishing** toolpath with **Stepover** 1 and in the **Limit** page set the **Boundary Trimming** option to **Keep inside** (Shallow areas).



37 Select **File** > **Save Project As**:

.....\COURSEWORK\PowerMill-Projects\Boundary-mod



These are the resultant toolpaths with the **Leads** and **Links** undrawn.



The techniques used in this example can equally be applied to **Patterns**, which also have the added advantage on being able to exist both as open or closed segments (**Boundaries** cannot contain open segments).



The same **Curve Editor** toolbar is accessed via the local **Pattern** menu.



12. 2D Machining

Introduction

PowerMill offers a comprehensive range of 2.5D machining strategies created by either **Feature Machining** (*Drilling*, *Turning*, and *Milling*) or direct **Curve Machining** (*Milling*).

Feature Group Machining

Features are wireframe entities that are extruded along Z for *Milling* or rotated about the X axis for **Turning**. During creation they are specifically defined in a **Feature Group** that can contain an assortment of different **Feature** types. It is essential that a **Feature Group** includes all **Features** that need to be machined together as a component. **Hole Features** are contained separately in **Hole Feature Sets**. It is also possible to extract **Hole Features** directly from the 3D model. **Hole Feature Sets** can also be created during **3D Area Clearance** strategies to enable the pre-drilling of plunge move, positions.

On completion of a **Feature Group**, the range of **Feature Machining** strategies will allow the user to create roughing, semi finishing, and finishing strategies.

Drilling strategies can only be applied to **Hole Features**. A comprehensive, list of cycle types are supported that include; Standard Drilling, Boring, Helical/Profile milling, Tapping, and Thread Milling.

There are several types of **Feature** that can be included in a **Feature Group** which fall into 2 main groups consisting of 5 for *Milling* and 4 for *Turning*.






It is not possible to change an existing a **Feature** into one of a different type.



Creating Features from Pattern segments

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Open the Read-only Project:

.....\PowerMill_Data\Projects\2D-Drawing



The imported **Project** contains a **Pattern** defining 2D geometry ready to be used to create a **Feature Set**.

3 Select File > Save Project As:


.....\COURSEWORK\PowerMill-Projects\2DPatternExample

4 In the **PowerMill** *explorer*, right-click on **Feature Groups** and from the local menu, select **Feature** editor.

The **Feature** toolbar (shown below) will appear above the graphics area.



- 5 Back in the graphics area select the outer rectangle on the displayed **Pattern**.
- 6 From the **Feature** editor toolbar select **Create a freeform boss**.





This will open the **Create Freeform Boss Feature** dialogue.



7 Fill in the **Create Freeform Boss Feature** dialogue exactly as shown on the following page (Note; use *Curve position* as **Top**).








- 8 Select **Apply** to create the rectangular **Boss Feature** (shown above) and then **Cancel** the dialogue.
- 9 From the **Feature Editor** toolbar select the **Create a freeform pocket** option.




10 Select the 2 inner **Pattern** segments (circle and radiused rectangle) and fill in the dialogue exactly as shown below.






11 Select **Apply** to create the 2 **Pocket Features** (shown on the following page).




- 12 Cancel the **Feature** creation dialog and then select the **Green** tick on the **Feature Editor** toolbar to accept all of the created **Features**.
- 13 In the **PowerMill** *explorer* right click on **Hole Feature Sets** and from the local menu select **Create Holes**.
- 14 Select all of the Dia 6 circular Pattern segments and then enter values exactly as shown in the following Create Holes dialog (Note use Create from Circles).





- 15 Select **Apply** to create the **12 Hole Features**.
- 16 Close the **Create Hole** dialogue.




The contents of the **Hole Feature Set** and the **Feature Group** should be similar to the above illustration (Note: A naming system has been chosen where a **Boss** is prefixed with a **B**, a **Pocket** with a **P**, and a **Hole** with an **H**).




2D Feature Set Machining

- 1 Define a Dia 10 tiprad 1 Length 50 tool named **D10TR1**.
- 2 Click to open the **Block** dialog, set the **Type** as **Feature** and then select **Calculate**.
- 3 Click **t** to open the **Rapid Move Heights** dialog and select **Calculate**.
- 4 Activate the **Feature Group** (1).




- 5 Click to open the **Toolpath Strategies** dialog and select **Feature**Machining.
- 6 Select **Feature Area Clearance** and input the data exactly as shown in the following dialog.






7 In the Offset page tick Spiral.




8 In the Leads and Links - Lead in page select:-

1st choice > Ramp

Ramp Options > Follow Circle - Max zig angle 4.0 - Circle diameter (TDU) 0.65



9 Select Calculate to process the toolpath and then select Cancel to close the dialog.







The **Pocket Features** are machined with **0.5** stock left on the sidewalls and 0 stock on the base (**Radial thickness 0.5** and **Axial thickness 0**).



- 10 Click to open the **Toolpath Strategies** dialog and select **Feature Machining**.
- 11 Select **Feature Profile** and input data exactly as shown in the following dialog.



- 12 Select the **Lead In** page and for **1st Choice** select **Pocket Centre** and then select the **Lead out same as lead in** option .
- 13 Select **Calculate** to process the toolpath and then **Close** the dialog.







14 Activate the Hole Feature Set (1).



- 15 Create a Dia 3 Drill of Length 30, named **Drill3**.
- 16 Click to open the **Strategy selector** dialog and select the **Drilling** tab.
- 17 From the list, select **Single Peck** to open the **Drilling** dialog (below).




- 18 Select **Calculate** and all **Hole Features** will automatically be selected before the **Drilling** toolpath is processed.
- 19 Select Cancel to close the dialog.






- 20 Create a Dia 6 Drill of Length 50 and named Drill6.
- 21 Click to open the **Strategy selector** dialog and select the **Drilling** tab.
- 22 From the list, select **Break Chip** to open the **Drilling** dialog (below).




- 23 Select **Calculate** and all of the contained **Hole Features** will automatically be selected before the **Drilling** toolpath is processed.
- 24 Select Cancel to close the dialog.






25 Run a full **ViewMILL simulation** on all 4 toolpaths.



26 Save the Project.

2D Machining Exercise

For this exercise the following 2D drawing will be used along with the imported 2D wireframe **Pattern**:



- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Create an empty Pattern and Insert File:


.....\PowerMill_Data\Models\2d_Wizard_Example.dgk

3 Save Project As:-


.....\COURSEWORK\PowerMill_Projects\2D_Wizard_EX1



4 Create two **Feature Groups** (1 & 2) using the **Feature Editor** to create the appropriate **Features** using the above drawing dimensions.




- a In **Feature Group** (1) the outer square and small tapered, central upstand are created as **Freeform Boss Features**.
- **b** The intermediate square is created as a tapered **Freeform Pocket Feature**.
- c In **Feature Group** (2) the single red line on the drawing is used to define a **Slot Feature** with a slot width of **20**.
- d The four Dia **15** circles are created in a separate **Hole Feature Set**.
- 5 Create a Dia 10 with 3 Tip Radius tool named D10TR3 (Roughing, Semi-finishing within the main Pocket Feature including the small Boss).
- 6 Create a Dia 10 Tapered Tipped tool named D10TR3A5, with Tip Radius 3, Taper Angle 5 Deg, Length 25, Taper Diameter 7.5 (Final Finishing of tapered walls Main Pocket and small Boss).
- 7 Create a Shank of Dia 10 length 30.
- 8 Create a **Holder** with **Overhang** 50 and entities:-
- 9 Lower Dia 20 Upper Dia 30 and length 25.
- 10 Upper/Lower Dia 30 and Length 25.








To calculate the Taper Height based on the Taper Angle and base Taper Diameter, the Manual Input icon , adjacent to the Taper Height, is clicked to apply the **Calculate** option to this parameter.



- 11 Create a Dia 15 Drill named Drill15.
- 12 Create an End Mill of Dia 10 named EM10.



- 13 Activate the tool **D10TR3**.
- **14** Activate, **Feature Group 1** and create a **Block** (Type Feature).




15 Calculate default **Rapid Move Heights** ready to create the 2D **Feature** machining strategies.




Main Block and Central Pocket

D10TR3 - Feature Area Clearance - Offset Model

- 16 Click to open the Strategy selector dialog and select Feature Machining Feature Area Clearance.
- 17 In the **Feature Area Clearance** dialog input the data exactly as shown in the following dialog.



- 18 Open the **Step cutting** page, Tick **Step cutting**, and input a **Stepup** of **2.5**.
- 19 Calculate the toolpath and perform a ViewMILL simulation as shown below.







D10Tr3A5 - Feature set Profile

20 Click to open the **Toolpath Strategies** dialog and select **2.5D Area** Clearance.

Select **Feature Profile** and input the data exactly as shown in the following dialog.




21 Calculate the toolpath and continue the **ViewMILL** simulation (as shown below).






Drill15 - Drilling

- 22 Click to open the **Toolpath Strategies** dialog and select **Drilling**.
- 23 Select **Deep Drill** and input the data exactly as shown in the following dialog.



24 Calculate the toolpath and continue the **ViewMILL simulation** (as shown below).






EM10 - Feature Set Slot




The Y dimension of the existing Block will need to be adjusted to fully, include the Slot Feature.

- 25 Open the **Block** dialog and input **60** for the **Max Y** value before selecting Accept (Do not select Calculate in the Block dialog).
- 26 Activate Feature Group 2.
- 27 Click to open the <u>Toolpath Strategies</u> dialog and select **2.5D Area** Clearance.
- 28 Select Feature Set Profile and input the data exactly as shown in the following dialog.




- 29 Select the **Slot Feature** only and then **Calculate** the toolpath.
- 30 From the local toolpath menu use **Edit** –**Transform Move Toolpaths** to make **2** copies of this **Feature Slot** strategy positioned 5mm away on both sides.
- 31 Rename these toolpaths as EM10-SLOT-RHside and EM10-SLOT-LHside.
- 32 Where necessary use **edit Reorder reverse** to maintain a *Climb milling* direction on these 2 toolpaths.





33 Continue the **ViewMILL simulation** on the last 3 toolpaths (as shown below).



34 Save the **Project**.




Creating Features directly from holes in the Model

As well as being able to use imported **2D geometry**, **Hole Features** can be automatically defined from selected **Holes** in the **3D Surface** or **Solid model**.

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Select File > Import Model:


.....\PowerMill_Data\Models\3Axis-Drilling



3 Save Project As:-


.....\COURSEWORK\PowerMill-Projects\DrilledHoles-Example

- 4 Make sure the **Block** is not defined at this stage, as the top of the **Hole Features** will be created at the nearest Z dimension (Max or Min) of the **Block**.
 This is more than likely to result in some **holes** being created the wrong way up (It is however possible to reverse a Hole Feature).
- 5 Activate the Workplane MC-datum.
- 6 Select the whole **model**.
- 7 In the PowerMill explorer, right-click on Hole Feature Sets and from the local menu select Create Holes.





- 8 Input data into the **Feature** dialog exactly as shown on previous page, and click **Apply**.
- 9 Undraw the **model**.



A **Hole Feature** is created for each of the 33 selected, **Hole** elements within the **model** (including the Chamfers and Counter-bores as separate **Features**).

EXERCISE

- 10 Define suitable tools, then **Drill** and **Counter Bore** the **Holes** using the **Drilling** dialog options.
- 11 Save the Project.



Hole Capping


Hole Features can be used as the basis for capping holes in the 3D **model**. If the intersection of the hole and the top face is non-planar, **PowerMill** will cap the hole with a **surface** that follows the tangency of the surrounding 3D **model**.

Example


The following example illustrates the process of capping cylindrical **Hole Features** defined from a **3D model**.

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Import the model:

.....\PowerMill_Data\Models\Block_with_holes.dgk




- 3 Calculate a Block using Defined by Box and Type Model (In this case the Hole Features will be created upside down).
- 4 Select and **Blank** the top face, and then select the rest of the **model** by dragging a box over it while the left mouse button is depressed.
- 5 Right mouse click on Hole Feature Sets and from the local menu select Create Holes.



6 In the Feature dialogue enter Name root H and select Apply.





In this case the tops of the **Hole Features** are positioned at the shortest distance from the face of the **Block**. This results in all of the **Hole Features** being created upside down.




If the **Block** had <u>not</u> been defined prior to this, then the **Hole Features** would have been created the 'right way up' relative to the Z Axis.

It is also possible to control the resultant direction from within the **Create Holes** dialogue. This is achieved if '**Use active workplane only**' is *ticked* along with selecting the option '**Find holes going down**'.



Any Hole Features that are created to a different orientation from the original Z Axis, will automatically be assigned to a separate Feature Set and associated Workplane.


In this case the holes were deliberately created upside down to demonstrate the **Reverse Holes** editing option.



- 7 Right-click Feature Set 1 and in the menu click Select All and then from the same menu, select Edit > Reverse Selected Holes.
- Finally, Unblank and select the top surface of the Model and in the PowerMill explorer, right-click Feature Set 1 and from the local menu select Edit Cap Holes.




The new **Capping Surfaces** will be generated (Tangential to the selected top surface) in a new **model** called **Capping Surfaces** created along with a new **level** of the same name.



- 9 Click the *light bulb* to undraw **Feature Set 1** (0).
- 10 Expand **Levels** by clicking on the + symbol (2).
- 11 Click the *light bulb* to undraw main surfaces (3).

The new **Capping Surfaces** may be created inside out (Surface Normals reversed). If required they can be selected and from the local **Surfaces** menu, **Reverse Selected** can be applied.





The **Capping Surfaces** are automatically assigned to the new **Level** for easy selection.

- 12 Click on the *light bulb* on the **Block with holes** level to re-display the main model.
- 13 Save Project As:-

.....\COURSEWORK\PowerMill-Projects\CappedHoles-Example



Internal Thread Milling




Thread Milling is included as one of the options in the **Drilling** dialog.

If the **Cycle Type** - **Thread Milling** option is selected, the tool plunges centrally to a specified depth, leads on to the sidewall, and then pitches upwards before leading off.

Within the options it is possible to apply a number of passes (stepping outwards by an allowance value) to avoid tool overload. It is also possible to choose either a Right Hand or Left Hand thread.

- 1 Select File > Delete All and Tools > Reset forms.
- 2 Open the Project:

....\PowerMill_Data\Projects\ThreadMILL_2014-Start




3 Select File > Save Project As:

.....\COURSEWORK\PowerMill-Projects\ThreadMILL-Example1


- 4 Activate the *Thread Milling* tool named M40-Coarse-Pitch-5.
- 5 Activate the **Hole Feature Set** named **Pocket** (This defines the large central hole).



- 6 Select **Toolpath Strategies** and in the **Strategy Selector** dialog, select the **Drilling** tab followed by the **Thread Mill** option.
- 7 In the **Drilling** dialog set both **Radial** and **Axial Thickness -3**, **Pitch 5**, **Name M40-RH-IntThread**, leaving all other parameters as default (shown below).




- 8 Select the **Cutter Compensation** page.
- 9 Tick the **CNC cutter compensation** box and select **Type Tool wear**.




10 Calculate the toolpath and then Close the dialog.





- 11 Calculate a new Block using **Defined by** Box and **Type** Model.
- 12 Right-click the **NC Program** *MC-All* and in the local menu select **Simulate** from **Start**.
- 13 Open a new **ViewMILL** session and run a simulation of all toolpaths. (Do not activate any of the toolpaths, otherwise the current **Block** will become oversize).



The completed **ViewMILL** simulation is as shown above.


14 Disconnect ViewMILL from the simulation (but do not apply Exit ViewMILL), and return to the PowerMill window.

External Thread Milling


- 15 Activate the **Feature Set** named **Boss** (This defines the outside of the central boss).
- 16 Select Toolpath Strategies and in the Strategy Selector dialog, select the Feature Machining tab followed by the Feature External Thread Milling option.



17 In the dialog, set both *Radial* and *Axial* Thickness -3, *Pitch* 5, *Name* M40-RH-IntThread, leaving all other parameters as default (as shown below).



- 18 Calculate the form and then Close the dialog.
- 19 Re-open and re-connect the **ViewMILL** session and run a **simulation** of the latest toolpath **M40_RH-ExtThread**.



20 Select File - Save Project.



2D Curve Machining

PowerMill contains 3 strategies that directly machine relative to 2D **Pattern** segments. These include:


- 2D Curve Area Clearance.
- 2D Curve Profile.
- Chamfer Milling.

There is also a dedicated **Face Milling** strategy that calculates relative to the **Block** dimensions.


Example 1

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Open the Project:

.....\PowerMill_Data\Projects\2DCurve-2015mc-Start




- 3 Select File > Save Project As:
 -\COURSEWORK\PowerMill-Projects\2DCurve-Machining
- 4 Activate the **Pattern** named **CurveAll**.
- Calculate a Block using Defined by Box and Type Active Pattern (Do not close the dialog).
- 6 In the **Minimum Z** co-ordinate box input **-22** before selecting **Accept** to close the dialog.






- 7 Select Rapid move heights and in the Safe area dialog select Calculate.
- 8 Activate the **Face Milling** tool named **D50T6**.
- 9 From the Curve Machining options select Face Milling and enter data into the dialog exactly as shown below.




- 10 In the *Toolpath connections* Links page, set *1st choice* as Circular Arc and Apply constraints ticked with Distance < 40.
- 11 Click **Calculate** to create the toolpath and then **Close** the dialog.






- 12 Activate the Tip Radiused tool named D16T3.
- 13 In the **Curve Machining** options select **2D Curve Area Clearance** and enter data into the form exactly as shown below.



14 Select the *Cut distances* page and input **Stepdown 5**.






15 In the Leads and Links – Lead in page select:-

1st choice > Ramp

Ramp Options > Follow Circle - Max zig angle 4 - Circle diameter (TDU) 0.65

16 From the main Curve area clearance page, Curves definition, select Interactively modify machinable sections.


These options enable the user to have full control of direction of cut and the areas to be machined.






While the **Curve Area Clearance** form is open, the areas to be machined are displayed as a shaded preview.

- 17 Select to exit the **Interactively modify machinable sections** toolbar.
- 18 Select **Calculate** to create the toolpath and then **Close** the dialog.






- 19 Activate the End Mill named EM16.
- 20 From the **Curve Machining** options select **2D Curve Profile** and enter data into the dialog exactly as shown below.



21 Select the Cut distances page and input Stepdown 25.




- 22 Select the **Lead in** page and for **1st Choice** select **Pocket Centre** and then select **Make the lead outs the same as the lead ins** option .
- 23 Click Calculate to process the toolpath and then Close the dialog.






For the leads to work in this case it is necessary to apply **Edit** - **Move Start Points**




- 24 Activate the *Chamfer Tool* named **D25Tr1A45**.
- 25 From the **Curve Machining** options select **Chamfer Milling** and enter data into the dialog exactly as shown below (Do not select Calculate yet!).






26 Select the Cut distances page and input Number of cuts as 1.



27 Click **Calculate** to process the toolpath (Do not close the dialog).



The resultant **Chamfer milling** strategy has appeared (incorrectly) on the outside of the **Pattern** segments.


The toolpath needs to be recycled with the **Chamfer Milling** tool tracks changed to appear on the inside of the **Pattern** segments.

- 28 In the **Chamfer milling** dialog, select the **Recycle** icon to enable changes to be made to the above strategy.
- 29 Select Interactively modify machinable sections to access the *Edit Machinable* Sections toolbar.
- 30 Select the **Reverse machining side** option, followed by to accept the changes and close the toolbar.




31 In the main **Chamfer milling** dialog, select **Calculate** to create the toolpath and then **Close** the dialog.







The ${\it Chamfer\ milling\ }$ options selected result in the angled part of the tool overlapping the base of the chamfer by 1mm.



A 3D ${\bf model}$ of the finished component has been imported to provide a visual check of the ${\bf Chamfer\ machining}$.









Cutter Compensation Example


Where applicable a **Cutter Compensation** page is available in a **2.5D Machining Strategy** dialog **explorer** options.

- 1 Select File Delete All and Tools Reset forms.
- 2 In the **PowerMill** explorer right click on **Patterns** and from the local menu select **Create Pattern**.
- 3 Rename the **Pattern** as **Profile1**.
- 4 Right click on the new **Pattern** and from the local menu select **Curve Editor**.



5 Select **Rectangle** from the lines options.






In the data input box (below the graphics area) input **0** to set the 1st corner of the rectangle, followed by **100 50** to define the X Y dimensions.




The numerical input is absolute in this case but if it is required to use relative numerical input click on the icon to toggle it to this.

- 7 Select **Rectangle** from the lines options again to deselect it.
- 8 Select the *green tick* to close the **Curve Editor** and accept the rectangular **Pattern**.
- 9 Create a Dia 10 End Mill named EM10.
- 10 Calculate a Block using Defined by Box and Type Active Pattern.
- 11 Input the value *Min Z* as -20 and then lock both *Min Z* and *Max Z* values.
- 12 Input **Expansion 15** and then select **Calculate** to add stock to the X and Y dimensions of the **Block**.






- 13 Select Rapid Move Heights and in the Safe Area dialog select Calculate.
- 14 In the **Strategy Selector** form select the **Curve Machining** options.
- 15 Then select the **2D Curve Profile** strategy and enter data as shown in the following illustration.



16 Select the **Cut Distances** page and input **20** for both the **Stock depth** and the **Stepdown**.




17 Return to the Curve Profile page and select the Edit Machining Sections options.



18 If required, select **Reverse machining side** to move the profiling pass to the outside of the **Pattern**.






The above preview shows the cutter being switched from the inside to the outside of the **Pattern** prior to calculating the toolpath.



This toolpath will not contain any data that relates to **Tool Compensation** output.

- 19 Select the *green tick* to accept the changes and exit **Edit Machining Sections**.
- 20 Calculate the Curve Profile toolpath.




21 Open the Leads and Links form and select Lead in – Horizontal Arc – Angle 110 and Rad 10.



- 22 Copy the Lead In settings to Lead Out.
- 23 Select Lead Extensions and input an Extended move of 10 for both Extended move in and Extended move out.
- **24 Apply** the **Lead ins** and **Lead outs** settings to the active toolpath.
- 25 Right click on the active toolpath (**EM10-Profile-NoComp**) and from the local menu select **Settings** to open the **Curve Profile** dialog.
- 26 Once the **Curve Profile** dialog is open select the **Make a Copy** option.
- 27 Rename the new toolpath as EM10-Profile-FullComp.



28 Select the Cutter Compensation page, tick the CNC cutter compensation box, and select *Type* as Full radius.




- 29 Calculate the new Curve Profile toolpath, but do not close the form.
- 30 To test the validity of the applied tool compensation the **Toolpath** toolbar needs to be active (**main** pulldown menu:- **View Toolbar Toolpath**).



31 In the Toolpath toolbar select the Draw compensated toolpath option.






If **Full Compensation** is successfully applied it is displayed as a **thicker** green toolpath but offset inwards to the same **XY** dimensions as the **Pattern** (If the toolpath is displayed in red then the compensation is not geometrically valid).






- 32 Select the Make a Copy option again.
- 33 Rename the new toolpath as **EM10-Profile-WearComp**.
- 34 Select the Cutter Compensation page, tick the CNC cutter compensation box, and select Type as Tool wear.



- **35** Calculate the new Curve Profile toolpath, and then Close the dialog.
- **36** In the **Toolpath** toolbar select the **Draw compensated toolpath** option.





If **Wear Compensation** is successfully applied it is displayed as a **thicker** green version of the original toolpath.


37 Save Project As:-

.....\COURSEWORK\PowerMill-Projects\ToolCompExample



Viewing the NCData output files for a heid controller


38 In the PowerMill explorer, right mouse click on NC Programs and from the local menu select Preferences.



- 39 Open the folder containing the **Machine Option File** and from the list select the file **Heidenhain_3axis_ref.pmoptz** and click the **Open** tab.
- 40 Close the **NC Preferences** dialog.
- 41 In the **PowerMill** *explorer* right mouse click on **Toolpaths** and from the local menu select **Create Individual NC Programs**.
- 42 Right mouse click on NC Programs and from the local menu select Write All.
- 43 Minimise the **PowerMill** window to access the **Desktop** options and select **File explorer**.



44 Once the *File Explorer* has opened browse to C:\temp\NCPrograms.



- 45 In Windows explorer, right mouse click on an NCdata output file and from the local menu select Open with WordPad.
- 46 Repeat for all of the NCdata output files and compare the output.



Full Compensation

```
39 L M03
42 ; WORKPLANE : World
43 ;======
44 CYCL DEF 32.0 TOLERANCE
45 CYCL DEF 32.1 T0.01
46 CYCL DEF 32.2 HSC-MODE:0 47 L M09
18 L X50.0 Y25.0 F MAX
49 L Z10.0 F MAX
50 L X-15.443 Y-23.896 R0 F MAX
51 L 25.0 F MAX
52 L Z-20.0 FQ1
53 L X-4.267 Y-24.201 RL FQ2
54 CC X-10.607 Y-10.607
55 C X0.0 Y0.0 DR+
56 T. Y50.0
57 L X100.0
58 L Y0.0
59 L X0.0
60 CC X-10.607 Y-10.607
61 C X-24.201 Y-4.267 DR+
62 L X-23.896 Y-15.443 R0 63 L Z10.0 F MAX
64 L M09
65 L M05
66 CYCL DEF 32.0 TOLERANCE 67 CYCL DEF 32.1
68 L M30
70 END PGM EM10-Profile-FullComp MM
```

Wear Compensation

```
39 L M03
: EM10-Profile-WearComp
42 ; WORKPLANE : World 43 ;======
45 CYCL DEF 32.1 T0.01
46 CYCL DEF 32.2 HSC-MODE:0
47 L M09
40 L X50.0 Y25.0 F MAX
49 L Z10.0 F MAX
50 L x-15.443 Y-23.896 R0 F MAX
51 L Z5.0 F MAX
52 L Z-20.0 FQ1
53 L X-6.38 Y-19.67 RL FQ2
54 CC X-10.607 Y-10.607
55 C X-3.536 Y-3.536 DR+
56 CC X0.0 Y0.0
57 C X-5.0 Y0.0 DR-
58 L Y50.0
59 CC X0.0 Y50.0
60 C X0.0 Y55.0 DR-
61 L X100.0
62 CC X100.0 Y50.0
63 C X105.0 Y50.0 DR
64 L Y0.0
65 CC X100.0 Y0.0
66 C X100.0 Y-5.0 DR-
67 L X0.0
68 CC X0.0 Y0.0
69 C X-3.536 Y-3.536 DR-
70 CC X-10.607 Y-10.607
71 C X-19.67 Y-6.38 DR+
72 L X-23.896 Y-15.443 R0
73 L Z10.0 F MAX
74 L M09
75 L M05
76 CYCL DEF 32.0 TOLERANCE
77 CYCL DEF 32.1
70 L M30
80 END PGM EM10-Profile-WearComp MM
```



The output file using Full Compensation is exactly matching the geometry of the 100 X 50 rectangular Pattern.



The output file using Wear Compensation is offset by 10mm (the cutter radius) outside the 100 X 50 rectangular Pattern.


47 Save Project As:-

.....\COURSEWORK\PowerMill-Projects\ToolCompExample

Protected Cutter Compensation



With **Type** – **Full radius** selected any internal (concave) corners will require a suitable <u>Minimum radius</u> value included to allow for corner radii that are less than the required full offset value.






2D Curve Machining Example – Inc. Clamp Avoidance

- 1 Select File > Delete All and Tools > Reset forms.
- 2 Open Project:


.....\PowerMill_Data\Projects\2DCurveProfileSplit-Start



The imported **Project** also contains a Dia25 **End Mill** and a **Pattern** defining the 2D geometry used in the existing 2D Machining Strategy.

3 Select File > Save Project As:

.....\COURSEWORK\PowerMill-Projects\2DCurveProfileSplit-EX1



The existing 2D Curve profile toolpath is clearly passing straight through the defined clamp positions. This will be fixed by applying the Split Section option that is accessed from the 2D Curve Profile form.


- 4 Select a View down Z.
- 5 From the main pulldown menus select, Draw Cursor Tool and Draw Cursor Cross Hair (Or use the shortcuts Crtl T and Ctrl H).
- 6 Ensure that the Pattern OuterForm is displayed (PowerMill explorer, light bulb on).



7 Right click on the toolpath EM25-FullProfile and from the local menu ensure Activate is ticked, and then select Settings.




- 8 Once the **Curve Profile** form is open select the **Make a Copy** option.
- 9 Rename the new toolpath as EM25-SplitProfile.




10 On the Curve Profile page select Interactively modify machinable sections.



11 While the above toolbar is open, move the cursor to a point on the left hand side of the **Pattern** segment, and then right click to open the local menu.



12 From the local menu select **Split Section** and an extra **start and end** point will be created on the **Pattern** at this point.




13 From the main pull down menus select Draw - Cursor - Cross Hair (Ctrl H).






The cross hair will be displayed on the cursor to assist with alignment of start and end point.

14 Using the left mouse key, drag the new **green** - start point along the **Pattern** to a position to the right of the upper left clamp (as shown below).



- 15 Locate and drag the corresponding **red** end point to a position to the right of the lower left clamp (as shown above).
- 16 Repeat the process on the other (Left hand) span and drag the start and end points to the left hand side of the **Pattern** (as shown above).
- 17 Split the toolpath again twice, to the left of both the upper and lower right clamps (as shown below).




18 Move the new start and end points to form 4 distinct spans along the **Pattern** as shown in the following diagram.




For accurate alignment use the displayed cross hairs and key points.





- 19 Once the 4 new spans have been aligned, select the **green** tick in the **Edit Machining Sections** toolbar to accept the modifications.
- 20 Back in the **Curve Profile** machining form select **Calculate** to process the new **EM25-SplitProfile** toolpath and then **Close** the dialog.




To check visually check the toolpath for collisions, a triangle model of the stock along with the clamps will be imported and used as the **ViewMILL** block.

- 21 Select an ISO1 view.
- 22 Right mouse click on the toolpath **EM25-SplitProfile** in the **PowerMill explorer** and from the local menu select **Simulate from start**.
- 23 Open the Block form and select Defined by Triangles and Coordinate System - Global Transform (See diagram on next page).
- 24 Select the **Load block from file** option and browse to the model:-


....\PowerMill_Data\Triangles\2DCurveprofileSplit.dmt




25 Accept the Block form.



The **Block** will appear as shown below (**Opacity** slider set to full))



26 Connect **ViewMILL** to the toolpath simulation and run with the **Rainbow Shaded Image** option set.



The tool is no longer crashing through the clamp positions.

27 Select File - Save to update the stored Project.





13. NC Programs

Introduction


Once a series of **toolpaths** have been generated their names can be listed in an **NC Program** file to be post processed as an output file for a specific **NC machine control**. Any number of **toolpaths** can be included and reordered as required depending on the limitations of the particular **NC machine** along with the associated post processor.

If the **NC machine** has a tool change facility then **toolpaths** created with different cutter sizes can be included in the same **NC Program**.

If the **NC machine** does not have a tool change facility then only **toolpaths** created with the same cutter can be included in the same **NC Program**.

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Open the 'read only' Project:

.....\PowerMill_Data\Projects\NCProgram-Start



3 Select File > Save Project As:-


.....\COURSEWORK\PowerMill-Projects\NCProgram-ex1



Defined PowerMill Paths – NC Program output

- 4 From the top pulldown menu bar, select **Tools > Customise Paths**.
- 5 In the PowerMill Paths dialog, select NC Program Output followed by Add path to top of list


If not already defined, it is now required to set up a path to where the **Post Processed** files (**NCPrograms**) are to be stored.




In the **PowerMill Paths** dialog, Select **NC Program Output** and (if it is not already displayed) add the new path **C:\Temp\NCPrograms**.



If this method is used the destination folder for **NCPrograms** must exist on your pc otherwise it will not be possible to output the **NCProgram** files.






- 7 Click **OK** to accept and close the above dialog.
- 8 Close the **PowerMill Paths** dialogue.



Use Project On - NC Program output


An alternative method to control the destination for **NCdata** output is to use the **active Project** as the default, destination for outputting **NC Data** files. In the **NCPrograms - Preferences** form, switch **Use Project** to **ON**.



On applying the **Write** command on an **NC Program** a folder named **NC Programs** will be created in the currently active **Project** folder. This will not work if a **PowerMill Project** has not yet been created (**Save Project**).


Setting the NC Preferences

1 In the PowerMill explorer, right-click NC Programs and select Preferences.




In the references dialog, select the folder icon to access the machine tool, Option File list.





3 From the Select Machine Option Filename dialog (below), select the heid426.opt and click the Open tab.



The selected option file translates the output to the correct Machine Tool output format.




It is not unknown to have more than one **Option File** for the same machine tool to allow for different operational requirements.

4 Click **Accept** on the **NC Preferences** dialog.




Creating the NC Program

1 In the **PowerMill** *explorer*, right-click on **NC Program** and from the local menu, select **Create NC Program**.



2 Enter the name Job_646_Top and click Accept.



3 In the PowerMill explorer select the +/- box by NC Programs to toggle the display of the existing NCPrograms.



One or more **Toolpaths** can be added to the active, **NC Program**.


4 Select the **Area Clearance** icon with the left mouse button and keeping it held down drag the mouse to the right (The cursor will display ghosted icons).



5 Continue to drag the toolpath onto the active NC Program, Job_646_Top and release the mouse button. In the PowerMill explorer, NC Programs area select the +/- box by Job_646_Top to toggle a display of the contents (Roughing_16).




6 Drag the other toolpaths into the last file in the active NC program area to maintain the required machining order.




Add to – NC Program (alternative method)

It is also possible to add several toolpaths to the active **NC Program**. In the **PowerMill explorer**, select one or more **toolpaths** and then *Right Mouse Click* on one to open the local **Toolpaths** menu.




Select **Add to – NC Program** and all of the selected toolpaths will be added to the **NC Program** list.

7 Right-click on any of the toolpaths in the current NC Program to access the local Toolpath options, but do not apply any of the options at this stage.






8 Right-click on the **NC Program** (**Job_646_top**) and select **Settings**.





You can open (and edit) the **NC Program** form current by selecting **Settings** from the local right click menu.






Several of the settings assigned to a specific toolpath can be changed in the above dialog. The toolpath row is selected and relevant values (Tool Number, Coolant, etc) are then modified before clicking **Apply**. These local edits do not affect the original toolpath.

9 Click Accept.




10 Right-click on the NC Program, Job_646_Top and select Write to create the Post-Processed output file.

During the translation an **Information** window appears containing a progress report.




Newly created **Toolpaths** are automatically added to the **Active NC program**. It can be useful to **Create** and **Activate** an **NC Program** prior to toolpath creation to save having to drag them in later as a separate operation.

- 11 De-activate the **NC Program**, **Job_646_Top** in the **PowerMill explorer**.
- 12 Activate the existing Dia 10 Ball nose tool named 10_B.
- **13 Calculate** a **3D Offset Finishing** toolpath, named **3Doffset-test1** using the settings and values as shown below.










It is not always required to output all **toolpaths** in one **NC Program**. As a result it is possible to create an **NC Program** directly from an individual **toolpath** entity.

14 Right-click on the **toolpath** named **3Doffset-test1** and select **Create Individual NC Programs**.



15 A new **NC Program** is created. Select the + symbol to the left of **NC Program** 1 to access its contents (the + symbol will change to a - symbol).





The **NCProgram** icon for **3Doffset-test1** will remain blue until the output file is processed (**Write**). The icon will then turn to green.



Viewing the NC-Data output

Once Post-processed, the **NC Data** output file can be viewed directly from the local menu.

Right-click on the NC Program, Job_646_top and from the local menu, select
 View File.




An **Information** dialog will open to enable the user to view (but not edit) the contents of the NC Data output file.

Manually Editing the NC-Data output

If the user needs to edit the code manually, then the NC-Data output file will have to be edited in Wordpad.

- 1 From Windows Explorer, browse to C:\temp\NCPrograms to where the NC-Data files are downloaded.
- 2 Right-click on one of the NC-Data files and from the local menu, select Open With > Wordpad.



3 From the main (top) toolbar select File > Save to update the Project followed by Close.




14. Setup Sheets

Introduction

All the Setup data required from a **PowerMill Project** such as **cutter definitions**, **images** and **information** relating to **toolpaths** can be downloaded as **HTML files** and then printed out as required. This is essential for the CNC Operators who will be running the programs.

- 1 Select Delete > All and Tools > Reset forms.
- 2 Open the Project:


.....\PowerMill_Data\Projects\SetupSheet-Start



3 Select Save Project As:

.....\COURSEWORK\PowerMill_Projects\SetupSheet-ex1


From the main pulldown menus select Tools > Options > Setup Sheets > Setup Sheets, and tick the box Load Setup Sheets with Project.



5 Accept the form.



6 From the main pulldown menus select File - Project Settings to open the following dialogue.




7 Input **Customer**, **Part Name**, and **Order Number** details as shown above and then **Close** the dialogue.




There are 2 other tabs for the user to input additional information as **User Defined Settings** and **Project Notes**.

- **Activate** one of the toolpaths to reinstate the original setup (Block, Workplane, Rapid Move Heights, etc).
- 9 Ensure that no tools or toolpaths are visible and only the shaded model and wireframe Block (minimum Opacity) are displayed in an ISO 1 view.






10 Right-click on the NC Program named MC-All and from the local menu select Setup Sheets > Project Snapshot > Current View.



An image of the model has now been captured and will be automatically used on the front page of the setup sheet.

- 11 Undraw the model leaving the Workplane and wireframe Block as the only displayed items.
- 12 Right-click on the NC Program MC-All again and select Setup Sheets > Snapshot > All Toolpaths > ISO View.



Images of all the **toolpaths** in the selected **NC program** have now been captured.

Each toolpath will have a separate page on the Setup Sheet.

13 Right-click on the NC Program - MC-All again and select Setup Sheets - Preview.

This action will create the **Setup Sheet**, **HTML** files.

The **PowerMill Setup Sheets: Index** is displayed on the left side of the screen.






14 In the above *Index* dialog left click on **Project Setup Sheet-ex1** to display the following sheet.



Once a page has been selected the text will change from red to blue.





15 From the **Index** page select the **Toolpath** and **Summary** pages in turn and view the content.








Each HTML page can be printed out as individual items. Right-click on the page and from the local menu, select **Print Picture**.

The 1st sheet of the **Summary Page** is as shown below.

AUTODESK.		POW	POWERMILL°		
PowerMILL Setup Sheet					
Project	SetupSheet-ex1				
PowerMILL Version	PowerMILL 21.000 CodeBase 1203007				
Page Generated:	02:18 PM on 2016-11-09				
Summary sheet 1 of 2					
Toolpath / TAP File	NC Program	Strategy	Tool		
Roughing_16F C:/Temp/NCPrograms/MC-All.tap		Raster Area Clearance	Type	End Mill	
			Diameter	16	
	MC-All		Tip radius	0	
			Length	80	
			Number	12	
		Raster	Type	Ball Nose	
			Diameter	10	
Semi_Finish_10B C:/Temp/NCPrograms/MC-All.tap	MC-AII		Tip radius	5	
C. Temp/IVOI Tograms/IVIC-All.tap			Length	50	
			Number	14	
		Raster	Туре	Ball Nosed	
Finish_10B C:/Temp/NCPrograms/MC-All.tap			Diameter	10	
	MC-All		Tip radius	5	
			Length	50	
			Number	(14)	
Corner_Finish-6B C:/Temp/NCPrograms/MC-All.tap	MC-All	Along Corner	Type	Ball Nosed	
			Diameter	6	
			Tip radius	3	
			Length	30	
			Number	7	



- 16 Return to the display to show the **PowerMill explorer** again.
- 17 Right-click on the NC Program MC-All and select Setup Sheets > Export.





Export stores all the Setup Sheets as HTML documents into the current Project Folder.

Setup Sheets can be printed internally from PowerMill or externally from the Exported HTML documents.



Customising Setup Sheets

By editing the **HTML** templates it is possible to customise the output of the **Setup Sheets**.


The use of **HTML** editing software is the recommended method to implement changes to the **Setup Sheet** output. There are free downloads available from the web. **Microsoft Word** can also be used but this can give unpredictable results.




Always create a copy of the template document so that the original is still available if things go wrong.

In the following example an alternative template will be substituted into the **Setup Sheet Toolpath Template** search paths.

1 Right-click on the NC Program named MC-All and select the option Setup Sheets > Paths.




2 On the Paths tab select the folder icon in the Toolpath > Write field.






3 Browse to\PowerMill_Data\setup-sheets and Open the Toolpath2.html file (customised template).



- 4 Click Close on the Setup Sheets dialog.
- 5 Right-click on the **NC Program** named **MC-All** select the option, **Setup Sheets** > **Preview** and re-run the **Setup Sheets** using the new template.
- 6 On the Index page select the new page for the toolpath Roughing_16F (Shown below)






15. Specialist Finishing

Projection Machining.

Projection Finishing provides greater control of the projection direction of machining strategies onto a component. Applications include the machining of undercut features using specialist tooling and a more accurate finish for features positioned at complex angles to the tool axis. **Projection Finishing** also provides essential strategies for use with **Five Axis** tool alignment applications.

There are five different strategies **Point**, **Line**, **Plane**, **Curve**, and **Surface Projection**.



The simplest way to understand the principle of projection machining is to regard the first four strategies comparable to beams of light radiating into or away from a defined source (Only the areas visible to the theoretical light source will be machined).

- A Point strategy is similar to light radiating from a single light bulb.
- A **Plane** strategy is similar to light radiating from a rectangular floodlight.
- A **Line** strategy is similar to light radiating from a fluorescent tube.




- A Curve projection strategy is similar to light radiating from a curved neon tube.
- A Surface projection projects the tool Inwards or Outwards along the normals
 of a selected surface.

In the **Finishing** dialog, the projection **Direction** can be toggled between **Outwards** and **Inwards** from the user defined plane.


In the **Projection Finishing** forms, angular definitions are input using **Azimuth** and **Elevation**. By using a combination of the two any complex 3D angle can be defined.

 Azimuth Angle:- Starting from +X = 0 this is the angle anticlockwise around the Z axis.



This is shown on the chamber model, with a view looking down the Z-axis.

Elevation Angle - this is the upward angle from the XY plane



This is shown on the chamber model, with a view looking down the X-axis.




Plane Projection Example

All five **Projection Finishing** strategies can be used to machine undercut features if used with suitable tooling such as Disc or Spherical. The following example shows an undercut application using the **Plane Projection** strategy.

- 1 Select File Delete All and Tools Reset Forms.
- 2 Select File > Open Project:


.....\PowerMill_Data\Projects\Heatsink-Ucut2-Start



3 Save the Project As:

.....\COURSEWORK\PowerMill_Projects\ Heatsink-Ucut2-EX1


- 4 Activate the toolpath **D25TR3-RGH1** to reinstate the original setup.
- 5 Open the Block form and with Defined by Box and Type Model set select Calculate.
- 6 Simulate the NCProgram (all of the existing toolpaths) in ViewMILL.









7 Return the ViewMILL simulation to the No-Image view



- 9 Activate the D75-H6-T2 Disc Cutter.
- 10 In the **Block** dialog *lock* all 4 of the **X** and **Z** values.
- 11 Calculate the Y values of the Block with an Expansion value of 40.




12 In the **Strategy Selector** - **Finishing** dialog, select **Projection Plane Finishing** and fill in the pages of the dialog exactly as shown below.




The **Location** is the local datum for the projection strategy. All other coordinates entered in the dialog are relative to this point.





The values for the **Start** and **End** heights can be obtained by viewing the model in the **X** direction and using the cursor position to display **Z** values at the bottom right of the screen.






The **Projection Plane > Preview** is displayed as shown and the user can dynamically alter the view to visually check for potential adjustments.

When using projection finishing, (**Point**, **Line** or **Plane**), the **Anchor Point** must be positioned (along the projection direction) away from the model by at least the cutter radius.

14 Select Calculate to create the toolpath and then Close the dialog.






Observe that the tool is **gouging** through the fins when it retracts at the end of each pass. This is confirmed by the **red** toolpath, icon displaying an exclamation mark in the explorer.



In this case suitable **Leads and Links** will be applied to easily rectify the problem.


1 Open the **Leads and Links** dialog and select the **Lead in** tab.






2 Input the following in the **Lead in** page:

1st Choice - Straight Distance 45 Angle 0





4 Apply and Accept the dialog.



The toolpath **Lead** moves are now updated and the **red warning** icon in the **PowerMill explorer** has automatically updated to **white**.


5 Save, but do not close, the **Project** as it is to be continued in the next section.

Surface Projection Example

Surface Projection will be used for the **finishing** strategy as it will provide a consistent **stepover** within the undercut regions. To allow this a specially created, single, **reference surface** will be imported (To create this surface the user would require the services of a suitable CAD package such as **PowerSHAPE**). The **reference surface** does not necessarily have to represent the true shape of the finished component. In practice it could be positioned inside, outside, or flush with the actual model surfaces to be machined. In this example the **reference surface** is flush with the existing model.

1 **Import** the additional **model**:

.....\PowerMill Data\models\heatsink-ref.dgk



The new imported surface appears as a separate item in the **Models** section of the **PowerMill** explorer. This will be useful when selecting it as the **reference surface** to be used with the **Surface Projection** dialog.




2 From the main pull down menus select View - Toolbar - Command to open the command input window below the graphics area and type in the following 3 lines:-

EDIT SURFPROJ AUTORANGE OFF

EDIT SURFPROJ RANGEMIN -1 EDIT SURFPROJ RANGEMAX 1

This is to restrict the tool projection distance to within 0.5mm of the reference surface. Otherwise it would be projected from infinity onto non-undercut faces on the outside of the model.






The default setting is restored by typing:-


EDIT SURFPROJ AUTORANGE ON


- 3 From the Toolpath Strategies dialog, select Projection Surface Finishing.
- 4 In the **PowerMill** *explorer*, right-click the model, **Heatsink-ref** and from the local pull down menu click **Select Surfaces**.






5 In the Surface Projection Finishing dialog input the settings and data exactly as shown below.






- 6 Select Ordering as One way.
- 7 Set the Start Corner as: Max U max V
- 8 Select Preview.





The **Preview** pattern for the strategy is displayed on the **reference surface** (for clarity, a stepover value of 3 was used in this illustration).

9 Calculate the toolpath and then **Close** the dialog.





The unidirectional toolpath is shown here without the defined **Leads and Links** displayed.

A suitable **Lead In** and **Lead Out** must be applied to prevent the tool from **gouging** through the overhang.

The application of **Surface Projection** Finishing has produced a strategy with a consistent **stepover** across all of the undercut areas.

10 Select **File** > **Save** to update the stored **Project**.



Line Projection Example

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Select File > Open Project:


.....\PowerMill_Data\Projects\ucut_proj

3 Select File > Save Project As:

.....\COURSEWORK\PowerMill-Projects\Line-Projection

4 Select an **ISO 3** view.


The imported **Project** (training_ucut_proj) contains a **Model**, **Tooling**, **Roughing**, and **Semi-Finishing** strategies with **1** and **0.3 thickness** values respectively. The undercut regions have not yet been machined.



5 Activate the **toolpath** (**Rough**) to reinstate the settings and then simulate both existing toolpaths in **ViewMILL**.

Tipped Disc cutters will be used for machining the undercut areas. The toolpath will be created by projecting a suitable strategy inwards, towards a vertical line, located at the lower, left corner.

- 6 Disconnect the **ViewMILL** session and select a **View from Top (Z)**.
- 7 Place the cursor over the lower left, corner point without clicking and read the X & Y values from the information toolbar located below the graphics area.






The **Intelligent Cursor** will accurately lock onto the corner providing accurate coordinate values.






- 8 Activate the TD30 cutting tool.
- 9 From the **Toolpath** strategies dialog, select **Projection Line Finishing**.
- 10 Fill in the pages of the strategy dialog exactly as shown below.




The values for the **Start** and **End** heights were obtained by dynamically moving the cursor over the model to obtain the **Z** values in the **cursor coordinate boxes** at the bottom right of the graphics area.




11 Select Preview.



The **Preview** shows the location of the **projection line** with **arrows** showing an inward projection direction from the **pattern**.



12 Calculate the toolpath and then **Close** the dialog.




The tool is currently **gouging** through the overhang at the end of each pass.

This is indicated by the red colour of the toolpath icon as displayed in the **PowerMill** *explorer*.



13 From the main toolbar select Leads and Links to access the Lead in dialog.





14 Input the following information:

1st Choice > Horizontal Arc

Distance > 5


Angle > 90

Radius > 10

15 Select the Lead out the same as lead in tab.



16 Click Apply and then Accept to close the dialog.





The **extension** value in **Leads and Links** must be greater than the tool radius to prevent gouging during the link moves.

The **red** warning icon in the **PowerMill explorer** will now have changed to **green**.

17 Select **File** > **Save** to update the stored **Project**.




Point Projection Example


- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Select File > Import Model:
 -\PowerMill_Data\Models\radknob.dgk
- 3 Select File > Save Project As:
 -\COURSEWORK\PowerMill Projects\PointProj-ex1
- 4 In the **PowerMill** explorer, right-click **Workplane 1** and from the local menu select **Activate** followed by **Workplane Editor** to display the following toolbar:



5 From the toolbar select **Twist about Y** to open the **Twist** dialog.




- 6 In Angle, enter 180 and click Accept.
- 7 Click the **Green** tick to accept the changes and close the toolbar.
- 8 Select an ISO 1 view.




The **Workplane** is rotated **180** degrees about **Y** to provide vertical machining access to the inner wall. However, machining is currently impossible due to the pocket being shielded by an untrimmed planer **surface** (shown part shaded). This example will apply **Component Thickness** options to set this **surface** to be **ignored** while applying the machining strategy.

- 9 Create a Dia 16 ball nosed cutter named BN16.
- 10 Calculate a Block using Defined by Box and Type Model.
- 11 Calculate the Rapid Move Heights using the default settings.
- 12 From the Strategy Selector dialog, select Projection Point Finishing.









13 Fill in the page of the dialog exactly as shown above and select **Preview** to observe the **Point Projection** setup.






14 In the main page of the Point Projection Finishing dialog select the Component Thickness icon and in the dialog select the Surfaces tab.




Click on any of the 8 rows to display a coloured box at the start. In the graphics area, ensure that the only the untrimmed planar, **surface** is selected.







- **15** Click the **Acquire Components** icon to add the selected, planar surface to the row.
- **16** Select **Ignore** in the **Machining Mode** box.
- 17 Apply and Accept the Component Thickness dialog.
- **18 Calculate** the **Projection Point Finishing** toolpath and then **Close** the dialog.



The inside of the pocket has successfully been machined. This would not have happened if the untrimmed surface, blocking access had not been included in a **Component Thickness** list with the **Machining Mode** set to **Ignore**.

19 Select **File** > **Save** to update the stored **Project**.




Curve Projection Example

- 1 Select File > Delete All and Tools > Reset forms.
- 2 Select File Import Model and select:

.....\PowerMill_Data\Models\ crvproj_3D.dgk


(Note the model also includes a wireframe curve running centrally along the slot).



3 Select File > Save Project As:-

.....\COURSEWORK\PowerMill Projects\CurveProj-Ex1


- 4 Calculate the **Block** using **Defined by Box** and **Type Model**.
- 5 Define a Dia 16 Ball Nosed tool called BN16.
- 6 Calculate **Rapid Move Heights** using the default settings.
- 7 In the PowerMill explorer, right-click Pattern and from the local menu select Create Pattern.
- 8 Select the *wireframe curve* (coloured green) running centrally along the slot on the **Model** (Note; The **Wireframe** view be visible).




- 9 In the PowerMill explorer, right-click on the new Pattern (1) and in the local menu select Insert > Model.
- 10 From the Strategy Selector dialog, select Projection Curve Finishing.




11 Fill in the page of the dialog exactly as shown below and select **Preview** to observe the **Curve Projection** setup.








Visually the **preview** is somewhat of a mess, containing crossovers and loops along the path. The actual toolpath however should not suffer the same problem, with the projection distance to the machining areas being a lot shorter (well before loops or crossovers start to appear).



12 Calculate the Projection Curve toolpath and then Close the dialog.





The **Curve** used as the basis for the strategy will in the majority of cases be created in a CAD package as part of the **Model**. In these cases the imported **wireframe** curve must then be inserted into a **Pattern**.


13 Select **File** > **Save** to update the stored **Project**.



Swarf Finishing

Swarf Finishing is specifically designed to machine across one or more surfaces where a linear transition exists along the tool alignment direction. It will not work where the surface transition is concave or convex.

For 3 Axis applications the tool axis must be set to **Vertical**.




The strategy can be set to create either single (default) or multiple passes, exactly following the upper edge, lower edge, or both (merging).

In the following example the Spar sidewalls will be selected and Swarf machined. This will provide a strategy similar in appearance to Constant Z but applied locally to the selected surfaces and guaranteed to run the final pass exactly along the bottom edge (subject to gouge checking).

- 1 Select File > Delete All and Tools > Reset forms.
- 2 From File > Open Project select the (read-only) Project:


.....\PowerMill_Data\Projects\3Axis_SwarfStart1



- 3 From File select Save Project As:
 -\COURSEWORK\PowerMill-Projects\3AxisSwarfExample
- 4 In the **PowerMill explorer**, activate the **workplane** *mc-Datum*.
- 5 In the **PowerMill** explorer, activate the Dia 16 End Mill (EM16).
- 6 Calculate a **Block** using **Defined by Box** and **Type Model**.
- 7 Calculate the **Rapid Move Heights** using the default settings.




- 8 In the PowerMill explorer, click the [+] adjacent to Levels and Sets to access all of the existing Levels.
- 9 Right-click on the Level Swarf-MC and click Select Surfaces from the local menu.




All **Surfaces** on **Level Swarf-MC** will be selected (light blue) to be included in the **Swarf** strategy.


- 10 In the **Strategy Selector**, select the **Finishing** tab, and then select the **Swarf Finishing** strategy.
- 11 Enter data exactly as shown in the following 2 pages of the dialog.







12 Select Calculate to create the Swarf Finishing toolpath and then Close the dialog.







The tool tracks that machine the base of the **selected surfaces** have progressively offset upwards (by the stepdown value) until fragmentation occurs when the upper edge is exceeded. This can be prevented by using, **Mode Merge** instead of **Offset Up**.

- 13 In the **PowerMill explorer**, right-click the **toolpath** *EM16-Swarf_OffsetUp* and select **Settings**.
- 14 Select the *Copy Toolpath* icon from the dialog
 - og 💴.
- 15 Rename the new Toolpath as EM16-Swarf_Merge.
- 16 In the page labelled **Multiple Cuts** change the **Mode** to **Merge** and with all **surfaces** on the **Level Swarf-mc** selected, **Calculate** the strategy.








Merge will use a variable stepdown to exactly track the selected surfaces, upper and lower edges and minimize the number of lift moves.

- 17 Right-click the last **toolpath** *EM16-Swarf_Merge*, in the **PowerMill** *explorer* and select **Settings**.
- 18 Select the *Copy Toolpath*




- 19 Rename the new toolpath as EM16-Swarf_SinglePass.
- 20 On the Multiple Cuts page, change the Mode to Off.





21 With all surfaces on the Level Swarf-mc selected, Calculate the strategy.



- 22 Close the **Swarf Finishing** dialog.
- 23 Select File > Save to update the stored Project.

.....\COURSEWORK\PowerMill-Projects\3AxisSwarfExample




Wireframe Profile Machining

Wireframe Profile machining is designed to machine to the left or right of the selected *curves* of a 3D Wireframe. The following example is a pressing that requires the outer form and recesses to be finish profiled. As the main imported model is in STL (triangle) format it is incompatible with **Boundary** options that operate on *selected surfaces*. It is also impossible to create the necessary 3D Wireframe curves direct from the STL model in PowerMill. To resolve, the stored 3D Curves will be imported into a pattern to be applied in the Wireframe Profile Machining strategy.

- 1 Select File Delete All and Tools Reset Forms.
- 2 Select File and Import the Model:

.....\PowerMill_Data\Models\3D-Curve-TriModel.stl




- 3 Select File > Save Project As:
 -\COURSEWORK\PowerMill-Projects\3D-WireframeProfile
- 4 Create a Dia 5 End Mill named **EM5**.
- 5 Create an empty Pattern, right-click on it, and from the local menu, select Insert > File:
 -\PowerMill_Data\Models\3D-Curve-Wire.dxf
- 6 Rename the Pattern as 3Dwire.
- 7 With the left mouse click on the **model** to select it.
- 8 In the PowerMill explorer, right-click on Workplanes and from the local menu, select Create and Orientate Workplane - Workplane at Bottom of Selection.
- 9 Rename the Workplane as MC-Datum.
- 10 Right-click on the **Workplane** (**MC-Datum**) and from the local menu, select **Workplane Editor** to open the **Workplane Editing** toolbar.




11 Click **Twist about Z** 💴 to open the following dialog.






- 12 Enter the value 90 and click Accept.
- 13 Click on the Workplane Editor toolbar to accept the changes and Close.
- 14 Activate the workplane (MC-Datum) and select an ISO 1 view.





The changes will not be physically active until the **Workplane Editor** toolbar has been **closed**.


- 15 Calculate a Block using *Defined by Box* and *Type Model*.
- 16 Lock the Maximum Z value only and then input an expansion value of 10 before re-selecting Calculate.






The final task prior to machining is to check the directions of the **Pattern** segments and to **reverse** any that will cause the tool to machine on the wrong side of a profile.

17 Right-click on the **Pattern** (*3Dwire*) and from the local menu, select **Instrument** to display directional arrows on the individual segments.



Two of the segments (indicated above) must be reversed for the **Wireframe Profile Machining** to *Climb Mill* to the left of the direction while remaining inside the aperture forms on the **STL model**.


18 Select the 2 **segments** (arrowed on the previous diagram) and from the local **Pattern** menu apply **Edit** > **Reverse Selected**.



- 19 Calculate the Rapid Move Heights using the default settings.
- **20** Select the **Strategy Selector** and select the **Finishing** tab in the dialog.




21 Select the **Wireframe Profile Machining** strategy and enter data exactly as shown on the following 2 pages of the dialog.




 $\pmb{\text{Curve side}}$ controls which side of the $\pmb{\text{Pattern}}$ segment direction the tool operates.

Axial offset controls the depth of machining below the wireframe curves.



22 Select Calculate to create the toolpath and then Close the dialog.





The **Wireframe Profile Machining** performs the profiling of the Pattern segments in 3D.


23 Select File > Save to update the stored Project.





16 Component Thickness

The **Component Thickness** options enable the user to apply varying **Thickness** and **Machining Mode** options to different parts of the component. These can be pre-defined as default settings in the **Thickness Preferences** dialog ready to copy into individual toolpath strategies. They can also be defined independently within individual toolpath strategies using the **Component Thickness** dialog.



The **Component Thickness** tab allows individual **surfaces** or **solid faces** to be assigned with different **thickness** values (**Axial** and **Radial**) within a **toolpath**.

Other important features in this dialog include the **Machining Mode** options, **Ignore** or **Collision** to control *machining status* on selected parts of the component. This is available from the pull-down list consisting of three options:

- Machine (default) is used to define specific areas of the component to be machined with a different Thickness to that that in the main strategy dialog.
- Collision is used to define areas of the component to be avoided by the machining process (such as a clamp).
- **Ignore** is used to define areas of the component to be made invisible to the machining process so that the toolpath will pass through them (such as a blanking surface used to prevent toolpath moves into a hole or pocket during earlier machining strategies).
- The Component Thickness options are also available in Boundary creation options that include an active Tool as part of the calculation.




Component Thickness Example

Select File > Delete all and Tools > Reset Forms.

From **File > Open Project** select the read-only **Project**:

.....\PowerMill-Data\Projects\CompThic_Start



The **Project** contains an unprocessed **Steep and Shallow Finishing** strategy along with a Dia 8 Ball Nosed tool and all essential parameter settings.


Select File > Save Project As:

.....\COURSEWORK\PowerMill-Projects\CompThickness-1



To make selection easier the **clamp surfaces** will be transferred to a new **Level** (**Clamps**) while the **split surfaces** will be copied to a new **Set** (**Splits**).

In the **PowerMill** *explorer*, create a new **Level** and rename it as **Clamps** and then create a new Set and rename it as **Split**.




With the **clamp surfaces** selected, right-click on the **Level** named **Clamps** in the **PowerMill explorer** and from the local menu select, A**cquire Selected Model Geometry**.



It will be easier to select and **Blank** (**Ctrl J**) all the other surfaces first before simply dragging a box over all of the remaining **clamp surfaces**.






With the **split surfaces** selected, right-click on the **Set** named **Splits** in the **PowerMill** *explorer* and from the local menu select, **Acquire Selected Model Geometry**.


In the **PowerMill** *explorer* switch off the light bulb next to the **Set** named **Splits** (This is to prevent them still being displayed if the light bulb for the **Level** *General* is still switched on).

In the **PowerMill** *explorer*, right-click on the unprocessed, **Toolpath BN8-a1** and in the local menu, select **Settings** to open the **Steep and Shallow Finishing** dialog.



Select **Component Thickness** be to open the following form.







With the **Machining Mode** set to **Collision**, a **Thickness** value of **2** will be applied. At this safe distance the active tool will either **retract** or **profile** around the clamps.

Select the 1st row of the **Component Thickness** table and a square, colour coded symbol (in this case blue) will appear at the start of the row.

With the 1st row still selected, change the **Machining Mode** to **Collision** with a **Thickness** value of **2**.







Switch Select by from Colour to Level or Set.

With **Clamps** selected in the **Levels or Sets** box click to acquire the clamp surfaces to the 1st row of the main dialog, and then **Close** the **Selection** dialog.





The 44 *Clamp Surfaces* are acquired to the 1st row.



Apply the **Component Thickness** dialog to update the settings.




In the above **Component Thickness** dialog, it is not necessary to use the 8 available rows in sequential order.



Select the 2nd row and a square, colour coded symbol (in this case purple) will appear at the start of the row.

In **Smart Selection** select **Splits** in the **Levels** or **Sets** box and click the arrow icon to Acquire them in the second row of the main dialog.


With the 2nd row still selected, keep the **Machining Mode** as **Machine** but with a **Thickness** of **1**.



The **Thickness** value of **1.0** will control how much stock is left on the acquired **split surfaces** for this strategy.




This is in addition to a Thickness value specified in the main machining strategy dialog. In the above Component Thickness dialog the sum of these is displayed in the Total Thickness column.





Select the 4th row and a square, colour coded symbol (in this case orange) will appear at the start of the row.




The *cap surface* must be ignored during the creation of this toolpath.

With the 4th row still selected, change the **Machining Mode** to **Ignore** with a **Thickness** value of **0**.

Use the left mouse key to manually select the cap surface and click on **Acquire**Components to include it in the 4th row.

Apply the Component Thickness dialog.




While the **Component Thickness** form is open, **Toolpath Thickness Shade** mode will be active. Acquired **surfaces** are shaded in the same colour as the row.






In the **Viewing** toolbar select the **Toolpath Machining Mode** Shade.



This time, relevant parts of the **model** are colour coded in **Red** (**Ignore**) or **Yellow** (**Collision**). Where applicable, these colour codes also appear at the end of a row.

Accept the Component Thickness dialog.

Select **Calculate** to create the toolpath and then **Close** the dialog.



Select **File** > **Save** to update the stored Project.


Do not close the **Project** as it will be continued in the next section.




Cloning the Component Thickness settings from an existing Toolpath

A **Corner Finishing** strategy **BN5-a1** will now be created using 'cloned' **Component Thickness** settings as used in **BN8-a1**.


From the **Toolpath Strategies** select the **Finishing** option, **Corner Finishing**, and input settings exactly as shown below:





Select **Calculate** and have a look at the resultant toolpath in the graphics area.






For the moment the **Corner Finishing** strategy is unable to access the base of the central pocket and has also produced unwanted tool tracks around the front edge of the clamps. This will be rectified by *cloning* the **Component Thickness** from the toolpath **BN8-a1**.

Back in the Corner finishing page, select Component Thickness



In the *Clone* area of the form use the downward chevron to display and then select the toolpath Bn8-a1.



Select the **Copy Thickness Data** icon to **Clone** the **Component Thickness** settings into the dialog.




The **Component Thickness** settings originally used in **BN8-a1** are now **cloned** into the strategy dialog for **BN5-a1**.



The process is not complete until the **Apply** button has been clicked.

Select **Apply** followed by **Accept** to fully update the **Component Thickness** settings in the strategy **BN5-a1**.

Calculate the **Corner Finishing** strategy and then **Close** the dialog.



Select File > Save Project.

This will update:-

.....\COURSEWORK\PowerMill-Projects\CompThickness-1




Modification of existing strategies to allow for interchangeable clamping bolts.

The following **Project** already includes some **Strategies** to create the 3D component form on a pre-machined material **Block**. All except the initial **Face Milling** strategy need to be modified to accommodate 2 interchangeable pairs of clamping bolts aligned along X and Y respectively.

Select File > Delete all and Tools > Reset Forms.

From **File > Open Project** select the read-only **Project**:

.....\PowerMill-Data\Projects\CompThic-2_Start



The individual parts (Component Model, Capping Surfaces, Fixture Plate, and Clamping Bolts) are already acquired to suitable **Levels**.

Select File > Save Project As:

.....\COURSEWORK\PowerMill-Projects\CompThickness-2

Select an **ISO 1** view (as shown in the above image).


In the **PowerMill** *explorer*, right mouse click on the *Toolpath* EM25-FaceMill-Top and from the local menu select **Activate** followed by **Simulate** from Start.



Before performing a ViewMILL simulation the Block will be modified to use a model of the pre-machined material.


From the *main* toolbar select the **Block** dialog.






Select **Defined by > Triangles** and **Coordinate System > Global before** selecting the option **Load block from file**.

In the **Open Block from Triangles** dialog browse to:-\PowerMill_Data\Triangles\CompThic-2_Block.stl and select Open.



This **Block** definition is an accurate model of the pre-machined component.

Toggle into **ViewMILL** and select the **Rainbow Shaded Image**. In the **Simulation** toolbar select the **Play** button.



Select the **No Image** option to return to the **PowerMill window** and for the time being disconnect **ViewMILL** from the **Simulation**.




From the main menu select the Block option and in the dialog move the **Opacity** slider all the way to the left (wireframe).

In the Viewing toolbar select the option **Multicolour Shade**.



Activate the Toolpath D16TR3-Rgh1.



This toolpath will be modified to **Ignore** the *purple*, clamping bolts along the X-Axis (These are to be physically removed when this toolpath is run).

This toolpath will also be modified to apply **Collision** status to the **green**, clamping bolts from a 2mm distance.


Right mouse click on the Toolpath D16TR3-Rgh1 and select Settings to open the Model Area Clearance dialog.



In the main page of the Model Area Clearance dialog, select the Component

Thickness dialog


In the dialog use **Smart Selection** to acquire the data stored on the **Level ClampingBolts-X** to one of the colour coded rows.




Set the row with **Machining Mode** > **Ignore**.



Select one of the other colour coded rows and use **Smart Selection** to acquire the data stored on the **Level** *ClampingBolts-Y*.




Set the row with **Machining Mode** > **Collision** with a **Thickness** > **2.0** and then select **Apply**.





The parts of the model acquired to a row will be shaded in the same colour.

Accept the Component Thickness dialog and then Calculate the toolpath.



The updated **toolpath** (**D16TR3-Rgh1**) now runs straight through the **X-Axis** clamping bolt area and clears the **Y-Axis** clamping bolts by a full 2mm.



We now require a copy of the **Toolpath** (**D16TR3-Rgh1**) that locally machines the remainder of the component in the clamping bolt area along the Y-Axis.


Right mouse click on the **Toolpath D16TR3-Rgh1** and select **Settings** to open the **Model Area Clearance** dialog.

Select the *Make a Copy* option and in the **Model Area Clearance** dialog rename it as **D16TR3-Rgh2**.



As the new toolpath is a direct copy, the Component Thickness settings will be exactly the same as in D16TR1-Rqh1.

In the main page tick the **Rest machining** box and then open the **Rest** page of the dialog.



In the above dialog, insert the reference **Toolpath** > **D16TR3-Rgh1** and fill in the other values exactly as shown.


In the main page of the **Model Area Clearance** dialog, select the **Component**Thickness dialog

Swap over the settings between the 2 existing rows (as shown below).



Accept the **Component Thickness** dialog and then **Calculate** the toolpath.





The updated **Rest Roughing**, toolpath (D16TR3-Rgh2) now runs straight through the **Y-Axis** clamping bolts.

Activate the *Toolpath* BN10-Fin1 and then select **Settings** from the local menu to open the **Steep and Shallow Finishing** dialog.



Select the **Re-cycle** option to enable editing to occur.

In the main page of the **Steep and Shallow Finishing** dialog, select the


Component Thickness dialog <u></u>



In the Clone pull down select the Toolpath D16TR3-Rgh1 and the click on the


Copy Thickness Data icon.





Accept the **Component Thickness** dialog and then **Calculate** the toolpath.





The updated **toolpath** (**BN10-Fin1**) now runs straight through the X-Axis clamping bolt area and clears the Y-Axis clamping bolts by a full 2mm.

The next stage is to create a copy of the above **toolpath** (**BN10-Fin1**) that locally machines the remaining areas within the two Y-Axis clamping bolts.

Right mouse click on the **Toolpath BN10-Fin1** and select **Settings** to open the **Steep and Shallow Finishing** dialog.

Select the **Make a Copy** option and in the **Model Area Clearance** dialog rename it as **BN10-Fin2**.



As the new toolpath is a direct copy, the **Component Thickness** all of the current settings will be exactly the same as in **BN10-Fin1**. In this case the required **Component Thickness** settings can be cloned from the **Toolpath D16TR3-Rgh2**.

In the main page of the **Steep and Shallow** Finishing dialog, select the

Component Thickness dialog



In the Clone pull down select the *Toolpath* D16TR3-Rgh2 and then click on

the Copy Thickness Data icon.




Accept the Component Thickness dialog.

In the **Steep and Shallow Finishing** dialog select the **Block** page and lock both the **Min Z** value (-35) and **Max Z** value (0) but do not close the **Block** page.


In the **PowerMill** *explorer*, right mouse click on the **Level** named ClampingBolts-Y and from the local menu click on Select All.






Back in the $\bf Block$ dialog enter an $\bf Expansion$ of $\bf 10$ and $\bf Calculate.$

Unlock the **Z Max** value and manually input the value **-26**.



Finally select **Calculate** at the bottom of the main **Steep and Shallow Finishing** dialog to create the new **toolpath BN10-Fin2**.

Cancel the Steep and Shallow Finishing dialog.




Save the **Project** (but do not close it).



Exercise


Activate the existing Constant Z Finishing toolpath D8TR1-Fin1.



Select **Settings** and **Recycle** on the above toolpath.

Use the **Component Thickness** options to **Ignore** the surfaces on **Level ClampingBolts-X** (purple), and **Machine** with a **4mm thickness** around the surfaces on **Level ClampingBolts-Y** (green).

Calculate the changes to toolpath D8TR1-Fin1.



Select **Settings** and **Make a Copy** of the toolpath **D8TR1-Fin1**.




Rename the copy as D8TR1-Fin2.


Use the **Component Thickness** options to **Ignore** the surfaces on **Level ClampingBolts-Y** (green), and **Machine** with a **4mm thickness** around the **surfaces** on **Level ClampingBolts-X** (purple).

Modify the X dimensions of the **Block** to keep the **Constant Z Finishing** toolpath **D8TR1-Fin2** inside the area already machined with **D8TR1-Fin1**.

Calculate the toolpath D8TR1-Fin2.



In the **PowerMill** *explorer* re-order the **Toolpaths** to keep them grouped for the same pair of clamping bolts.



Save the Project to update:-

.....\COURSEWORK\PowerMill-Projects\CompThickness-2





17. Stock Models


Introduction

A **Stock Model** provides both a visual and physical record of the remaining material after such entities as the material block and selected toolpaths have been considered.

Stock Model Rest Roughing

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Select File > Open Project:

.....\PowerMill_Data\Projects\StockModel_1



3 Select File - Save Project As:


.....\ COURSEWORK\PowerMill-Projects\StockModelExample

4 In the **PowerMill explorer** select **Stock Models** > **Create Stock Model**.




An empty **Stock Model** entity appears in the **PowerMill explorer** and an associated **Stock Model** settings dialog appears in the graphics area.





The default settings for triangulation of the **Stock Model** are displayed. In this case we will modify the settings to create a more accurate Triangle Mesh for the **Stock Model**. Once the **Stock Model** is physically created then these inherent settings cannot be retrospectively altered.




5 Modify the values in the **Stock Model** settings to be exactly as shown above and then **Accept** the dialog.



The displayed settings in the **Stock Model** will change accordingly.

Right mouse click on the toolpath **D20t3-RGH-a1** and from the local menu select Add to > Stock Model.




The toolpath and associated Block are included in the Stock Model tree but at this stage are not calculated.

7 In the **PowerMill explorer**, **Stock Models** area, right mouse click on >1 and from the local menu select **Calculate**.









The **Stock Model** will display the visual effect of toolpath **D20t3-RGH-a1** as a purple wireframe mesh.

- 8 Right-click on Stock Model 1 and from the local menu, select Drawing Options, and then tick both, Shaded and Show Rest Material.
- 9 From the Viewing toolbar, undraw the model (both Shaded and Wireframe).



The **Stock Model** is now displayed as shown with the component model and applied toolpath both taken into account.


This represents the remaining material outside the component form after the taking into account the toolpath **D20t3-RGH-a1**.




10 If the **Block** is made active in the **Stock Model** tree then this is the stage of the machining process that will be displayed.



11 From the Strategy Selector , Finishing options select the Offset Flat Finishing strategy and enter data in the 3 pages exactly as shown below.




- a Add approaches from outside is un-ticked to enable fully independent Leads to be applied.
- **b Allow tool outside flats** is **un-ticked** to limit the toolpath exactly to the X Y dimensions of the **Block**.
- c The Rest Machining box (Rest machining to Stock Model) is ticked to prevent the already finished, upper flat areas from being included in the toolpath.
- d By ticking this option the **Rest** page will become available for selection in the local browser.



12 In the above dialogue select the **Stock Model** as **1**.




13 From the local explorer select the **Leads and Links** options and in the **Lead in** form enter data exactly as shown below.






- 14 Then copy the Lead in options to the Lead out
- **15 Accept** the dialog.
- 16 Calculate the Offset Flat finishing strategy and then Close the dialog.











The latest **Toolpath** - **D20t3-Flats-a1** is automatically added as a reference item in the **Stock Model** list but not as a physical entity.

17 In the **PowerMill** explorer, right-click over the **Toolpath** - **D20t3-FLATS-a1** and in the local menu select **Add to** > **Stock Model**.



18 In the **PowerMill explorer**, right-click on the **Stock Model** named **1** and in the local menu select **Calculate**.




After the calculation, the **Stock Model** will be displayed again only this time with the **Offset Flats Finishing** included.

19 Activate the **toolpath D20t3-RGH-a1** and in the local menu select **Settings...** to open the **Model Area Clearance** dialog.




20 Select **Create a new toolpath based on this one** and input new data into the dialog exactly as shown on the following page.



- 21 Activate the **D10t1** tool.
- 22 Set the Style as Offset model.


Tick the **Rest** machining box.

23 Select the **Rest** page and in **Rest Machining** use **Stock Model – 1**.






24 Select **Calculate** on the **Model Area Clearance** dialog to machine within the limits of the specified **Stock Model**.



- 25 Close the **Model Area Clearance** dialog.
- 26 The latest **Toolpath D10t1-RGH-a1** is automatically added as a reference item in the **Stock Model** list but not as a physical entity.
- 27 In the PowerMill explorer use the left mouse button to drag the Toolpath D10t1-RGH-a1 to the bottom of the list.



- 28 In the **PowerMill** explorer, right-click over the **Toolpath D10t1-RGH-a1** and in the local menu select **Add to** > **Stock Model**.
- 29 In the **PowerMill explorer**, right-click on the **Stock Model** named **1** and in the local menu select **Calculate**.




The **Stock Model** is now displayed as shown with the latest toolpath removed.




Now that the bulk of the material is removed, the main component form is now ready to be finish machined.

- 30 Un-draw the Stock Model.
- 31 **Select** and **Blank** all except the following surfaces:




- 32 Using the left mouse button, drag a box across the model above to select all displayed surfaces.
- 33 Activate the tool BN8.
- 34 In the **PowerMill** *explorer*, right-click on **Boundaries** and in the local menu, select the **Selected Surface** option.




- 35 Enter data exactly as shown above and then **Apply** to create the **Boundary**.
- 36 Check that both Boundary 1 and the BN8 tool are both Active.



- 37 Select the **Toolpath Strategies** and open the **Finishing** page.
- 38 Select the **Steep and Shallow Finishing** option and enter data into the dialog exactly as shown below:



39 Select the **Limit** page and enter data exactly as shown in the following image:




40 Select **Calculate** to create the **Toolpath** and then **Close** the dialog.




41 In the Leads and Links options Apply (1st Choice) Lead in/out as Surface Normal Arc with Angle 90 and Radius 4.



The **Toolpath BN8-FIN-a1** has been limited to be inside the **Boundary**.



- 42 In the **PowerMill explorer**, right-click the **toolpath BN8-FIN-a1** and in the local menu select **Add to** > **Stock Model**.
- 43 In the **PowerMill** *explorer* right-click on **Stock Model 1** and select **Calculate** to update.



The remaining **Stock Model** is displayed as shown above.




Stock Model Rest Boundary

Most of the **Finishing** strategies do not have a direct **Rest Machining** option that relates to the **Stock Model**.

It is however possible to create a **Stock Model Rest Boundary** to define the areas with material left on. This can then be used to limit a finishing strategy such that only the remaining stock is removed.


1 In the PowerMill explorer, right-click on Boundaries and in the local menu select Stock Model Rest.



2 Enter data exactly as shown in the above image and Apply and then Cancel.




Boundary segments will only be created where the **BN4** tool is able to access the model form.




The **Stock Model Rest Boundary** identifies the area of the remaining **Stock Model**.



- 3 Select the **Toolpath Strategies** and select the **Finishing** tab in the dialog.
- 4 Check that the new Boundary BN4-StockModelRest and the BN4 tool are both Active.
- 5 Select the 3D Offset Finishing strategy and enter data exactly as shown below:




6 Select the Limit page and enter data exactly as shown in the following image:



- 7 Select Calculate to create the toolpath and then Close the dialog.
- 8 In the Leads and Links options Apply (1st Choice) Lead in/out as Surface Normal Arc with Angle 90 and Radius 3.





- 9 In the **PowerMill explorer**, right-click the **toolpath BN4-FIN-a1** and in the local menu select **Add to** > **Stock Model**.
- 10 In the PowerMill explorer, right-click on the Stock Model and select Calculate to update.




The **Stock Model** displayed with **Show Rest Material** set will have visually disappeared apart from perhaps, a few tiny, insignificant patches.



If a previous toolpath in the **Stock Model** tree is selected then the status of the material at that point will be displayed.

11 In the **PowerMill** explorer, **Stock Model** - **1** tree, Activate the toolpath named **D20t3-RGH-a1**.






12 In the PowerMill explorer, Stock Model - 1 tree, Activate the toolpath named BN4-FIN-a1.



The **Stock Model** will visually disappear while the **Show Rest Material** option is active.

13 Right-click on the **Stock Model** and in the local menu, switch on (tick) the option **Show All Material**.



The **Stock Model** is now exactly the same shape and size as the **model**.

14 Select File > Save Project to update the stored Project.




Stock Model starting from a complex block.

If a casting is to be machined then it is not possible to directly add the complex shape to a **Stock Model**. It is however possible to import a **Triangle** model of the original casting as the initial **Block** and then use it as the first entity in a **Stock Model**. The **Stock Model** can then be used as the referenced entity in an initial **Rest Roughing** strategy.

On import the **Block** must use the option, *Coordinate System* as **Global Transform** (Exported **Triangle** models do not support **Workplanes**).

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Select File > Open Project:


.....\PowerMill_Data\Projects\StockModelCasting_Start



3 Select File - Save Project As:


.....\ COURSEWORK\PowerMill-Projects\StockModelCasting

4 Open the **Block** form and set **Coordinate System** to **Global Transform**.




5 Select **Defined by** – **Triangles**, select and browse to the triangle model:-C:\Training_Data\PowerMill_Data\Triangles\StockModel-Casting.dmt






- 6 Open the **Rapid Move Heights** form and select **Calculate**.
- 7 Activate the tool D25TR3.
- 8 Create a new Stock Model.
- 9 Right mouse click on the new Stock Model and from the local menu select Settings.




- 10 Edit the dialogue with above values and **Accept**.
- 11 Right mouse click on the new **Stock Model** and from the local menu select **Apply Block**.



The complex **Block** is added as the first entity in the **Stock Model**.

- 12 Right mouse click on the new **Stock Model** and from the local menu select **Calculate**.
- 13 Undraw the Block.
- 14 Right mouse click on the new **Stock Model** and from the local menu select **Drawing Options** and tick both **Shaded** and **Show Rest Material**.






The **model** form is visually removed from the **Stock Model**.

Exercise:

- 15 Calculate a Block of *Type* Cylinder and *Defined by* Model.
- 16 Create a Model Rest Area Clearance Offset Model strategy with the D25TR3 tool, using the Stock Model as the reference item.



The **Area Clearance** - **Rest** strategy is created within the defined volume of the **Stock Model**.



18. Macros & User Menu

Introduction

There are various ways in which the user can customise **PowerMill**. This chapter looks at the creation of:

- Macros
- User Menus

Home Area


The usual method to enable the **User Menu** to be recognised by **PowerMill** is to set up and use a **home** area in **Windows**. This can be located to any convenient area on the hard disk. In the following example the **home** area is:-

C:

To check if a **Home** area already exists on a computer;



- 1 Open the windows File Explorer
- 2 In the local explorer, right-click on This PC and select Properties to open the System dialog.









Alternatively, at the lower left corner of the screen, right mouse click on **Start** and from the local menu select **System**.

3 In the **System** dialog select the **Advanced system settings** option and then in the **System Properties** dialog, select **Environment Variables**.



4 If the home area is not already defined as shown below, select New...



- 5 In the **User Variables** dialog, enter **home** in the **Variable** name field and **C:** in the **Value** field.
- 6 Click OK.



You must have Admin rights to create a **New User Variable**.

If it does not already exist, create a folder named **pmill2** in the required **home** area (C:\pmill2).



If the **pmuser.mac**, **user_menu** and any other **macros** are being stored in this folder, then **PowerMill** will have immediate access through the default **Macro** search paths.



Macros

A **Macro** is a text file, which contains a sequence of commands to drive **PowerMill** operations. These can be created by recording each command or by typing in the commands directly. **Macros** (which have a .mac extension) can then be run from the **PowerMill explorer** or from a **user defined menu**.

When **PowerMill** starts up, it will attempt to identify and run the **initialisation macro** (if it exists!) called **pmuser.mac**. By adding customised **PowerMill** commands to the initialisation macro, the user can set up their own default settings and parameters.

For immediate use a **pmuser.mac** can be placed in the **pmill2** folder, directly below the users **Home** area. The **pmill2** directory is also a convenient location for storing other user-defined **macros** ideally arranged in suitable sub-folders. This will be covered later.


Creating a pmuser macro

Macros are created in **PowerMill** by recording the operations as they occur. Only flags or parameters that are physically changed will be recorded into the macro; therefore to record a value that is already set, it must be re-entered or a flag reswitched. For example, if the finishing tolerance is currently set to 0.1mm, and it is required that the macro stores the same value, then it must be re-entered over the existing copy in the form during recording.

- 1 Select File > Delete All.
- 2 To start recording, right-click on Macros in the **PowerMill explorer** and select **Record**.



3 Save **pmuser.mac** by first clicking on the existing folder displayed in **Save in**.



4 Then, in the resultant dialog, browse to **C:\pmill2** and at the bottom of the dialog enter the file name, **pmuser** before clicking **Save**.







The Macro icon changes to red while recording is in progress




The **pmuser.mac** automatically runs whenever **PowerMill** starts up, thereby providing the user with custom default settings. It can also be run at any time during a session to reinstate the initialisation settings without having to restart **PowerMill**.




All required data or options must be set or selected if they are to be included in a macro (Even if it is necessary to overwrite or switch them off first).

- 5 From the **Main** pull-down menus select **Tools** > **Options**.
- Select Tools > Feeds and Speeds, change the Feed Rate Plunge Factor to 0.2, tick the Auto Load Feed Rate box, and Accept the dialog.




7 Open the Leads and Links dialog and input both Short and Long as Skim, and Default as Incremental.



8 Accept the **Leads and Links** dialog.



9 In the PowerMill explorer, right-click on NC Programs, and select Preferences.




- 10 On the NC Preferences dialog Output page, select the Machine Option File as Heidenhain_3axis_ref.pmoptz.
- 11 Even if already set, select:
 - Use Project On
 - Tool Value Tip
 - Automatic Tool Alignment On
 - Connection Moves Move, Rotate
- 12 Select the **Toolpath** page and even if already set, select:-
 - Tool Change On New Tool
 - Tool Numbering As Specified
 - Tool Change Position After Connection
 - Cutter Compensation: Length Off
 - Radius None
- 13 To save and exit the dialogue select **Close**.




It is important to remember to Accept and not to Apply forms that are opened while creating an Initialisation Macro, the only exception being the creation of NC Program Preferences (An initialisation file is for pre-setting forms but at this stage without executing the commands).

14 Select **Stop** from the local **Macros** menu to stop the recording process.



- 15 Select the plus (+) sign next to **Macros** in the **PowerMill** *explorer* to open the tree.
- **16** Right-click **pmuser**, then select **Edit**.





This is a standard **Wordpad** document that can be edited with new values and then saved.

To prove this is running during **PowerMIII** start up you will need to exit and reopen **PowerMIII**.

17 Select File > Exit and restart PowerMill to check that the settings from pmuser.mac have been activated.

Other Typical Macro Applications

Apart from tailoring **PowerMill** by the creation of an initialisation macro other useful applications include macros for un-draw, draw and resetting **Leads and Links**, locating and inserting tooling **Templates**, setting **NC Preferences**, regularly used machining sequences or settings, and input of preview, commands not yet available on the GUI. Note the pmuser macro can be run through the browser at any time during a **PowerMill** session to restore your settings.

Creating NC Preference macros

1 From the PowerMill explorer, record a macro called Fanuc3Axis_prefs and save it in:-

C:\pmill2\NCpreferences\...


- 2 In the NC Programs > Preferences > Output tab select the Machine Option File as Fanuc_3axis_ref.pmoptz.
- 3 Input the remaining settings exactly as applied earlier for the Heidenhain_3axis_ref.pmoptz in the pmuser macro.
- 4 Stop the Macro recording process.





Even if already set it is essential to re-specify settings if they are to be recorded into the macro.

A macro file (**Fanuc3Axis_prefs.mac**) is now created that sets up **NC Preferences** for a post-processor option file and the command lines are shown below.



Exercise

1 Create two more independent **NC Preference** macros for the Heidenhain 3 Axis and Mazak 3 Axis option files (Use the filenames **Heid3Axis_prefs.mac** and **Mazak3Axis_prefs.mac** respectively for the macros), and save them to:

C:\pmill2\NCpreferences\...



User Menu

In PowerMill it is possible to create a user menu enabling the user to further streamline and customize the command structure. To access the user menu, right mouse click within an empty area of the PowerMill explorer.

1 Right-click in an empty area of the PowerMill explorer to access the current user_menu (if it exists).

This menu is created from a text file called user_menu. It must be in the directory pmill2 in the Home area of the computer for the individual user, and saved as a text file (not a word Document) and with no extension. If available it is easier to obtain a copy of an existing user_menu and modify it as required.

A user menu can be setup to provide easy access to existing PowerMill commands, Macros and Templates.

2 Load the in-active user_menu file (which is in the pmill2 folder) into Wordpad.

Below are instructions for the user_menu command line input (these exist in the sample file).

A command line will be added to the above user_menu to run the **Heid3Axis_prefs** macro.


I "Heid3Axis" 1 "macro NCpreferences\Heid3Axis prefs"

3 Add the above command line to run the **Heid3Axis_prefs** macro directly from the **user_menu**.


This line locates and runs the file **Heid3Axis_prefs.mac** created earlier in this chapter. It needs to include the correct drive and path where the macro is located. All lettering must be in the correct upper or lower case and include the inverted commas and hyphens.

A more complete version of a typical **user_menu** is as shown below:





This is the **user_menu** file as displayed in the **Wordpad**.



Note the **NC-Preferences** section uses a **sub-menu**:

M denotes the start of the sub-menu.

Z denotes the end of the sub-menu.






19. Tutorials

Y-Branch

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Import the Model:-

....\PowerMill_Data\Models\Y-BranchDuct.dgk



3 Save Project As:

....\COURSEWORK\PowerMill_Projects\Y-Branch-MC

4 Create the following Tools:-

Dia 16 with a 3 Tip Radius named D16TR3

Dia 12 End Mill named EM12

Dia 12 Ball Nose named BN12

Dia 5 Ball Nose named BN5


5 Create an **NC Program**.




Newly processed Toolpaths are automatically added to an Active NC Program.



- 6 Activate the existing **Workplane 1**, then using the default settings **Calculate** a suitable **Block**, and **Rapid Move Heights**.
- 7 Create a 3D Model Area Clearance toolpath using the Tool D16TR3.
- 8 Create an Offset Flat Finishing Toolpath on the base of the Y-form using the Tool EM12.
- 9 Create two suitable Boundaries (Selected Surface) to limit the Finishing Toolpaths for the BN12 and BN5 tools. (Note:- For the BN5 tool select all of the end recess surfaces, including the vertical faces, and Tick the box marked Top in the Boundary dialogue).



- 10 Activate the Tool BN12.
- 11 Create a **Constant Z Finishing** toolpath (limited to be inside the **BN12 Boundary**) using both a Min (0.01) and Max (0.5) **stepdown** combined with a suitable Cusp height (0.03) with the Machine down to flats box ticked.
- 12 Activate the Tool BN5.
- 13 Create a suitable **3D Offset Finishing** toolpath (limited to be inside the BN5 Boundary) using a Stepover of 0.25, and with both **Spiral** and **Smoothing** ticked.
- 14 Perform a full ViewMILL simulation on the Active NC Program.




Save the Project.



Corner Bowl

- 1 Select File > Delete All and Tools > Reset Forms.
- 2 Open the (read only) Project:-
 -\PowerMill_Data\Projects\CnrBwl-Start



3 Save Project As:

....\COURSEWORK\PowerMill_Projects\CornerBowl-Example

The **Project** contains; a **Model**, 2 **Workplanes**, 9 **Tools** (including a **Form Tool** along with the **Pattern** used to create it), 7 **Toolpaths** that fully machine the underside (OP1), and an **NC-Program** named **OP1-CnrBwl-All**.

Setup

- 4 Activate the Workplane named MC-Datum-OP2.
- 5 Create a new NC Program named OP2-CnrBwl-All.




The New **NC Program** will be **Active** on creation. Newly processed toolpaths are automatically added to an **Active NC Program**.

- 6 Open the Block dialog and with Defined by Box and Type Model set select Calculate.
- 7 In the Rapid Move Heights dialog enter the Workplane MC-Datum-OP2 and Calculate before selecting Accept.




Area Clearance - Tool D25TR3

- 1 Activate the tool **D25TR3**.
- 2 From the Strategy Selector, open the 3D Area Clearance strategy dialog and select a Model Area Clearance strategy.
- 3 Enter the toolpath name **OP2-D25TR3-RGH1**.
- 4 In the **Limit** page ensure that no **Boundary** is **Active** and then select **Allow** tool centre outside the block



- 5 In the Model area clearance page, use Style Offset model, with Thickness 0.5, Stepover 5, Stepdown 25.
- 6 In the **Offset** page, tick **Spiral**.
- 7 In the Step cutting page, tick Step Cutting and input Step-up 2, Detect material thicker than 0, and Expand area by 0.
- 8 In the Unsafe segment removal page, tick Remove segments smaller than threshold, with Threshold 0.95, and un-tick Only remove segments from enclosed areas.
- 9 In the Flat machining page, set Machine flats to Level.
- 10 In the Approach page, tick Add approaches from outside.
- 11 In both the Lead in/out pages set 1st choice as Vertical arc with Distance 15, Angle 90, and Radius 8.
- 12 For Lead in, 2nd choice select Ramp, and in the Ramp options dialog set Follow Circle, Max zig angle 4, and Circle Diameter (TDU) 0.65.
- 13 Accept the Leads and Links dialog.
- 14 Select Calculate in the main Area Clearance dialog to create the toolpath.
- 15 Close the **Area Clearance** dialog.




The **toolpath** is automatically added to the **Active NC Program** list.




Finish Machining – Tool BN16

- 1 Activate the Tool BN16.
- 2 In the PowerMill explorer select Boundaries Create Boundary Shallow.




3 Enter data exactly as shown above, and un-tick the box Allow boundaries to be private in the Shallow Boundary dialog before selecting Apply.



4 Select and **Delete** all except the 2 innermost **Boundary** segments.






- 5 Right mouse click on the new **Boundary Flat-BN16** and from the local menu select **Curve editor**.
- 6 In the **Curve editor** select the outer **Boundary segment** and apply an **Offset** (2D round) of **2**.




- 7 Select the inner **Boundary segment** and apply an **Offset** (2D round) of **-6**.
- 8 Select the **Green** tick at the far right of the **Curve Editor** toolbar to accept and return the changes back to **PowerMill**.
- 9 From the Strategy Selector, open the Finishing dialog and select a Steep and Shallow Finishing strategy.
- 10 In the Steep and Shallow finishing dialog enter the toolpath name OP2-BN16-FIN1.
- 11 In the Limit page, select the Boundary Flat-BN16 with Trimming set to Keep inside.
- 12 In the **Steep and Shallow finishing** page enter data exactly as shown below.






- 13 For the Leads select Lead in/out 1st choice set Vertical arc with Distance 0, Angle 90, and Radius 8.
- 14 Select **Calculate** in the main **Steep and Shallow finishing** dialog to create the toolpath.
- 15 Close the Steep and shallow finishing dialog.






Finish Machining – Tool EM30

- 1 Ensure that no Boundary is Active.
- 2 Activate the Tool EM30.
- 3 From the Strategy Selector, open the Finishing strategy dialog and select an Offset Flat Finishing strategy.
- 4 In the Offset Flat Finishing dialog enter Toolpath name OP2-EM30-FlatFIN1.
- 5 In the Limit page, select Limit tool centre to block edge




6 In the **Offset flat finishing** page, enter data exactly as shown below (Note the **tick box** settings!).




- 7 In the main Leads and Links dialog select Lead in/out 1st choice set Vertical arc with Distance 15, Angle 90, and Radius 12.
- 8 Accept the Leads and Links dialog.
- 9 Select **Calculate** in the main **Offset flat finishing** dialog to create the toolpath.
- 10 Close the Offset Flat Finishing dialog.






Finish Machining – Tool D16TR3

- 1 Activate the tool D16TR3.
- 2 Select the upper edge of the **Surface Model** 3D form.




3 In the PowerMill explorer select, Boundaries - Create Boundary - User Defined.






4 In the above **User defined Boundary** dialog **un-tick** the box **Allow**





Rename the **Boundary** as **OP2-Form-TopEdge** before selecting **Accept** to close the dialog.




- **6 Select** and **Delete** the inner **Boundary** segment (as shown above).
- 7 From the Strategy Selector, open the Finishing dialog and select a Constant Z Finishing strategy.
- 8 In the Constant Z Finishing dialog enter the Toolpath name OP2-D16TR3-FIN1.



83 2297


Minimum

- 9 In the Limit page select the Boundary OP2-Form-TopEdge with Trimming set to Keep outside.
- 10 In the Limit page Z Limits:-
- 11 Tick the **Minimum** box and use the **picking** option trap and insert the value **-85** (left mouse click within the top of the base surface).
- 12 Tick the **Maximum** box and insert the value **-79** (this is **6mm** above the top of the base surface).
- 13 In the *Constant Z finishing* page, enter data exactly as shown below (Note the tick box settings!).



- 14 In the main Leads and Links dialog:-
 - For the Lead in 1st choice set Surface normal arc with Distance 0, Angle 90, and Radius 8.
 - For the Lead out 1st choice set Vertical arc with Distance 0, Angle 90, and Radius 8.
- 15 Accept the Leads and Links dialog.
- 16 Select Calculate in the main Constant Z finishing dialog to create the Toolpath.
- 17 Close the Constant Z finishing dialog.






Finish Machining - Tool EM16

- 1 Re-open the OP2-D16TR3-FIN1 toolpath dialog and select Create a new toolpath based on this one
- 2 Rename the new toolpath as OP2-EM16-FIN1.
- 3 Activate the tool **EM16**.
- 4 In the **Limit** page, **Z Limits** section, tick **Maximum** and input the value **-82** (this is approx. 3mm above the top of the base surface).
- 5 In the Constant Z finishing page, Stepdown section, enter the data exactly as shown below.




6 Select **Calculate** in the main **Constant Z finishing** dialog to create the **Toolpath**.





Finish Machining – Tool FormTool-1

The 40 Degree angle on top of the step near the bottom of the 3D form will be machined with a **Form Tool**. The profile for the **tool tip** was created from a **Pattern** which in turn was constructed using the **Curve Editor** options.




The **Pattern** must be created in the **+ve X** and **Y** quadrant, relative to the **Transform** (Global Datum) for it to be valid when used in **Form Tool** creation options. Once the **Form Tool** has been created it will no longer be dependent on the **Pattern**.




The above **Tool** and original **Pattern** already exists in the start up **Project**.



- 1 Select a View down Z and un-draw all items except the existing Pattern FormTool-1.
- 2 Zoom into the lower area of the Pattern and from the main toolbar select the Measurer
 .



With the **Measure** tab selected, click on the **Open the position input** option




- 4 In the **Position** dialog select the **Between** tab
- On the Pattern in the graphics area, left click on key point 1 followed by key point 2 (shown above left).
- 6 Make a note of the displayed **End point** values **7.5** and **2.517299**.


Next a new **Pattern segment** will be created along the top, inner edge of the 40 Degree chamfer (corresponding to **key point 2** above). The above values will be used to offset (**7.5**) and move (**Z-2.517299**) the new **Pattern segment** to provide a path for the form tool centre (**key point 1**).




7 Select all of the **surfaces** that form the top face of the step near the bottom of the 3D form (shown shaded light below).



- 8 In the **PowerMill** *explorer* right mouse click on **Patterns** and from the local menu select **Create Pattern**.
- 9 Rename the new Pattern as OP2-Chamfer40Deg.
- 10 Right mouse click on the new Pattern and from the local menu select Insert Model (Pattern segments will be created along the open edges of the selected model).



- 11 Select and **Delete** the outer **Pattern** segment (as shown above).
- 12 Right mouse click on the **Pattern** and from the local menu select **Curve Editor**.
- 13 Select the **Pattern** segment.
- 14 In the Curve Editor toolbar select Offset item (2D Round)




- 15 Input a **Distance** value of **7.5** and press return to accept the action.
- 16 Select the Pattern segment.



17 In the Curve Editor toolbar select Move item.




18 In the Data Input box below the main graphics area enter and return the relative XYZ move values 0 0 -2.517299.



- 19 Select the green tick to accept the changes and return the Pattern to PowerMill.
- 20 Right click on the Pattern, segment and from the local menu select Instrument to display the direction arrow.
- 21 If the arrow is pointing along the upcut direction (anticlockwise if viewed from above) select **Edit Reverse Selected**.

The **Pattern** is now suitably positioned for use as a **tool centre**, **drive curve** to be used in either a **2D Curve Profile** or **Pattern Finishing** strategy.

- 22 Ensure that no **Boundary** is **Active**.
- 23 Activate the tool FormTool-1.
- 24 From the **Strategy Selector**, open the **Curve Machining** dialog and select the **2D Curve Profile** strategy.
- 25 In the 2D Curve Profile dialog enter the toolpath name as:-OP2-FormTool1-Chamfer.






and snap at any point along

- 26 In the Limit page untick both the Z Limits, Maximum and Minimum boxes.
- 27 Set the Position option to The centre of the tool follows the pattern




28 Select the **Pick the lowest Z Height** option the drive curve, **Pattern** *segment*.





The snapped **Z height value** is inserted into the **Lower limit** box.

- 29 In the main Leads and Links dialog select Lead in/out 1st choice set Horizontal arc with Distance 0, Angle 90, and Radius 12.
- 30 Accept the **Leads and Links** dialog.
- 31 Select **Calculate** in the main **Offset flat finishing** dialog to create the toolpath.



The Form tool is accurately aligned to the angle across the top of the step.

32 Close the 2D Curve Profile dialog.




Hole Feature – Drilling

Drilling strategies can only be performed on **Hole Features** and not directly on the component **Model**.



To ensure that the **Hole Features** are created vertical relative to the active **Z axis** the **Block** must first be <u>deleted</u>.




- 1 From the main toolbar select the Block dialog and click on the blue cross to delete the current Block definition.
- 2 Select the whole of the component **model**.
- 3 In the PowerMill explorer, right mouse click on Hole Feature Sets and from the local menu select Create Holes.



4 Enter the data into the **Feature** dialog exactly as shown above before selecting **Apply**.






The **Feature Set** contains a total of **12** defined **Hole Features**.




Most of the **Hole** detail has been dealt with in **OP1** so the only remaining **Features** that require machining from this side are the 2 Counterbores.

- 5 Rename the new Hole Feature Set as OP2-Holes.
- 6 Activate the toolpath OP2-D16TR3-FIN1 to reinstate the Block and the tool D16TR3.
- 7 From the Strategy Selector, open the Drilling dialog and select the Drilling strategy.




8 Select *Cycle type* **Helical** and input remaining data into the **Drilling** dialog exactly as shown above and then click on the **Select** tab.






- 9 In the Diameter box select **22.00** and click on to add these holes to the **Selection Filter** box.
- 10 Close the Feature Selection dialog and select Calculate in the main Drilling strategy dialog.




11 Make a Copy of the last Drilling Toolpath named OP2-EM16-CBores and this time use the *Tool* EM16 and *Cycle Type* - Profile on both of the counterbore Features.







12 Input data into the **Drilling** dialog exactly as shown above and **Calculate**.



13 Perform ViewMILL simulations for both OP1 and OP2.







14 Save the Project to update:-


 $.... \backslash COURSEWORK \backslash PowerMill_Projects \backslash CornerBowl-Example$



2.5D Machining Example

- 1 Select File > Delete All and Tools > Reset Forms
- 2 Open the (read only) Project:-


....\PowerMill_Data\Projects\ 2DCurveMachining-2-Start



3 Save Project As:

....\COURSEWORK\PowerMill_Projects\2DCurveMachining-2


The **Project** already includes **Toolpaths** to rough and finish machine the 3D model form. It is however required to create additional recesses into the top face (7.5 deep with 10 Deg Draft) and front wall (25 deep – No draft) and 4 Dia 12 holes near the corners of the base (offset 15 from the outside of the base).






Create individual Patterns for the Top Recess, Front Recess, and Base Corner Holes:


The **Model** also includes **2D** curves which can be made visible by switching on **Wireframe** in the **Views** toolbar.



- 4 Create a new Pattern (1).
- 5 Select both of the closed *wireframe curves* on the **Model**.
- 6 In the **PowerMill** explorer right mouse click on the new **Pattern** and from the local menu select **Insert Model**.




7 Create another new Pattern (2) and this time Insert the open wireframe curve into it.







- 8 Create another new **Pattern** (3).
- 9 Select the upper base surface on the **Shaded** model and **Insert** it into the new **Pattern**.



10 Select and **Delete** the inner **Pattern** segment.



- 11 Double left mouse click on the remaining **Pattern** segment in the graphics area to access the **Curve Editing** toolbar.
- 12 Offset the selected segment inwards by 15.




13 To accept the edits, select the green tick at the end on the Curve Editor toolbar.




Machine the top recess with a 10 degree draft angle:-

- **14 Activate** one of the existing toolpaths to reinstate the settings (Workplane, Block, and Rapid Move Heights).
- 15 Activate the D12TR1 tool.
- 16 From Toolpath strategies open the 2D Curve Area Clearance dialog.





17 Input the data and settings exactly as shown in the following images.




18 Select to preview and if required apply the **Pattern Decoration** options to modify the machining area and directions.











19 Select **Calculate** to process the toolpath and then **Close** the dialog.







- 20 Activate the **D6TR1** Tool.
- 21 From Toolpath strategies open the 2D Curve Area Clearance dialog.
- 22 Input the data and settings exactly as shown in the following images.












23 Select Calculate to process the toolpath and then Close the dialog.






- **24** From Toolpath strategies open the **2D Curve Profile** dialog.
- 25 Input the data and settings exactly as shown in the following images.






26 Select Calculate to process the toolpath and then Close the dialog






The next stage is to machine the vertical, front recess:-

- 27 Activate the EM12 Tool.
- 28 From Toolpath strategies open the 2D Curve Profile dialog.
- 29 Input the data and settings exactly as shown in the following images.









30 Select **Calculate** to process the toolpath and then **Close** the dialog.





Drill four Dia 12 holes offset 15mm from the base walls:-


The next stage is to create a **Hole Feature Set** defining four Dia 12 through holes down from the corners of **Pattern 3**.




- 31 Select the rectangular **Pattern 3** located on top of the base surface.
- 32 In the **PowerMill** explorer right mouse click on **Hole** Feature Sets and from the local menu select **Create Holes**.



- 33 In the Create Holes dialog select the option *create from* Points.
- 34 Input the **Absolute** values **-50** (top) and **-75** (bottom).




35 Select Apply to create four Dia 12 Hole Features.




- **36** Activate the Dia 3 Drill named **Drill3**.
- 37 From Toolpath strategies select the **Drilling Single Peck** option.
- 38 Input the data and settings exactly as shown in the following image.






39 Calculate the Drilling toolpath and then select **Re-cycle** the strategy.






- 40 Activate the Dia 12 Drill named **Drill15**.
- 41 Input the data and settings exactly as shown in the following image.



42 Calculate the Drilling toolpath and then **Close** the above dialog.



Save the Project to update:-

....\COURSEWORK\PowerMill_Projects\2DCurveMachining-2