

Фиг. 1.




Фиг. 2.



Фиг. 3.



Фиг. 4.



Фиг. 5.



Фиг. 6.



Фиг. 7.



Фиг. 8.



Фиг. 9.



Фиг. 10.



Фиг. 11.



Фиг. 12.



Фиг. 13.



Фиг. 14.



Фиг. 15.



Фиг. 16.



Фиг. 19.

Фиг. 20.

Фиг. 17.



Фиг. 18.



Фиг. 19.



Фиг. 20.



Фиг. 21.



Фиг. 22.




Фиг. 23.

Фиг. 24.

Фиг. 25.

Фиг. 26.





Фиг. 27.



Фиг. 28.



Фиг. 29.



Фиг. 30.



Фиг. 31.



Фиг. 32.



Фиг. 33.



Фиг. 34.



Фиг. 35.



Фиг. 36.



Фиг. 37.

Фиг. 38.




Фиг. 39.



Фиг. 40.



Фиг. 41.



Фиг. 42.



Фиг. 43.



Фиг. 44.



Фиг. 45.



Фиг. 46.

Фиг. 47.



Фиг. 48.



Фиг. 49.



Фиг. 50.



Фиг. 51.



Фиг. 52.



Фиг. 53.



Фиг. 54.



Фиг. 55.



Фиг. 56.



Фиг. 57.



Фиг. 58.



Фиг. 59.





Фиг. 60.




Мотивы токарных работ
М. ГРЕФЪ, Вып. II.

Листъ 6.


Фиг. 61.



Фиг. 62.




Фиг. 64.




Мотивы токарныхъ работъ
М. ГРЕФЪ ВЪДЪ ИТ.


Фиг. 68.



Фиг. 69.



Фиг. 67.



Фиг. 66.

